

BURNET COUNTY



AUTHORIZATION AND ASSIGNMENT OF COUNTY PROPERTY

Name of Item	Description	Property #	(Auditor's Use)
			Cost
1.) 1984 AM GEN TRUCK	M915A1	16-1077	
2.) JOHN DEERE DIGGER	POST HOLE AUGER WITH KIT	9584-09	
3.) BOBCAT TIRES	4 USED BOBCAT SOLID CORE TIRES		
4.) CATERPILLAR	H80 HYDRAULIC HAMMER W/BIT	21-1186	
5.) 1990 CATERPILLAR	CB34B IRON WHEEL ROLLER 51"	14-1089	
6.) CATERPILLAR	PS-180 PNEUMATIC ROLLER	3026	
7.) ATLAS COPCO COMPRESSOR	MODEL XAS175	17-1076	
8.) 2017 KUBOTA	KUBOTA ZD 323 ZERO TURN MOWER	18-1017	
9.) LEE BOY TACK TRAILER	TACK TRAILER WITH 8' SPRAY BAR	14-1226	
Dept. Transferred From: RB4		Dept. Assigned To: AUCTION	

Requested By: _____ DATE: _____

Comments: _____

COMMISSIONERS COURT APPROVAL:

☐ New in Service ☐ Transfer
☐ Return to Donor ☐ Out of Service ☐ Hold For Auction
☐ Dispose ☐ Donation

Authorization Signature: _____ Date: _____

Comments: _____

PROPERTY MOVED BY MAINTENANCE DEPT.:

Authorization Signature: _____ Date: _____

Comments: _____

CHANGES MADE TO RECORDS BY AUDITOR'S OFFICE:

Changed in Books: _____ Date of change: _____

Comments: _____

Per LGC 263.153 (c)--Burnet County, Texas contracts with online auction sites as licensed under Chapter 1802 of the Occupations Code to sell surplus and/or salvage property. The property is posted on the auction site for at least 10 days to comply with the publication requirement for the notice of sale.

Heavy Truck Inspection Form

Inventory ID: 428	Asset Number:	Fair Market Value: 5000.00
--------------------------	----------------------	-----------------------------------

Short Description:
Year 1984 Manufacturer AM General Model M915A1

VIN: 1 U T S H 6 6 8 X E 0 0 2 2 5 9 Title Restriction: ☐ Y ☒ N

Mileage/Odometer: 4 5 7 7 Odometer Accurate ☒ Y ☐ N:

Long Description: Primary Use for Vehicle: Tractor unit to haul trailer overhauled 10-09 GVW: 50,000

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only

Date Removed From Service: Currently used Maintenance Records: ☐ Available ☐ Not Available For Inspection

Engine Manufacture: unk **Engine:** L, V ☐ Gas ☒ Diesel

This vehicle was maintained every ☐ Days ☐ Hours ☐ Miles # of Axles 3

Engine Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition Jake Brake: ☐ Yes ☐ No

Engine Repairs needed: None

Transmission Manufacture: ☒ Automatic ☐ Manual Speed

Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown ☐ Rebuilt (Date:)

Transmission Repairs Needed: None

Exterior: Color Army Green **Windows:** ☐ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☒ Scratches ☐ Dings **Tire Condition:** ☐ Low ☐ Flat

Damage to: Will need some tires replaced as they are starting to show signs of cracks

Additional Damage to:

Decals: ☐ None ☐ Have been sprayed ☒ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Capacity: Loader: ☐ Front ☐ Side Electronic Tarp: ☐ Yes ☐ No Condition:

Interior: Color Army Green ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: No

Damage to Dash/Floor: None

Radio: Brand NONE ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors **Airbags:** ☐ Driver's Side ☐ Dual

☐ AC ☐ No AC AC Condition: ☐ Cold ☐ Unknown **Power:** ☐ Windows ☐ Doorlocks ☐ Steering ☐ Seats

Additional Equipment: Manufacturer: Model:

Serial # Description:

Equipment Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition

Other Equipment:

Location of Asset: Burnet County Precinct 4

For more information contact: Homer Will (409) 882-2242

Generic Inspection Form

Inventory ID: _____

Asset Number **9584-09**

Anticipated Sale Price: **500.00**

Short Description: John Deere 3 Point Post Hole Auger With Down Pressure Kit

Year unk

Manufacturer John Deere

Model _____

Please fill in or check if apply

Long Description:

John Deere 3 Point Posy Hole Auger With Down Pressure Kit

This Equipment: ☐ Is Operable ☒ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☐ Hours: _____ This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # XFPHD0X275390

Repairs needed: Down Pressure Kit Shaft is Bent

Description of Use

Post Hole Drilling

Color Green ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: Burnet County Pct 4 Barn

For more information contact: Homer Will / 409-882-2242

Generic Inspection Form

Inventory ID: _____

Asset Number _____

Anticipated Sale Price: 500.00

Short Description: (4) Used Bobcat Solid Core Tires 36.5x12 20

Year unk

Manufacturer _____

Model _____

Please fill in or check if apply

Long Description:

(4) Used Bobcat Solid Core Tires 36.5x12 20

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☐ Hours: _____ This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # _____

Repairs needed: None

Description of Use

(4) Used Bobcat Solid Core Tires 36.5x12 20

Color Black ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☒ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: Burnet County Pct 4 Barn

For more information contact: Homer Will / 409-882-2242

Generic Inspection Form

Inventory ID: _____

Asset Number _____

Anticipated Sale Price: **7500.00**

Short Description: Caterpillar H80 Hydraulic Hammer W/Bit

Year unk

Manufacturer Caterpillar

Model H80

Please fill in or check if apply

Long Description:

Caterpillar H80 Hydraulic Hammer W/Bit

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: _____ This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # _____

Repairs needed: None / excellent condition, used a handful of times. Purchased new approx 3 yrs ago

Description of Use

Used for demolition / rock removal

Color Black ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

See attached picture(s)

Location of Asset: 110 Rodeo Drive Marble Falls, Tx 78654

For more information contact: Homer Will 409-882-2242

Generic Inspection Form

Inventory ID: **E-6**

Asset Number **14-1089**

Anticipated Sale Price: **3000.00**

Short Description: 1990 Caterpillar CB34B (Diesel) Iron Wheel Roller 51"

Year 1990

Manufacturer Caterpillar

Model CB34B

Please fill in or check if apply

Long Description:

1990 Caterpillar CB34B (Diesel) Iron Wheel Roller 51"

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☒ Hours: 1276.1 This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # 42300146

Repairs needed: _____

Description of Use

Compaction

Color Yellow ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: Burnet County Pct 4 Barn

For more information contact: Homer Will / 409-882-2242

Generic Inspection Form

Inventory ID: **E-11**

Asset Number

Anticipated Sale Price: **3000.00**

Short Description: Caterpillar PS-180 Pneumatic Roller

Year _____

Manufacturer Caterpillar

Model PS-180

Please fill in or check if apply

Long Description:

Caterpillar PS-180 Pneumatic Roller

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☒ Hours: 2769 This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # Un-readable

Repairs needed: Minor repairs needs, brakes, battery ect.

Description of Use

Equipment was utilized a roller for seal coats pavement projects

Color Yellow ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: Burnet County Pct 4 Barn

For more information contact: Homer Will / 409-882-2242

Generic Inspection Form

Inventory ID: **E-27**

Asset Number **17-1076**

Anticipated Sale Price: **2500.00**

Short Description:

Year unk

Manufacturer Atlas

Model Copco Compressor

Please fill in or check if apply

Long Description:

Atlas Copco Compressor Pull Behind / Diesel Engine

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☐ Hours: _____ This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # ARP920308

Repairs needed: Needs new battery

Description of Use

Atlas Copco Compressor Pull Behind

Color Yellow ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: Burnet County Pct 4 Barn

For more information contact: Homer Will / 409-882-2242

Generic Inspection Form

Inventory ID: **E-28**

Asset Number **18-1017**

Anticipated Sale Price: **5000.00**

Short Description: Kubota ZD 323 Zero Turn Mower 60"

Year 2017

Manufacturer Kubota

Model ZD 1211

Please fill in or check if apply

Long Description:

Kubota ZD 323 Zero Turn Mower 60" Cut

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☒ Hours: 384 This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # _____

Repairs needed: None

Description of Use

Used for roadway mowing / Diesel motor / 60" cut deck

Color Orange ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☒ Plastic ☐ Wood ☐ Rubber

Minor damage to: Deck

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: Burnet County Pct 4

For more information contact: Homer Will

Generic Inspection Form

Inventory ID: **T-9**

Asset Number **14-1226**

Anticipated Sale Price: **3500.00**

Short Description: Lee Boy L250T Tack Trailer with 8' Spray Bar

Year unk

Manufacturer Lee Boy

Model L250T Tack Trailer

Please fill in or check if apply

Long Description:

Lee Boy L250T Tack Trailer with 8' Spray Bar

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☐ Hours: _____ This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # 1B9AA1111E1309886

Repairs needed: Needs a new carburetor for the motor

Description of Use

Paving oil distribution for roadway paving

Color Black ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: Burnet County Pct 4 Barn

For more information contact: Homer Will / 409-882-2242