

MB

CONSTABLES PRECINCT #1 BUILDING

- FOUND WATER LEAKING THROUGH THE NORTH SIDE EXTERIOR DOORS THROUGH THE MAGNETIC LOCK AND SCREWS DRILLED INTO THE DOOR FRAME
- FOUND WATER PENETRATING THROUGH THE BLOCK ON CERTAIN AREAS OF THE BUILDING. FOUND CEILING TILES WITH WET SPOTS THROUGH OUT THE BUILDING
- CALCIUM HAS FORMED ON CERTAIN LOCATIONS OF THE EXTERIOR WALLS THROUGH OUT THE BUILDING DUE TO LACK OF WATER SEALING THE BUILDING
- FOUND WATER STAINS ON THE WALL INSIDE GARAGE/CAR PORT

RECOMENDATION

- WATER SEAL THE ENTIRE EXTERIOR WALL OF THE BUILDING TOP TO BOTTOM EITHER IN HOUSE OR THROUGH A JOC VENDOR.
- WATER SEALING TREATMENT WAS NOT PART OF HOLCHEMONT'S ( CONTRACTOR )SCOPE OF WORK.

COURTHOUSE GATES

- AS OF FRIDAY JANUARY 3, 2014 ALL GATES ARE CURRENTLY WORKING EXCLUDING THE MIDDLE GATE THAT GOES INTO THE JUDGES PARKING LOT DUE TO A COUNTY EMPLOYEE DAMAGING THE GATE WITH A COUNTY VEHICLE.
- REMOVED PEDESTRIAN GATE SENSORS ON SOUTH SIDE GATE AND WEST SIDE GATE. SENSORS WERE CAUSING GATES TO MALFUNCTION DUE TO RAIN OR DEBREE. SENSORS ARE ONLY FOR PEDESTRIANS WHICH NO PEDESTRIANS GO IN AND OUT OF THOSE GATES.