

TRUCK APPRAISER'S REPORT

Recommendation: <input type="checkbox"/> Repairable <input checked="" type="checkbox"/> Total Loss <input type="checkbox"/> Borderline		PDA Office: Harlingen, TX 334	
Adjuster: CHRISTOPHER "CHRIS" DUFFY		Claim Number: 2482653	
Assignment Number: 334-912-0080		Owner: Hidalgo County	
Date of Loss: 12/3/2019		<input checked="" type="checkbox"/> Insured <input checked="" type="checkbox"/> Claimant	
Make: Kenworth		Model: T800	
Year: 2012		VIN: 1XKDDP9X6CJ329089	
Odometer: 248,843		Hubometer (Yes/No/NA) NA	
Hub Hours: NA		Engine Hours: NA	
Recent Engine Overhaul: No		Engine: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Alternative Fuel	
Horsepower: 425		Transmission: Make: Eaton	
Model: Fuller		Speeds: 10	
Front Axle Capacity: 12,000LBS		Steering Gear: N/A	
Dual Steering Gear (Y/N): NO		<input checked="" type="checkbox"/> Power <input type="checkbox"/> Manual	
Rear Axle Make: DS		Model: DSP40	
<input type="checkbox"/> Single <input checked="" type="checkbox"/> Tandem <input type="checkbox"/> Tri Axle <input type="checkbox"/> Tag		Rear Suspension Make: KW	
Type: Air/Leaf		Capacity: 40,000LBS	
Brakes <input checked="" type="checkbox"/> Hydraulic <input type="checkbox"/> Air <input type="checkbox"/> Vacuum Assist		Fifth Wheel Make: N/A	
<input type="checkbox"/> Fixed <input checked="" type="checkbox"/> Slider <input type="checkbox"/> Manual <input checked="" type="checkbox"/> Air		Fuel Tanks <input checked="" type="checkbox"/> Aluminum <input type="checkbox"/> Steel <input checked="" type="checkbox"/> Polished <input type="checkbox"/> Painted <input type="checkbox"/> Step	
<input type="checkbox"/> Paddled <input checked="" type="checkbox"/> Saddle		Number: 2	
Capacity: 100		Cab <input type="checkbox"/> COE <input checked="" type="checkbox"/> Conventional <input type="checkbox"/> Sleeper <input type="checkbox"/> Integrated	
Sleeper Size and Type: None		Equipment <input type="checkbox"/> Wet Kit <input type="checkbox"/> Owner/Operator PTS <input checked="" type="checkbox"/> A/C <input type="checkbox"/> Heated Mirror	
Other Equipment: None		Other Accessories: PTO	
Exterior <input type="checkbox"/> Special Paint <input type="checkbox"/> Custom Pin Stripes <input type="checkbox"/> Murals		Number of Colors: 1	
Frame <input checked="" type="checkbox"/> Steel <input type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Heat Treated <input type="checkbox"/> Reinforced <input type="checkbox"/> Standard Length <input type="checkbox"/> Extended Length		Front Wheels <input checked="" type="checkbox"/> Aluminum <input type="checkbox"/> Steel	
<input checked="" type="checkbox"/> Polished <input type="checkbox"/> Chrome		<input type="checkbox"/> Painted <input type="checkbox"/> Disc	
<input type="checkbox"/> Bud <input type="checkbox"/> Dayton		Rear Wheels <input checked="" type="checkbox"/> Aluminum <input type="checkbox"/> Steel	
<input checked="" type="checkbox"/> Polished <input type="checkbox"/> Chrome		<input type="checkbox"/> Painted <input type="checkbox"/> Disc	
<input type="checkbox"/> Bud <input type="checkbox"/> Dayton		Front Tires Size: 11/R24.5	
Make: Michelin		RF 18/32	
LF 18/32		<input checked="" type="checkbox"/> Radial <input type="checkbox"/> Recaps	
Rear Tires Size: 11/R24.5		LRFO 16/32	
LRFI 16/32		RRFO 16/32	
LRRO 16/32		RRFI 16/32	
RRRO 16/32		<input checked="" type="checkbox"/> Radials	
RRRI 16/32		<input type="checkbox"/> Recaps	
Loss Type <input type="checkbox"/> Collision <input checked="" type="checkbox"/> Fire <input type="checkbox"/> Theft <input type="checkbox"/> Flood <input type="checkbox"/> Other: Fire Damage		Charges Towing: N/A	
Storage/Day: No		Recovery Fee: No	
Repair Facility: Total Loss		Repair Facility Contact: None	
Phone Number: None		Agreed Cost To Repair: \$74,691.40	
Repair Days: 30		Est. ACV: \$48,250.	
Est. Salvage: \$0.00		Recommendations: The damages to the unit are to the front bumper, front crossmember, grille, hood, headlamps, fender extensions, cooling pack, suspension, steering assembly, front suspension, engine, transmission, wire harness, air cleaner, cab, glass, cab complete interior, frame rails, tool box, battery tray, fairings, and fuel tanks. This unit is an obvious total loss.	
General Condition: Good.		Prior Damage: None.	
Betterment: No Betterment Applied.		Alternative Parts: French Ellison-Alex, raneystruckparts.com, truckpartsinventory.com, mylittlesalesman.com	
Temporary Repairs: None		Appraiser: JOEL MARTINEZ	
Date: 2/19/2019			



TRUCK APPRAISER'S REPORT

Recommendation: <input type="checkbox"/> Repairable <input checked="" type="checkbox"/> Total Loss <input type="checkbox"/> Borderline		PDA Office: Harlingen, TX 334	
Adjuster: CHRISTOPHER "CHRIS" DUFFY		Claim Number: 2482653	
Assignment Number: 334-912-0078		Owner: Hidalgo County	
Date of Loss: 12/3/2019		<input checked="" type="checkbox"/> Insured <input checked="" type="checkbox"/> Claimant	
Make: Peterbilt		Model: 384	
Year: 2010		VIN: 1XPVD09X6AD797681	
Odometer: 150,720		Hubometer (Yes/No/NA) NA	
Hub Hours: NA		Engine Hours: NA	
Recent Engine Overhaul: No		Engine: Make: Cummins Model: ISM <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Alternative Fuel	
Horsepower: 370		Transmission: Make: Eaton Model: Fuller	
Speeds: 10		Front Axle: Capacity: 12,000LBS Steering Gear: N/A	
Dual Steering Gear (Y/N): NO		<input checked="" type="checkbox"/> Power <input type="checkbox"/> Manual	
Rear Axle: Make: DSA Model: DSP40		<input type="checkbox"/> Single <input checked="" type="checkbox"/> Tandem <input type="checkbox"/> Tri Axle <input type="checkbox"/> Tag	
Rear Suspension: Make: Peterbilt Type: Air/Leaf		Capacity: 40,000LBS	
Brakes: <input checked="" type="checkbox"/> Hydraulic <input type="checkbox"/> Air <input type="checkbox"/> Vacuum Assist		Fifth Wheel: Make: N/A <input type="checkbox"/> Fixed <input checked="" type="checkbox"/> Slider <input type="checkbox"/> Manual <input checked="" type="checkbox"/> Air	
Fuel Tanks: <input checked="" type="checkbox"/> Aluminum <input type="checkbox"/> Steel <input checked="" type="checkbox"/> Polished <input type="checkbox"/> Painted <input type="checkbox"/> Step		<input type="checkbox"/> Paddled <input checked="" type="checkbox"/> Saddle	
Number: 2		Capacity: 100	
Cab: <input type="checkbox"/> COE <input checked="" type="checkbox"/> Conventional <input type="checkbox"/> Sleeper <input type="checkbox"/> Integrated		Sleeper Size and Type: None	
Equipment: <input type="checkbox"/> Wet Kit <input type="checkbox"/> Owner/Operator PTS <input checked="" type="checkbox"/> A/C <input type="checkbox"/> Heated Mirror		Other Equipment: None	
Other Accessories: None.		Exterior: <input type="checkbox"/> Special Paint <input type="checkbox"/> Custom Pin Stripes <input type="checkbox"/> Murals	
Number of Colors: 1		Frame: <input checked="" type="checkbox"/> Steel <input type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Heat Treated <input type="checkbox"/> Reinforced <input type="checkbox"/> Standard Length <input type="checkbox"/> Extended Length	
Front Wheels: <input type="checkbox"/> Aluminum <input type="checkbox"/> Polished <input checked="" type="checkbox"/> Painted <input checked="" type="checkbox"/> Bud		<input checked="" type="checkbox"/> Steel <input type="checkbox"/> Chrome <input type="checkbox"/> Disc <input type="checkbox"/> Dayton	
Rear Wheels: <input type="checkbox"/> Aluminum <input type="checkbox"/> Polished <input checked="" type="checkbox"/> Painted <input checked="" type="checkbox"/> Bud		<input checked="" type="checkbox"/> Steel <input type="checkbox"/> Chrome <input type="checkbox"/> Disc <input type="checkbox"/> Dayton	
Front Tires: Size: 11/R24.5		Make: Michelin	
RF 18/32		LF 18/32	
<input checked="" type="checkbox"/> Radial <input type="checkbox"/> Recaps		Rear Tires: Size: 11/R24.5	
LRFO 16/32		RRFO 16/32	
LRFI 16/32		RRFI 16/32	
LRRO 16/32		RRRO 16/32	
LRRF 16/32		RRRI 16/32	
LRRR 16/32		RRRI 16/32	
Make: Bridgestone		<input checked="" type="checkbox"/> Radials <input type="checkbox"/> Recaps	
Loss Type: <input type="checkbox"/> Collision <input checked="" type="checkbox"/> Fire <input type="checkbox"/> Theft <input type="checkbox"/> Flood <input type="checkbox"/> Other: Fire to Left Front		Charges: Towing: N/A Storage/Day: No Recovery Fee: No	
Repair Facility: Total Loss		Repair Facility Contact: None	
Phone Number: None		Agreed Cost To Repair: \$47,767.58	
Repair Days: 18		Est. ACV: \$23,700	
Est. Salvage: 1,500.00		Recommendations: The damages to the vehicle are to the front bumper, grille, hood, headlamps, steering gear, cooling assembly, engine, wire harness, left fender extension, left front wheel, left front tire, battery box, cab assembly, windshield, left front door, instrument panel, and interior trim. I've made a correction on the estimate I removed the sales tax. This vehicle is an obvious total loss.	
General Condition: Good.		Prior Damage: None.	
Betterment: No Betterment Applied.		Alternative Parts: raneystruckparts.com, vanderhaags.com, truckpartsinventory.com, mylittlesalesman.com	
Temporary Repairs: None		Appraiser: JOEL MARTINEZ	
Date: 2/20/2019			

Exhibit B

Pct. 3 Property Loss: 19-12-03-1838

Location: Pct. 3 Motor Pool

8310 W. Mile 7 Road., Mission, TX

Unit# 249 2012 Kenworth VIN: 1XDPPX6CJ329089



Pct. 3 Property Loss: 19-12-03-1838

Location: Pct. 3 Motor Pool

8310 W. Mile 7 Road., Mission, TX

Unit# 202 Peterbilt VIN: 1XPVD09X6AD797681

