







ProjectDox[®]

Changemarks Report

Project Name: Lynwood 3rd Addition

Workflow Started: 10/27/2023 8:20 AM

Report Generated: 12/06/2023 10:50 AM

Grouping	Cycle	Ref #	Complete?	Status	Department	Snapshot	File	Markup Name	Changemark Subject	Changemark Details	Markup Date	Updated By	Applicant Response
Main Workflow	1	6	False	Unresolved	Civil Engineer IV		14-16 CD - LW3RD.pdf	LL	This sheet does not load.		12/04/2023 9:26 AM	Len Linton	
		5	False	Unresolved	Environmental Review		Lynwood PH3LP 1.pdf	CA	HA	This symbol is not shown on the Landscape Plan for Phase 3 plantings. Is this supposed to be HB?	11/16/2023 8:47 AM	Chris Anderson	
		4	False	Unresolved	Environmental Review		04 STRT - LW3RD.pdf	CA	Existing?	Does this symbol maybe represent existing street lights?	11/16/2023 8:26 AM	Chris Anderson	
		2	False	Unresolved	Engineering Tech		14-16 CD - LW3RD.pdf	Logan Czech	Sheet number	Duplicate number shown as overlapping	11/16/2023 8:02 AM	Logan Czech	
		3	False	Unresolved	Engineering Tech		14-16 CD - LW3RD.pdf	Logan Czech	Extra details	Eliminate details that aren't relevant to 3rd addition	11/16/2023 8:02 AM	Logan Czech	
		1	False	Unresolved	Engineering Tech		07 SW - LW3RD.pdf	Logan Czech	Storm sewer	Is this the storm pipe? the elevation seems to be off. If there is less than 2' of separation between storm and WM (even at service crossings) then insulation will need to be added.	11/16/2023 7:23 AM	Logan Czech	