



Home Sub-category Item List **Item Detail**

Item Info

Asset Number 48-019-9703-48-003

NSN Group Code 2540 - VEHICULAR FURNITURE AND ACCESSORIES (2540)

Description 4 MAN SOFT TOP KIT CAMO

Manufacturer

Model

Model Year

Quantity 5

UoM each

Service Charge \$150.00

Surplus Location FORT WORTH - YARD - BULK

Notes 1 FOUR-DOOR HUMVEE/ SOFT-TOP

Notes 2

San Antonio

210-661-2381

Questions? Interested in placing this item on hold? Please contact the appropriate location:

Fort Worth (817) 831-6767 / FortWorth.Surplus@tfc.state.tx.us

San Antonio (210) 661-2381 / SanAntonio.Surplus@tfc.state.tx.us

Austin (512) 475-3705 / federal.surplus@tfc.state.tx.us

NOTE: This property is available to approved program participants only. It is not for sale to the general public. For more information on which organizations are eligible, please visit <http://tfc.state.tx.us/FSP>.

Requestor is responsible for picking up the asset at the location listed above.



image[1].jpg



image[3].jpg



image[2].jpg

TXSASP - Copyright © 2020 AssetWorks LLC. All rights reserved.





PACKING LIST

Description: **KIT, FOUR MAN CREW, HMMWV, SCAPP**
 Part Number: **53952 (reference 57K3501, NSN 2540-01-434-8598)**
 Date: **03/15/06**
 Revision Level: **005**
 Approval: *[Signature]*

Item	Quantity	GMA Name	Government Name	GMA Part Number	Government Part Number	Case
1.0	2	Loop Assy. Footman, Flat, HMMWV, Black	Loop	52850	1/ 12338839-8	19207
2.0	4	Screw, Oval - HD CR 10-32 x 3/4, HMMWV	Screw	80840	157166	24617
3.0	4	Nut - Hex 10 - 32 wister Washer, HMMWV	Nut	80852	271169	19207
4.0	1	Installation Drawing	Installation Drawing	82429	12342453 (sheet 1 of 4)	19207
4.1	1	Installation Drawing	Installation Drawing	82430	12342453 (sheet 2 of 4)	19207
4.2	1	Installation Drawing	Installation Drawing	82431	12342453 (sheet 3 of 4)	19207
4.3	1	Installation Drawing	Installation Drawing	82432	12342453 (sheet 4 of 4)	19207
5.0	1	Installation Instructions	Installation Instructions	82440	12447131 (sheet 1 of 5)	19207
5.1	1	Installation Instructions	Installation Instructions	82447	12447131 (sheet 2 of 5)	19207
5.2	1	Installation Instructions	Installation Instructions	82448	12447131 (sheet 3 of 5)	19207
5.3	1	Installation Instructions	Installation Instructions	82449	12447131 (sheet 4 of 5)	19207
5.4	1	Installation Instructions	Installation Instructions	82450	12447131 (sheet 5 of 5)	19207
6.0	4	Screw	Screw	82421	B18218H031F100R	05047
7.0	8	Screw	Screw	82420	MS51958-63	96906
8.0	1	Striker Assy. Rear, Left, HMMWV, Black	Latch Striker	52365	2/ 12340182-1	19207
9.0	1	Striker Assy. Rear, Right, HMMWV, Black	Latch Striker	52366	2/ 12340182-2	19207
10.0	1	Brace, Reinforcement, C-Pillar, Left Hand, HMMWV, Black	Brace, Reinforcement, C-Pillar, LH	52590	3/ 12447123	19207
11.0	1	Brace, Reinforcement, C-Pillar, Right Hand, HMMWV, Black	Brace, Reinforcement, C-Pillar, RH	52591	3/ 12447124	19207
12.0	8	Rivet	Rivet	82401	M78856-6-05	81349
13.0	2	Screw	Screw	82402	191881	24617
14.0	4	Washer	Washer	82403	120393	24617
15.0	2	Nut	Nut	82404	4/ MS51943-32 (MS17828-4F)	96906
16.0	2	Loop Assembly, Footman, HMMWV, Black	Loop	52928	1/ 12338839-4	19207
17.0	12	Nut - Hex HD PT 5/16 - 24, HMMWV	Nut	80655	4/ MS51943-34 (9419476)	24617
18.0	2	Screw, Flat - HD CR 10 - 32 x 3/4, HMMWV	Screw	80839	MS51835-3LE12	80205
19.0	4	Nut - Hex HD PT 1/4 - 20, HMMWV	Nut	80634	MS51943-31	24617
20.0	4	Mount Assy. Hinge, HMMWV, Black	Hinge	52352	12338650	19207
21.0	4	Screw	Screw	82422	B18218H031F112N	05047
NOTE: Items 1 through 21 are consolidated under part number 54505 within the kit.						
22.0	1	Rail Assy. Horizontal, Left, Four Man, HMMWV	Side Rail	52059	2/ 12340222-1	19207
23.0	1	Rail Assy. Horizontal, Right, Four Man, HMMWV	Side Rail	52060	2/ 12340222-2	19207
NOTE: Item 22 and 23 are consolidated items within the kit.						
24.0	2	Bow Assy. Horizontal, HMMWV, Black	Bow	52062	3/ 12340682	19207
25.0	1	Pillar Assy, "C", HMMWV, Black	C-Pillar	52061	3/ 12340679	19207
26.0	1	Top Assy, Four Man Crew, HMMWV, SCAPP	Top	54278	5/ 12340678-31	19207
27.0	1	Curtain Assy, Four Man Crew, HMMWV, SCAPP	Curtain	54279	5/ 12342475-6	19207
NOTE: Item 26 and 27 are consolidated items within the kit.						
28.0	1	Door Assy, Rear, Left, HMMWV, SCAPP	Door	54284	5/ 12340245-8	19207
29.0	1	Door Assy, Rear, Right, HMMWV, SCAPP	Door	54285	5/ 12340245-7	19207
30.0	1	Door Assy, Front, Left, HMMWV, SCAPP	Door	54282	5/ 12340231-10	19207
31.0	1	Door Assy, Front, Right, HMMWV, SCAPP	Door	54283	5/ 12340231-11	19207

NOTES:

For use in kit only



Home Sub-category Item List **Item Detail**

Item Info

Asset Number	48-020-9287-06-024
NSN Group Code	2540 - VEHICULAR FURNITURE AND ACCESSORIES (2540)
Description	MIRROR ASSEMBLY
Manufacturer	PM
Model	WEST COAST 666
Model Year	
Quantity	2
UoM	each
Service Charge	\$12.00
Surplus Location	SAN ANTONIO - BULK
Notes 1	
Notes 2	7" X 16" SIDEVIEW MIRROR

Questions? Interested in placing this item on hold? Please contact the appropriate location:

Fort Worth (817) 831-6767 / FortWorth.Surplus@tfc.state.tx.us
 San Antonio (210) 661-2381 / SanAntonio.Surplus@tfc.state.tx.us
 Austin (512) 475-3705 / federal.surplus@tfc.state.tx.us

NOTE: This property is available to approved program participants only. It is not for sale to the general public.
 For more information on which organizations are eligible, please visit <http://tfc.state.tx.us/FSP>.

Requestor is responsible for picking up the asset at the location listed above.



WIN_20200430_14_37_44
Pro.jpg



untitled.png