



**Pronghorn Park
7931 E. Rusty Spur Trail
Prescott Valley, AZ 86315**





**AT&T NEW SITE DEVELOPMENT FOR BALLFIELD LIGHT POLE
SEPTEMBER 2026**











Legend

RSRP (dBm) - Indoor

- Best RSRP (RS EPRE) Level (dBm) ≥ -90
- Best RSRP (RS EPRE) Level (dBm) ≥ -98
- Best RSRP (RS EPRE) Level (dBm) ≥ -103
- Best RSRP (RS EPRE) Level (dBm) ≥ -108
- Best RSRP (RS EPRE) Level (dBm) ≥ -113
- Best RSRP (RS EPRE) Level (dBm) ≥ -116
- Best RSRP (RS EPRE) Level (dBm) ≥ -118
- Best RSRP (RS EPRE) Level (dBm) ≥ -126



Legend

RSRP (dBm) - Indoor

- Best RSRP (RS EPRE) Level (dBm) ≥ -90
- Best RSRP (RS EPRE) Level (dBm) ≥ -98
- Best RSRP (RS EPRE) Level (dBm) ≥ -103
- Best RSRP (RS EPRE) Level (dBm) ≥ -108
- Best RSRP (RS EPRE) Level (dBm) ≥ -113
- Best RSRP (RS EPRE) Level (dBm) ≥ -116
- Best RSRP (RS EPRE) Level (dBm) ≥ -118
- Best RSRP (RS EPRE) Level (dBm) ≥ -126

Enhancement to Pronghorn Ranch and surrounding area

AT&T 5G coverage in this area is very low. Data Speeds (DL and UL) confirm the low coverage for the area. The only way to alleviate the burden on the surrounding is to build a new wireless communication tower that will create a more consistent and uniform coverage area.