

[illegible]

LAYOUT EXHIBIT FOR WILD WING ACRES

PRELIMINARY – ADMINISTRATIVE REVIEW

PURSUANT TO THE STATE OF TEXAS ADMINISTRATIVE CODE SECTION 1.66-23(e), THIS DOCUMENT IS "PRELIMINARY, THIS DOCUMENT SHALL NOT BE RECORDED FOR ANY PURPOSE AND SHALL NOT BE USED OR VIEWED OR RELED UPON AS A FINAL SURVEY DOCUMENT."

PROJ. NO. 29738 PREPARED FOR: DARRYL COMBS TECH: PLANNING APPROVED: KCI FIELDWORK: PERFORMED ON: N/A DATE: 06/29/2010 DESIGNED BY: 2003-06-29 CHECKED BY: 2003-06-29 DRAWN BY: 2003-06-29	
1500 OULIE LANE MARBLE FALLS, TX 78654 PH: 252-586-3300 FAX: 661-6815 WWW.CUPLIPLANSOCIATES.COM	
SCALE 1" = 200' 	
DATE	BY
REVISIONS	

SHEET 1 OF 1

KEVIN MOORE SEPTIC

PROFESSIONAL SANITARIAN # 3542

TCEQ INSTALLER II # 19037

TCEQ SITE EVALUATOR # 11071

275 Longhorn Oaks

Liberty Hill, TX 78642

Phone (512) 689-9293

Fax (512) 758-8037

septicplan@gmail.com

September 19, 2025

RE: WILD WING ACRES, ABS A0446 H.T. & B.R.R.CO., 53.069 ACRES, BURNET COUNTY
TX

DRAINAGE PLAN:

Positive drainage exists at this property.

FLOODPLAIN:

This property is not located within the 100-year floodplain.

EARZ:

This property is not located within the EARZ.

SITE EVALUATION

profile #1

0 - 16"	Class III brown silty clay loam. No evidence of ground water. No restrictions. Less than 30% gravel.
16 - 62"	Class III tan silty clay loam. No evidence of ground water. No restrictions. Less than 30% gravel.

profile #2

0 - 14"	Class III brown silty clay loam. No evidence of ground water. No restrictions. Less than 30% gravel.
14 - 60"	Class III tan silty clay loam. No evidence of ground water. No restrictions. Less than 30% gravel.

OSSF TYPES:

Based on the above-mentioned site evaluation, the following OSSF's may be utilized:

- Conventional
- Low Pressure Dose
- A.T.U. drip irrigation
- A.T.U. surface irrigation

This property is suitable for the use of private sewage facilities and will meet or exceed the requirements for on-site sewage facilities as specified under 30 TAC Chapter 285 relating to on-site sewage facilities. Sufficient replacement area exists.

KJM

Kevin J. Moore, R. S. #3542
Site Evaluator
OS-0011071



09-19-2025