



SERVICE ESTIMATE

312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

Invoice #	Order #	Date
	W0601959	08/24/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road
 Edinburg TX 78542

Ship To:
 HIDALGO COUNTY PCT #4
 1051 N. DOOLITTLE RD
 EDINBURG TX 78541

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua

Ship Via: FedEx

COMPLAINT

BROKEN HYDRUALIC COUPLER

CAUSE

FOUND COUPLER BROKEN ON QUICK DISCONNECT.

CORRECTION

REMOVED AND REPLACED COUPLER AND ADDED REQUIRED HYDRAULIC FLUID NEEDED.

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
111631		E-20 PAN SCRAPER	Miscellaneous	E-20	21920	

PARTS/LABOR

Qty./Hours	Mfr.	Part#	Description	Unit Price	Amount
1		ZONE 1-LIGHT-CON	Zone Charge**	78.00	78.00 ✓
1		FLUIDS	HYDRAULIC FLUID	7.24	72.40 ✓
1	MS	MS925875	COUPLER REPLACEMENT # 12 FEMALE	108.64	108.64 ✓
1		MISC SUPPLIES	Supplies/Hardware	10.20	10.20 ✓
2h		FL	Field Labor	80.00	160.00 ✓

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts	108.64
Labor	160.00

Misc.
Freight
Discount
Tax

160.60

Resale Cert. No. :

TOTAL

429.24



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

SERVICE ESTIMATE

Invoice #	Order #	Date
	W0601938	08/10/2009
Apply To	Customer ID	PO
	43204	JM GARCIA

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road
 Edinburg TX 78542

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD
 EDINBURG TX 78539

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua

Ship Via: FedEx

COMPLAINT

AMBER CENTRAL WARNING "CLOGGED INTERCOOLER"

CAUSE

DIRTY INTERCOOLER, A/C CONDENSOR AND RADIATOR.

CORRECTION

BLEW OUT A/C CONDENSOR, INTERCOOLER, RADIATOR, AND ENGINE COMPONENTS WERE VERY DIRTY.
 TOP OFF HYDRAULIC OIL AND TRANSMISSION OIL. UNIT TESTED OKAY.

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
111993		T450D SCRAPER HAULER	Volvo	T450D	17016	1,064.00

PARTS/LABOR

Qty/Hours	Mfr.	Part#	Description	Unit Price	Amount
2.58h		FL	Field Labor	80.00	206.40
1		FLUIDS	HYDRAULIC OIL	7.24	28.96
1		FLUIDS	TRANSMISSION OIL	9.00	18.00
1		ZONE 1-LIGHT-CON	Zone Charge**	78.00	78.00
1		MISC SUPPLIES	Supplies/Hardware	5.16	5.16

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts

Labor	206.40	✓
Misc.	130.12	✓
Freight		
Discount		
Tax		

Resale Cert. No. :

TOTAL

336.52



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

SERVICE ESTIMATE

Invoice #	Order #	Date
	W0601950	08/17/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road

 Edinburg TX 78542

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

 EDINBURG TX 78539

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua

Ship Via: FedEx

COMPLAINT

CUSTOMER CALLED AMBER WARNING

CAUSE

DIRTY FUEL FILTERS

CORRECTION

REMOVED AND INSTALLED NEW FUEL FILTERS AND TESTED UNIT OKAY.

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
111993		T450D SCRAPER HAULER	Volvo	T450D	17016	1,123.00

PARTS/LABOR

Qty/Hours	Mfr.	Part#	Description	Unit Price	Amount
1	VM	VOE20976003	FUEL FILTER	22.03	22.03
1	VM	VOE11110683	PRIMARY FILTER	55.48	55.48
1.64h	FL		Field Labor	80.00	131.20
1		ZONE 1-LIGHT-CON	Zone Charge**	78.00	78.00
1		MISC SUPPLIBS	Supplies/Hardware	3.28	3.28

Schedule Name	Amount
HIDALGO STATESTAX - 8.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL	
Parts	77.51
Labor	131.20

Misc.
Freight
Discount
Tax

81.28

Resale Cert. No. :

TOTAL

289.99



312 Park St
 Mercedes TX 78570
 Phone 956-365-0100
 Fax 956-365-1765

SERVICE ESTIMATE

Invoice #	Order #	Date
	W0601974	09/08/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road

 Edinburg TX 78542

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

 EDINBURG TX 78539

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua

Ship Via: FedEx

COMPLAINT

AMBER CENTRAL WARNING ON I-ECU DISPLAY.

CAUSE

FOUND LOW OF HYDRUALIC OIL.

CORRECTION

ADDED REQUIRED HYDRAULIC FLUID LEVEL.

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
111993		T450D SCRAPER HAULER	Volvo	T450D	17016	1,190.00

PARTS/LABOR

Qty./Hours	Mfr.	Part#	Description	Unit Price	Amount
0.50h		FL	Field Labor	80.00	40.00
1		FLUIDS-HYDRAULIC OIL	Hydraulic Oil - Chevron AW46	7.24	21.72
1		MISC SUPPLIES	Supplies/Hardware	2.20	2.20

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts	
Labor	40.00
Misc.	23.92
Freight	

Resale Cert. No. :

Discount
Tax

TOTAL

63.92



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

SERVICE ESTIMATE

Invoice #	Order #	Date
	W0601657	02/24/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road

 Edinburg TX 78542

Ship To:
HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

 EDINBURG TX 78539

Please Remit To:
ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua Ship Via: FedEx

COMPLAINT

OPERATOR COMPLAIN BURNT LAMPS, FUSES AND RELAYS.
 BROKEN ROLLER PIN ON WELDMENT ON SCRAPER SN#21924.

CAUSE

FOUND THE LAMPS FROM SCPAPERS SHORTING THE LIGHT CIRCUIT OF THE HAULER.
 FOUND DIRT BUILD UP (HARD CLAY) BINDING ON THE BOTTOM LEFT AND RIGHT CORNERS OF THE TRAVEL PATH OF BUCKET.

CORRECTION

INSTALLED NEW BULBS ON BURNT LAMPS ONE AT A TIME. CHECKED LIGHT FOR PROPER OPERATIONS OKAY.
 ON SCRAPER USE HAMMER AND CHISEL TO LOOSEN DIRT AND CLEAN AREA. RECHECKED OPERATION OF BUCKET
 CHECKED OKAY. DIRT WAS BINDING. CLEAN CRACKED ON REAR LH ROLLER PIN WELDMENT AND WBLD CRACK.
 REINSTALLED REMOVED COMPONENTS. UNIT TESTED OKAY.

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
112562		T450D SCRAPER HAULER	Volvo	T450D	17030	1,340.00

PARTS/LABOR

Qty./Hours	Mfr.	Part#	Description	Unit Price	Amount
4	VM	VOE990037	BULB	16.46	65.84
4	VM	VOE20374662	RELAY	17.04	68.16
6	VM	VOE943903	BULB	9.03	54.18
6	VM	VOE967708 ✓	BULB	4.90	29.40
2	VM	VOE990037	BULB	16.46	32.92
6	VM	VOE967709	BULB	2.94	17.64
1		MISC SUPPLIES	Supplies/Hardware	16.07	16.07
1		ZONE 1-LIGHT-CON	Zone Charge**	78.00	78.00
4.09h		PL	Field Labor	80.00	327.20

Schedule Name Amount
 Page 1 of 2 Printed on 10/22/2009 At 8:58 AM

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts	268.14
Labor	327.20
Misc.	94.07
Freight	
Discount	
Tax	

TOTAL

689.41

Resale Cert. No. :



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

SERVICE ESTIMATE

Invoice #	Order #	Date
	W0601657	02/24/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road

 Edinburg TX 78542

Ship To:
HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

 EDINBURG TX 78539

Please Remit To:
ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua Ship Via: FedEx

COMPLAINT

OPERATOR COMPLAIN BURNT LAMPS, FUSES AND RELAYS.
 BROKEN ROLLER PIN ON WELDMENT ON SCRAPER SN#21924.

CAUSE

FOUND THE LAMPS FROM SCPAPERS SHORTING THE LIGHT CIRCUIT OF THE HAULER.
 FOUND DIRT BUILD UP (HARD CLAY) BINDING ON THE BOTTOM LEFT AND RIGHT CORNERSOF THE TRAVEL PATH OF BUCKET.

CORRECTION

INSTAL;LED NEW BULBS ON BURNT LAMPS ONE AT A TIME. CHECKED LIGHT FOR PROPER OPERATIONS OKAY.
 ON SCRAPER USE HAMMER AND CHISEL TO LOOSEN DIRT AND CLEAN AREA. RECHECKED OPERATION OF BUCKET CHECKED OKAY. DIRT WAS BINDING. CLEAN CRACKED ON REAR LH ROLLER PIN WELDMENT AND WELD CRACK. REINSTALLED REMOVED COMPONENTS. UNIT TESTED OKAY.

((((note))))

Regarding the date on the work order is incorrect. i could not figure out how i entered that date, but our program is new and i have not been able to correct. Just confirm repairs date should be 09/01/09.

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
112562		T450D SCRAPER HAULER	Volvo	T450D	17030	1,340.00

PARTS/LABOR

Qty./Hours	Mfr.	Part#	Description	Unit Price	Amount
4	VM	VOE990037	BULB	16.46	65.84
4	VM	VOE20374662	RELAY	17.04	68.16
6	VM	VOE943903	BULB	9.03	54.18
6	VM	VOE967708	BULB	4.90	29.40
2	VM	VOE990037	BULB	16.46	32.92
6	VM	VOE967709	BULB	2.94	17.64
1		MISC SUPPLIES	Supplies/Hardware	16.07	16.07
1		ZONE 1-LIGHT-CON	Zone Charge**	78.00	78.00
4.09h		FL	Field Labor	80.00	327.20

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts	268.14
Labor	327.20
Misc.	94.07
Freight	
Discount	
Tax	

Resale Cert. No. :

TOTAL **689.41**



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

SERVICE ESTIMATE

Invoice #	Order #	Date
	W0601932	08/07/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road

 Edinburg TX 78542

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

 EDINBURG TX 78539

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua Ship Via: FedEx

COMPLAINT

WARNING CENTRAL AMBER ALERT. CLOGGED INTERCOOLER

CAUSE

THE ONLY THING FOUND WAS INTERCOOLER, A/C CONDENSOR AND RADIATOR DIRTY.

CORRECTION

BLEW OUT DUST FROM INTERCOOLER, CONDENSOR AND RADIATOR. TESTED ALARM AND IT STOPPED COMING ON.
 NEXT DAY RECIEVED A CALL FOR OPERATOR AND MENTION ALARM COMING UP AGAIN.
 DROVE TO JOBSITE FROM ANOTHER SERVICE CALL AND INSPECTED UNIT AND OPERATOR MENTION ALARM HAD STOPPED COMING ON. SINCE THEN IT HAS BEEN WORKING PROPERLY..

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
112362		T450D SCRAPER HAULER	Volvo	T450D	17030	1,191.00

PARTS/LABOR

Qty./Hours	Mfr.	Part#	Description	Unit Price	Amount
5.42h		FL	Field Labor	80.00	433.60
1		MISC SUPPLIES	Supplies/Hardware	24.12	24.12
1		ZONE 1-LIGHT-CON	Zone Charge**	78.00	78.00

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts	
Labor	433.60
Misc.	102.12
Freight	
Discount	
Tax	

Resale Cert. No. :

TOTAL

535.72



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

SERVICE ESTIMATE

Invoice #	Order #	Date
	W0601969	09/02/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road

 Edinburg TX 78542

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

 EDINBURG TX 78539

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua

Ship Via: FedEx

COMPLAINT

AMBER CENTRAL WARNING ON I-BCU DISPLAY AND ACCORDING TO OPERATOR(RAGUEL) WARNING IS FOR LOW ENGINE OIL LEVEL AND ENGINE IS ON DE-STROKE MODE. AND ASKED HIM OIL LEVEL WAS CORRECT HE SAID SYES.

CAUSE

FOUND HYDRAULIC OIL LEVEL LOW.

CORRECTION

DROVE TO JOBSITE AND CLIMBED THE INTO THE CAB AND FOUND THE WARNIG IS FOR THE LOW HYDRAULIC OIL LEVEL. CHECKED AND ADDED REQUIRED HYDRAULIC FLUID NEEDED.. UNIT RELEASED FOR SERVICE.

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
112562		T450D SCRAPER HAULER	Volvo	T450D	17030	1,340.00

PARTS/LABOR

Qty/Hours	Mfr.	Part#	Description	Unit Price	Amount
2.75h		FL	Field Labor	80.00	220.00
1		MISC SUPPLIES	Supplies/Hardware	14.30	14.30
1		ZONE 2-LIGHT-CON	Zone Charge**	147.33	147.33

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts	
Labor	220.00
Misc.	161.63
Freight	
Discount	
Tax	

Resale Cert. No. :

TOTAL

381.63



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road

 Edinburg TX 78542

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

 EDINBURG TX 78539

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua

Ship Via: FedEx

COMPLAINT

BROKEN PIN WELDMENT.

CAUSE

UPON CHECKING THE TRAVEL PATH OF BUCKET FOUND THE BUCKET BINDING ON THE BOTTOM LEFT AND RIGHT CORNERS DUE TO HARDEN CLAY DIRT BUILD UP. AND FOUND A CRACK ON THE WELD ON PIN WELDMENT.

CORRECTION

USE HAMMER AND CHISEL TO LOOSEN DRT TO CLEAN BUCKET TRAVEL PATH.
 CLEAN CRACK ON REAR LH ROLLER PIN WELDMENT AND WELD CRACK.
 REINSTALLED REMOVED COMPONENTS AND TESTED OUNIT FUCTION OPERATION OKAY.

*PD-13
 \$ 17030*

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
111460		E-20 PAN SCRAPER	Miscellaneous	E-20	21924	

PARTS/LABOR

Qty/Hours	Mfr.	Part#	Description	Unit Price	Amount
1		ZONE 1-LIGHT-CON	Zone Charge**	78.00	78.00
2.33h		FL	Field Labor	80.00	186.40
1		MISC SUPPLIES	Supplies/Hardware	12.12	12.12

Schedule Name	Amount
HIDALGO STATESTAX - 8.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts

Labor	186.40
Misc.	90.12
Freight	
Discount	
Tax	

Resale Cert. No. :

TOTAL

276.52



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

SERVICE ESTIMATE

Invoice #	Order #	Date
	W0602002	10/05/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Edinburg TX 78542

EDINBURG TX 78539

Taken By: Jaime Anzaldúa

Ship Via: FedEx

COMPLAINT

APRON DOOR AND EJECTOR FUNCTION NOT WORKING PROPERLY, BROKEN RETAINING BRACKETS ON RH STATIONARY DIRT SHIELD ASSEMBLY.

CAUSE

CORRECTION

APRON DOOR AND EJECTOR FUNCTION. DISCUSSED SITUATION WITH RICK SANDERS FROM (MISKIN) HE EXPLAINED IT COULD BE A SEQUENCE VALVE IS OUT OF ADJSUTMENT OR NEEDS TO BE REPACKED(O-RING). REMOVED TAMPER CAPS ON SEQUENCE VALVES, MADE ADJSUTMENT ON APRON OPEN AND EJECTOR DUMP VALVES. TESTED AND PROBLEM STILL EXIST.
 REMOVED VALVE AND INSPECTED AND FOUND PACKING DAMAGE.. RECEIVED A SEQUENCE VALVE AND TESTED OKAY. CHECKED HYDRAULIC PRESSURE AND ARE WITH IN SPECS.
 REMOVED RH STATIONARY DIRT SHIELD.STRAIGHTEN BENTS DIRT SHIELD AND ADJUSTED. ALIGN AND WELD TO SIDE FRAME
 WHILE DOING REPAIRS ASLO FOUND APRON DOOR BINDING. INSPECTED AND FOUND THE LH SIDE PANEL ON APRON DOOR RUBBING AGAINST THE SIDE PANEL OF BUCKET.
 FOUND WELD CRACKED ON FRONT LOWER AREA OF BUCKET SIDE PANEL.
 CAUSING BUCKET SIDE PANEL TO BULGE OUTWARDS, CAUSING DOOR TO BIND.
 DISCUSSED SITUATION WITH JIMMY. GO AHEAD AND REPAIR.
 DISCONNECTED SCRAPER PAN FROM OTHERS SO HAULER WOULD BE HAULING DIRT WHILE IT WAS REPAIRED.
 NEXT USED TORCH TO REMOVE OLD WELD FROM CRACKED AREA.CLEAN AREA.
 HEATED THE BENT AREA ON SIDE PANEL AND USED PRY BARS TO STRAIGHTEN.
 PREHEAT AREA WHERE BUCKET WILL BE WELDED.
 WELD SEVERAL BEADS, CLEANING FLUX INBETWEEN WELDS.
 RECONNECTED SCRAPER HAULER TO HAULER AND OPERATED SCRAPER FUNCTION OKAY.

*PD13
 #17030*

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
111460		E-20 PAN SCRAPER	Miscellaneous	E-20	21924	

PARTS/LABOR

Qty/Hours	Mfr.	Part#	Description	Unit Price	Amount
42.71h		FL	Field Labor	80.00	3,416.80
1		MISC SUPPLIES	Supplies/Hardware	80.25	80.25
1		ZONE 2-LIGHT-CON	Zone Charge**	147.33	147.33

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts	
Labor	3,416.80
Misc.	227.58
Freight	
Discount	
Tax	

TOTAL **3,644.38**

Resale Cert. No. :



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road

 Edinburg TX 78542

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

 EDINBURG TX 78539

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua Ship Via: FedEx

COMPLAINT

CUSTOMER CALLED DAMAGED ROLLER BEARING/BENT MOUNTING FRAME.

CAUSE

FOUND ONE ROLLBEARING ON INJECTOR BAD, MOUNTING FRAME BENT TO ASIDE AND ROLLER WELDMENT WAS BENT.

CORRECTION

FIRST USED 2 TORCHES TO HEAT UP BENT AREA ON THE EJECTOR FRAME TO CHERRY RED.
 THEN SLEDGE HAMMER BENT ARE TO STRIGHTEN OUT.
 USE HAND GRINDER TO SMOOTH CONTACT SURFACE WHERE PIN FLANGE MOUNTS ON EJECTOR FRAME.
 SMOOTHED OUT PIN BORE AREA WITH A ROUND STONE AND CLEAN BOLTS HOLES.
 LUBRICATE NEW ROLLER PIN WELDMENT AND ROLLER. FIT IN PLACE, SECURE WITH BOLTS
 SERVICE GREASE FITTINGS. MOVED EJECTOR FRAME FORWARD AND REVERSE AND INSPECTED EJECTOR
 FRAME AND APRAON DOOR LOOKED GOOD.
 UNIT READY FOR USE.

17030
 PP13

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
111630		E-20 PAN SCRAPER	Miscellaneous	E-20	21919	

PARTS/LABOR

Qty./Hours	Mfr.	Part#	Description	Unit Price	Amount
1	MS	MS71026010	ROLLER-EJECTOR	1,004.28	1,004.28
1	MS	MS71026009	ROLLER SHAFT	67.68	67.68
11.44h	FL		Field Labor	80.00	915.20
1		ZONE 2-LIGHT-CON	Zone Charge**	147.33	147.33
1		MISC SUPPLIES	Supplies/Hardware	50.91	50.91

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00

Schedule Name	Amount
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL

Parts	1,071.96
Labor	915.20
Misc.	198.24
Freight	
Discount	
Tax	

TOTAL

2,185.40

Resale Cert. No. :



312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

SERVICE ESTIMATE

Invoice #	Order #	Date
	WO602004	10/05/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doolittle Road
 Edinburg TX 78542

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD
 EDINBURG TX 78539

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua

Ship Via: FedEx

COMPLAINT

BENT HINGE BRACKETS ON APRON CYLINDER HOOD ASSEMBLY.

CAUSE

CORRECTION

REMOVE SAFETY CHAIN FROM HOOD AND REMOVE HOOD. STRAIGHTEN BEND SHEET METAL ON HOOD. CLEAN DIRT AROUND HINGES AND STRAIGHTEN. LUBRICATE HINGES AND REINSTALLED HOOD AND LATCH, WITH SAFETY CHAIN.

PP13 - 17030

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
111630		E-20 PAN SCRAPER	Miscellaneous	E-20	21919	

PARTS/LABOR

Qty/Hours	Mfr.	Part#	Description	Unit Price	Amount
1		MISC SUPPLIES	Supplies/Hardware	2.23	2.23
0.50h		FL	Field Labor	80.00	40.00

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL	
Parts	
Labor	40.00
Misc.	2.23
Freight	

Resale Cert. No. :

Discount
Tax

TOTAL

42.23



SERVICE ESTIMATE

312 Park St
 Mercedes TX 78570
 Phone 956-565-0100
 Fax 956-565-1765

Invoice #	Order #	Date
	W0602007	10/06/2009
Apply To	Customer ID	PO
	43204	PENDING

Bill To:
 HIDALGO COUNTY PCT. 4
 1051 N. Doelittle Road

 Edinburg TX 78542

Ship To:
 HIDALGO CNTY PCT #4
 CURVE RD & DILLION RD

 EDINBURG TX 78539

Please Remit To:
 ROMCO Equipment Co.
 P.O. Box 841496
 Dallas, TX 75284-1496
 Phone (214) 819-4100
 Fax (214) 819-4143

Taken By: Jaime Anzaldua

Ship Via: FedEx

COMPLAINT

HYDRAULIC OIL LEAK
 ORDER CALLED I BY JIMMY.

CAUSE

FOUND COUPLER BROKEN AND LEAKING OIL. ON THE MULTIFASTMNER COUPLER ASSEMBLY.

CORRECTION

REMOVED ANDF INSTALLED NEW COUPLER AND ADDED REQUIRED HYDRUALIC OIL NEEDED.

*FD-13
 # 12030*

Asset ID	Cust. Equip. No.	Description	Make	Model	Mfr. Serial No.	Meter
111631		E-20 PAN SCRAPER	Miscellaneous	E-20	21920	

PARTS/LABOR

Qty./Hours	Mfr.	Part#	Description	Unit Price	Amount
1	MS	MS925875	COUPLER REPLACEMENT # 12 FEMALE	108.64	108.64
1		FLUIDS-HYDRAULIC OIL	Hydraulic Oil - Chevron AW46	7.24	94.12
1		ZONE 1-LIGHT-CON	Zone Charge**	78.00	78.00
1		MISC SUPPLIES	Supplies/Hardware	15.58	15.58
3.50h		FL	Field Labor	80.00	280.00

Schedule Name	Amount
HIDALGO STATESTAX - 6.25	0.00
HIDALGO CNTSTAX - 0	0.00
HIDALGO CNTLCLSTAX - 0	0.00
HIDALGO CTYSTAX - 2	0.00
HIDALGO CTYLCLSTAX - 0	0.00

SUBTOTAL
 Parts 108.64

Labor	280.00
Misc.	187.70
Freight	
Discount	
Tax	

Resale Cert. No. :

TOTAL

576.34