

Texas Farm Bureau Casualty Insurance Co.

Check No.: 242356

Date: 11/23/2011 Amount Paid: \$ 2,086.30
Claim Number: 307198 Policy Number: 21587777

Payee Name and Address:

HIDALGO COUNTY SAFETY DIVISION
PO BOX 1356
EDINBURG, TX 78540-1356

Form C04/0695 - DXM 00

Texas Farm Bureau Casualty Insurance Co.

Check No.: 242356

Date: 11/23/2011 Amount Paid: \$ 2,086.30
Claim Number: 307198 Policy Number: 21587777

Payee Name and Address:

HIDALGO COUNTY SAFETY DIVISION
PO BOX 1356
EDINBURG, TX 78540-1356

Form C04/0695 - DXM 00



Texas Farm Bureau Casualty Insurance Company

P.O. Box 2689 / Waco, Texas 76702-2689

56-382
412

7242356

NOT VALID AFTER ONE YEAR

In Full Payment For 2002 FORD RANGER XL

Policy No.: 21587777 Claim No.: 307198

Table with DATE: 11-23-2011

Table with PAY THIS AMOUNT: ** 2,086.30**

Wells Fargo Bank, N.A.
115 Hospital Drive
Van Wert, OH 45891

Pay Only >



Pay to the Order Of

HIDALGO COUNTY SAFETY DIVISION
PO BOX 1356
EDINBURG, TX 78540-1356

7-CLAIMS-CHECK
DXM
Texas Farm Bureau Casualty Insurance Company

Authorized Signature

Date: 11/7/2011 04:03 PM
 Estimate ID: 30719809-02
 Estimate Version: 0
 Committed
 Profile ID: HRL

TEXAS FARM BUREAU CASUALTY * TEXAS FARM BUREAU UNDERWRITERS
 TEXAS FARM BUREAU MUTUAL * FARM BUREAU COUNTY MUTUAL INS CO OF TEXAS

FAX-956-318-265

TEXAS FARM BUREAU INSURANCE COMPANIES

P O BOX 1699, PHARR, TX 78577
 (956) 787-8844 ext. 17
 Fax: (956) 787-4365

This is an estimate only, and is the basis for determining the Actual Cash Value of the damage. This is not an authorization to repair. By law, you have the right to select where your vehicle is repaired as well as the parts used to repair it. However, TEXAS FARM BUREAU INSURANCE COMPANIES is not required to pay more than reasonable amount for the damages. You may be required to pay the difference. Any additional damages found will have to be inspected, or approved for reimbursement by a representative of TEXAS FARM BUREAU INSURANCE COMPANIES.

Damage Assessed By: SAM SANCHEZ

Appraised For: DANNY MENDEZ
 (956) 787-8844

Type of Loss: Property Damage
 Date of Loss: 10/17/2011
 Contact Date: 11/7/2011
 Deductible: NONE
 Policy No: 21587777

Claim Number: 30719809-02

Insured: JESSIE SANCHEZ
 Claimant: HIDALGO COUNTY

Mitchell Service: 917623

Description: 2002 Ford Ranger XL
 Body Style: 2D PkUpXCb 6' Bed 125" WB
 VIN: 1FTYR14U82PA67869
 Mileage: 111,538
 OEM/ALT: A
 Color: WHITE
 Options: POWER STEERING, ANTI-LOCK BRAKE SYS., V6 ENGINE, FRONT AIR DAM, TINTED GLASS ANTI-THEFT SYSTEM, AM/FM STEREO, FRONT SPLIT BENCH SEAT, STEP BUMPER

Drive Train: 3.0L Inj 6 Cyl 2WD
 License: 828605 TX
 Search Code: HRL

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	702249	BDY	REPAIR	R Pickup Bed Side Panel	Existing		4.0* #
2	AUTO	REF	REFINISH	R Bed Outer Side Panel			C 2.8
3	900500	BDY *	ADD'L LABOR OP	SPRAY BED LINER ON TAILGATE	Sublet	175.00	* 0.0*
4	AUTO	REF	REFINISH	Tailgate Complete			C 2.6 #
5	701396	BDY	REMOVE/REPLACE	Tailgate Shell	1L5Z 9940700 BA	343.02	1.0
6	701505	BDY	REMOVE/INSTALL	R Rear Combination Lamp			0.2
7	AUTO	BDY	OVERHAUL	Rear Bumper Assy			1.1
8	704908	BDY	REMOVE/REPLACE	Rear Bumper Face Bar	Remanufactured	181.00	INC
9	AUTO	REF	REFINISH	Rear Face Bar			C 1.6
10	703328	BDY	REMOVE/REPLACE	Rear Bumper Step Pad	ORDER FROM DEALER	105.87	INC

ESTIMATE RECALL NUMBER: 11/07/2011 16:03:17 30719809-02
 Mitchell Data Version: OEM: OCT_11_V

Software Version: 7.0.435

Copyright (C) 1994 - 2011 Mitchell International
 All Rights Reserved

Page 1 of 3

Date: 11/7/2011 04:03 PM
 Estimate ID: 30719809-02
 Estimate Version: 0
 Committed
 Profile ID: HRL

11	701543	BDY	REMOVE/REPLACE	R Rear Bumper Mounting Arm	F37Z 17787 A	15.92	INC
12	701544	BDY	REMOVE/REPLACE	L Rear Bumper Mounting Arm	F37Z 17788 A	16.35	INC
13	703283	BDY	REMOVE/REPLACE	R Rear Otr Bumper Bracket	ORDER FROM DEALER	13.02	INC
14	703284	BDY	REMOVE/REPLACE	L Rear Otr Bumper Bracket	ORDER FROM DEALER	12.80	INC
15	704827	BDY	REMOVE/REPLACE	Rear Bumper Stabilizer	4L5Z 17D826 AA	255.88	INC
16	AUTO	REF	ADD'L OPR	Clear Coat			2.0*
17	AUTO		ADD'L COST	Paint/Materials		252.00	*
18	AUTO		ADD'L COST	Hazardous Waste Disposal		5.00	*

* - Judgment Item
 # - Labor Note Applies
 ** QUAL REPL PART - Quality Replacement Parts
 C - Included in Clear Coat Calc

KEYSTONE AUTOMOTIVE
 11011 BLUFF BEND DR.
 AUSTIN
 TX 78753
 (800) 580-8989 (512) 339-3001

8 ** FO1102357R 181.00

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	6.3	40.00	0.00	175.00	427.00	Taxable Parts	943.86
Refinish	9.0	40.00	0.00	0.00	360.00	Sales Tax @ 8.250%	77.85
Non-Taxable Labor					787.00	Total Replacement Parts Amount	1,021.51
Labor Summary	15.3				787.00		
III. Additional Costs					Amount	IV. Adjustments	Amount
Taxable Costs					252.00	Insurance Deductible	0.00
Sales Tax			@ 8.250%		20.79	Customer Responsibility	0.00
Non-Taxable Costs					5.00		
Total Additional Costs					277.79		
Paint Material Method: Rates Init Rate = 28.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I. Total Labor:	787.00
						II. Total Replacement Parts:	1,021.51
						III. Total Additional Costs:	277.79
						Gross Total:	2,086.30
						IV. Total Adjustments:	0.00
						Net Total:	2,086.30

** - Check will be mail to you from our WACO office*

ESTIMATE RECALL NUMBER: 11/07/2011 16:03:17 30719809-02
 Mitchell Data Version: OEM: OCT_11_V

Software Version: 7.0.435

Copyright (C) 1994 - 2011 Mitchell International
 All Rights Reserved