

CHECK NUMBER: 38358
DATE ISSUED: April 12, 2012
ISSUING CODE: C
AMOUNT: \$292.48
REASON: Property Damage Liability
CLAIM NUMBER: 2012-TXE01150-A
DATE OF LOSS: 11/22/2011
INSURED: APOLINAR LOPEZ
CLAIMANT: HIDALGO COUNTY

HIDALGO COUNTY
ATTN: SAFETY DIVISION
PO BOX 1356
EDINBURG, TX 78540

FOR SECURITY PURPOSES, THE FACE OF THIS DOCUMENT CONTAINS A COLORED BACKGROUND AND MICROPRINTING IN THE BORDER

ENDEAVOR GENERAL AGENCY, LLC
PAYMENT ON BEHALF OF OLD AMERICAN COUNTY MUTUAL
3723 SOUTH FM 551
ROYSE CITY, TEXAS 75189-5763

JPMORGAN CHASE BANK, N.A.
DALLAS, TEXAS

38358
32-61/1110

TWO HUNDRED NINETY-TWO AND 48/100 DOLLARS

DATE	AMOUNT
April 12, 2012	\$292.48

PAY TO THE ORDER OF
HIDALGO COUNTY
ATTN: SAFETY DIVISION
PO BOX 1356
EDINBURG, TX 78540

VOID AFTER 90 DAYS



PD-CHAIN LINK FENCE (SUNRISE HILL COLLECION SITE IN MERCEDES TX) REF # 11/22/11

SECURITY FEATURES INCLUDED. DETAILS ON BACK

⑈038358⑈ ⑆111000614⑆ 638477117⑈

CHECK:
HIDALGO COUNTY
ATTN: SAFETY DIVISION
PO BOX 1356
EDINBURG, TX 78540

CHECK NUMBER: 38358
DATE ISSUED: April 12, 2012
ISSUING CODE: C
AMOUNT: \$292.48
REASON: Property Damage Liability
CLAIM NUMBER: 2012-TXE01150-A
DATE OF LOSS: 11/22/2011
INSURED: APOLINAR LOPEZ
CLAIMANT: HIDALGO COUNTY

ASSURED AUTO APPRAISERS OF HOUSTON
 FOR SUPPLEMENTS CALL GLENN WELLS 830-313-3630
 PO BOX 735
 FATE, TX 75132
 (830)313-3630 Fax: (866)591-2387
 Written By: GLENN WELLS

For: **OLD AMERICAN COUNTY MUTUAL FIRE INSU - ENDEAVOR GENERAL AGENCIES**
 (972)772-1820 Fax: (972)772-3782
 Adjuster: YVONNE TAYLOR (972)772-1820

PRELIMINARY ESTIMATE

Insured: APOLINAR LOPEZ	Claim # 2012-TXE01150
Owner: HIDALGO COUNTY	Policy #
Address: WESLACO, TX	Date of Loss: 11/22/2011
	Type of Loss: Collision
Business: (956)318-2644	Point of Impact:
Inspect Location:	DRIVE_IN

Repair UNKNOWN	Days to Repair
Facility: Damaged Chain Link Fence	License #

CHAIN LINK FENCE Int: _____
 VIN: Lic: _____ Prod Date: _____ Odometer: _____

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
1#	Repl	50ft Roll Chain Link Fence Fabric 4' High B20%	1		54.00		
2#	Repl	1'' 1/3'' OD Top Rail 0.065 Swedged 11gauge 10' 1/2' Sect. B20%	4		42.36		
3#	Repl	1'' 5/8'' Galv. Fence Post 6' long B20%	4		46.68		
4#	Repl	Fence Top Loop Cap B20%	3		4.41		
5#	Repl	Tie Wire B20%	1		2.98		
6#	Repl	2'' Brace Band B20%	6		5.94		
7#	Repl	Cement	1		3.35		
8#	Repl	Sand	1		3.18		
9#	Subl	Fence Labor Minimum	1		125.00	X	
10#	Subl	Haul Off Debris	1		25.00	X	
Subtotals ==>					312.90	0.0	0.0

line 1 : 20% Betterment on fence due to age and condition.
 line 2 : 20% betterment due to age and condition
 line 3 : 20% betterment taken due to age and condition
 line 4 : 20% Betterment taken due to age and condition
 line 5 : 20% betterment taken due to age and condition
 line 6 : 20% betterment taken due to age and condition

PRELIMINARY ESTIMATE

0 CHAIN LINK FENCE Int:

Estimate Notes:

THE FENCE DAMAGED IS A 4FT. FENCE. IT WILL NEED 4 POST. 40FT. OF TOP RAIL..
40FT OF CHAIN LINK FENCE. PLUS THE LABOR.

Parts	162.90
Sublet/Misc.	150.00

SUBTOTAL	\$ 312.90
Sales Tax	\$ 162.90 @ 8.2500% 13.44

TOTAL COST OF REPAIRS	\$ 326.34
-----------------------	-----------

ADJUSTMENTS:

50ft Roll Chain Link Fenc B20%	11.69
1'' 1/3'' OD Top Rail 0.0 B20%	9.17
1'' 5/8'' Galv. Fence Pos B20%	10.11
Fence Top Loop Cap B20%	0.95
Tie Wire B20%	0.65
2'' Brace Band B20%	1.29

TOTAL ADJUSTMENTS	\$ 33.86
-------------------	----------

NET COST OF REPAIRS	\$ 292.48
---------------------	-----------

ALL SUPPLEMENTS MUST BE APPROVED BY THE APPRAISERS NOTED AT THE TOP OF THE ESTIMATE.

ALL SUPPLEMENTS MUST BE APPROVED PRIOR TO REPAIRS BY THE APPRAISER LISTED ON ESTIMATE.

ANY SUPPLEMENTAL REPAIRS COMPLETED WITHOUT PRIOR APPROVAL WILL NOT BE ACCEPTED.

CCC Pathways - A product of CCC Information Services Inc.