

PAYMENT NO 1 25 221330 J
PAYMENT AMOUNT \$939.64
ISSUE DATE 06-24-2014
AUTHORIZED BY LEWIS, AUDRA
PHONE (877) 806-6920

CLAIM NO 53-468Z-107
LOSS DATE 05-20-2014
POLICY NO 1099-956-530
INSURED PHILLIPS, GARY

HIDALGO COUNTY SHERIFFS DEPARTMENT
9805 N 10TH ST
MCALLEN TX 78504-9529

REMARKS '2008 Fird Pickup F150

COVERAGE DESCRIPTION
PROPERTY DAMAGE LIABILITY

ON BEHALF OF
HIDALGO COUNTY SHERIFFS DEPARTMENT

AMOUNT
939.64

RETAIN STUB FOR RECORDS



STATE FARM MUTUAL AUTOMOBILE INSURANCE COMPANY

STRATEGIC STAFFING GROUP
SSG - AUTO OFFIC P08PCL323

JPMORGAN CHASE BANK, NA 56-1544/441
COLUMBUS, OH 43240

1 25 221330 J

CLAIM NO 53-468Z-107
LOSS DATE 05-20-2014

INSURED PHILLIPS, GARY

DATE 06-24-2014
MM DD YYYY

*****EXACTLY NINE HUNDRED THIRTY-NINE AND 64/100 DOLLARS

\$*****939.64

Pay to the
Order of: HIDALGO COUNTY SHERIFFS DEPARTMENT

Edward B. Rust Jr.
AUTHORIZED SIGNATURE
P. J. Smith
AUTHORIZED SIGNATURE

SECURED DOCUMENT WATERMARK APPEARS ON BACK, HOLD AT 45° ANGLE FOR VIEWING

⑈ 25 1 7 2 2 1 3 3 0 ⑈ ⑆ 0 4 4 1 1 5 4 4 3 ⑆

6 2 7 1 1 9 2 0 9 ⑈

GREEN DROPOUT APPEARS ON FACE OF DOCUMENT

STATE FARM MUTUAL AUTOMOBILE INSURANCE COMPANY

Date: 6/23/2014 03:59 PM
 Estimate ID: 53-468Z-10702
 Estimate Version: 0
 Committed
 Profile ID: (01664) RIO GRANDE V

State Farm Insurance Companies

Fax: (866) 418-5736

ANY SUPPLEMENT REQUESTS ARE TO BE FAXED TO STATE FARM AT 866-418-5736

Damage Assessed By: Rolando (TJAA)

Appraised For: Team 22A - CP
 (888) 257-6077

Type of Loss: Property Damage
 Date of Loss: 5/20/2014
 Deductible: 0.00
 Claim Number: 53-468Z-10702

Insured: State Farm Insured
 Claimant: HIDALGO COUNTY SHERIFFS DEPARTMENT
 Address: 9805 N 10TH ST, MCALLEN, TX 78504-9529
 Owner: HIDALGO COUNTY SHERIFFS DEPARTMENT
 Address: 9805 N 10TH ST, MCALLEN, TX 78504-9529

Mitchell Service: 910158

Description: 2008 Ford Pickup F150 XLT
 Body Style: 4D PkUpXCb 6' Bed 133" WB
 VIN: 1FTRX12WX8FB16678
 Mileage: 119,013
 OEM/ALT: A
 Color: grey
 Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
 MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS.
 AUXILIARY INPUT, CHROME WHEELS, FRONT AIR DAM, TINTED GLASS, ANTI-THEFT SYSTEM
 AUTOMATIC HEADLIGHTS, AM/FM STEREO CD/MP3 PLAYER, FRONT SPLIT BENCH SEAT
 KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, STEERING WHEEL MOUNTED CONTROLS

Drive Train: 4.6L Inj 8 Cyl 2WD
 License: 24PBT7 TX
 Search Code: SFMFE

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/Part Number	Dollar Amount	Labor Units
1	002742	BDY	REMOVE/INSTALL	R Rear Door Assembly			1.0
2	002744	BDY	REMOVE/INSTALL	R Rear Otr Belt Moulding			0.2
3	004589	BDY	REPAIR	R Rear Door Shell	Existing		6.0*
4	AUTO	REF	REFINISH	R Rear Door Outside			C 2.1
5	900500	REF *	REFINISH/REPAIR	Partial Refinish Complete Panel Clear	Existing		-0.3*
6	007762	BDY	REMOVE/INSTALL	R Rear Door Handle			0.3
7	002807	BDY	REMOVE/INSTALL	Bed Assembly			2.5
8	004636	BDY	REPAIR	R Pickup Bed Side Panel	Existing		3.0* #
9	AUTO	REF	REFINISH	R Bed Outer Side Panel			C 2.8
10	900500	REF *	REFINISH/REPAIR	Partial Refinish Complete Panel Clear	Existing		-1.0*
11	002835	BDY	REMOVE/INSTALL	R Bed Rail Moulding			0.4
12	002859	BDY	REMOVE/INSTALL	R Rear Combination Lamp			0.2
13	900500	BDY *	REMOVE/INSTALL	TOOL BOX	Existing		0.5* r
14	002867	BDY	REMOVE/INSTALL	Rear Bumper Assy			INC
15	AUTO	REF	ADD'L OPR	Clear Coat			1.4
16	900500	REF *	REFINISH/REPAIR	CORROSION PROTECTION	Existing		0.3*
17	AUTO		ADD'L COST	Paint/Materials		148.40 *	
18	AUTO		ADD'L COST	Hazardous Waste Disposal		3.00 *	

ESTIMATE RECALL NUMBER: 06/23/2014 15:59:18 53-468Z-10702

Mitchell Data Version: OEM: MAY_14_V0617

MAPP: MAY_14_V0622 Copyright (C) 1994 - 2014 Mitchell International

Software Version: 7.1.164

All Rights Reserved

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	14.1	40.00	0.00	0.00	564.00		
Refinish	5.3	40.00	0.00	0.00	212.00	Total Replacement Parts Amount	0.00
Non-Taxable Labor					776.00		
Labor Summary	19.4				776.00		
III. Additional Costs					Amount	IV. Adjustments	Amount
Taxable Costs					148.40	Insurance Deductible	0.00
Sales Tax			@	8.250%	12.24	Customer Responsibility	0.00
Non-Taxable Costs					3.00		
Total Additional Costs					163.64		
Paint Material Method: Rates Init Rate = 28.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I. Total Labor:	776.00
						II. Total Replacement Parts:	0.00
						III. Total Additional Costs:	163.64
						Gross Total:	939.64
						IV. Total Adjustments:	0.00
						Net Total:	939.64

Register online to check the status of your claim and stay connected with State Farm®. To register, go to www.statefarm.com and select Check the Status of a Claim. If you are already registered, thank you! Not available in New Mexico.

Point(s) of Impact
 4 Right Rear Side (P)

Insurance Co: State Farm

Inspection Site: HIDALGO SHERIFF DEPARTMENT
 Address: 711 EL CIBOLO ST.
 EDINBURG, TX 78541
 (956) 292-7030
 Inspection Date: 6/23/2014

ESTIMATE RECALL NUMBER: 06/23/2014 15:59:18 53-468Z-10702

Mitchell Data Version: OEM: MAY_14_V0617

MAPP: MAY_14_V0622

Copyright (C) 1994 - 2014 Mitchell International

Software Version:

7.1.164

All Rights Reserved

Date: 6/23/2014 03:59 PM
Estimate ID: 53-468Z-10702
Estimate Version: 0
Committed
Profile ID: (01664) RIO GRANDE V

This is an estimate. Repair facilities must inspect the vehicle
to determine if any repairs not listed are required, and to
contact State Farm before making such repairs. Repairer also is
responsible for conducting any necessary inspection and safety
checks prior to and after completing repairs.
