

PAYMENT NO 1 25 531048 J  
PAYMENT AMOUNT \$2,097.62  
ISSUE DATE 02-26-2015  
AUTHORIZED BY JENKINS, CEDRIC  
PHONE (877) 806-6920

CLAIM NO 53-588F-675  
LOSS DATE 01-15-2015  
POLICY NO 2555-080-53  
INSURED CHAVEZ, ALEXANDER

COUNTY OF HIDALGO  
100 N CLOSER BLVD  
EDINBURG TX 78539-3563

REMARKS damages per estimate received

COVERAGE DESCRIPTION	ON BEHALF OF	AMOUNT
PROPERTY DAMAGE LIABILITY	HIDALGO, COUNTY OF	2,097.62

RETAIN STUB FOR RECORDS

**State Farm** STATE FARM MUTUAL AUTOMOBILE INSURANCE COMPANY  
STRATEGIC STAFFING GROUP  
SSG - AUTO OFFIC P08PCL332

JPMORGAN CHASE BANK, NA 56-1544/441  
COLUMBUS, OH 43240

1 25 531048 J  
DATE 02-26-2015  
M M DD YYYY

CLAIM NO 53-588F-675  
LOSS DATE 01-15-2015

INSURED CHAVEZ, ALEXANDER

\*\*\*\*\*EXACTLY TWO THOUSAND NINETY-SEVEN AND 62/100 DOLLARS\*\*\*\*\*  
\$\*\*\*\*\*2,097.62

Pay to the Order of: COUNTY OF HIDALGO

Edward R. Smit  
AUTHORIZED SIGNATURE  
P. J. Smit  
AUTHORIZED SIGNATURE

GREEN DROPOUT APPEARS ON FACE OF DOCUMENT  
VOID IF GREEN COLORED BACKGROUND IS MISSING

SECURED DOCUMENT WATERMARK APPEARS ON BACK, HOLD AT 45° ANGLE FOR VIEWING

Date: 2/24/2015 10:59 AM  
 Estimate ID: 53-588F-67502  
 Estimate Version: 0  
 Committed  
 Profile ID: (01664) RIO GRANDE V

# State Farm Insurance Companies

Fax: (866) 418-5736

Damage Assessed By: RAMON (HMPG)

Appraised For: TX Auto Injury IA ET / 97  
 (888) 257-6077

Classification: Field

Supplements must be approved by State Farm. Itemized supplement requests and any supporting documentation should be emailed to suppteam12@statefarm.com or faxed to 866-418-5736. A Supplement Request form may be found on b2b.statefarm.com

Type of Loss: Property Damage  
 Date of Loss: 1/15/2015  
 Deductible: 0.00  
 Claim Number: 53-588F-67502

Insured: State Farm Insured  
 Claimant: COUNTY OF HIDALGO  
 Owner: COUNTY OF HIDALGO

Mitchell Service: 910158

Description: 2006 Ford Pickup F150 XL  
 Body Style: 4D Pkup 8' Bed 145" WB  
 VIN: 1FTRF12W46NB57961  
 Mileage: 110,104  
 OEM/ALT: A  
 Color: WHITE

Drive Train: 4.6L Inj 8 Cyl 2WD  
 License: 224765 TX

Search Code: SFMFE

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER STEERING, TILT STEERING COLUMN  
 ANTI-LOCK BRAKE SYS., FRONT AIR DAM, TINTED GLASS, ANTI-THEFT SYSTEM  
 FRONT SPLIT BENCH SEAT, POWER DISC BRAKES, STEP BUMPER

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	002807	BDY	REMOVE/INSTALL	Bed Assembly			INC
2	002180	BDY	REMOVE/REPLACE	L Pickup Bed Side Panel	5L3Z 9927841 A	886.05	13.5 #
3	AUTO	REF	REFINISH	L Bed Outer Side Panel			C 3.5
4	900500	MCH *	REMOVE/INSTALL	RR TIRE, TO INSPECT & AIR UP	Existing		0.2* r
5	002188	BDY	REPAIR	L Otr Pickup Bed Wheelhouse Panel	Existing		1.5* #
6	006809	BDY	REMOVE/REPLACE	L Frt Pickup Bed Brace	4L3Z 99279A29 AA	21.58	
7	006943	MCH	REPAIR	Rear Susp Axle Housing -M	Existing		0.5* #
8				TO INSPECT FOR DMG			
9	AUTO	REF	ADD'L OPR	Clear Coat			1.4
10	900500	REF *	REFINISH/REPAIR	CORROSION PROTECTION	Existing		0.3*
11	900500	BDY *	ADD'L LABOR OP	WHEEL MOUNT & BALANCE	Sublet	20.00 *	0.0*
12	900500	REF *	REFINISH/REPAIR	STONEGUARD	Existing		0.3*
13	AUTO		ADD'L COST	Paint/Materials		165.00 *	
14	AUTO		ADD'L COST	Hazardous Waste Disposal		3.00 *	

ESTIMATE RECALL NUMBER: 02/24/2015 10:59:41 53-588F-67502

Mitchell Data Version: OEM: JAN\_15\_V0216

MAPP: JAN\_15\_V0222

Copyright (C) 1994 - 2015 Mitchell International

Page 1 of 3

Software Version: 7.1.175

All Rights Reserved

\* - Judgment Item  
 # - Labor Note Applies  
 C - Included in Clear Coat Calc  
 r - CEG R&R Time Used For This Labor Operation

### Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	15.0	42.00	0.00	20.00	650.00	Taxable Parts	907.63
Refinish	5.5	42.00	0.00	0.00	231.00	Sales Tax @ 8.250%	74.88
Mechanical	0.7	75.00	0.00	0.00	52.50		
Non-Taxable Labor					933.50	Total Replacement Parts Amount	982.51
Labor Summary	21.2				933.50		
III. Additional Costs					Amount	IV. Adjustments	
Taxable Costs					165.00	Insurance Deductible	
Sales Tax @ 8.250%					13.61	Customer Responsibility	
Non-Taxable Costs					3.00		
Total Additional Costs					181.61		
Paint Material Method: Rates Init Rate = 30.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I. Total Labor:	933.50
						II. Total Replacement Parts:	982.51
						III. Total Additional Costs:	181.61
						Gross Total:	2,097.62
						IV. Total Adjustments:	0.00
						Net Total:	2,097.62

Register online to check the status of your claim and stay connected with State Farm®. To register, go to [www.statefarm.com](http://www.statefarm.com) and select Check the Status of a Claim. If you are already registered, thank you! Not available in New Mexico.

Point(s) of Impact

8 Left Rear Side (P)

Insurance Co: State Farm

Inspection Site: RESIDENCE - Pablo Herrera

Address: 504 Santa Ana  
 Weslaco, TX 78596

Inspection Date: 2/24/2015

ESTIMATE RECALL NUMBER: 02/24/2015 10:59:41 53-588F-67502

Mitchell Data Version: OEM: JAN\_15\_V0216

MAPP: JAN\_15\_V0222

Copyright (C) 1994 - 2015 Mitchell International

Software Version: 7.1.175

All Rights Reserved

Date: 2/24/2015 10:59 AM  
Estimate ID: 53-588F-67502  
Estimate Version: 0  
Committed  
Profile ID: (01664) RIO GRANDE V

\*\*\*\*\*  
This is an estimate. Repair facilities must inspect the vehicle to determine if any repairs not listed are required, and to contact State Farm before making such repairs. Repairer also is responsible for conducting any necessary inspection and safety checks prior to and after completing repairs.  
\*\*\*\*\*

ESTIMATE RECALL NUMBER: 02/24/2015 10:59:41 53-588F-67502

Mitchell Data Version: OEM: JAN\_15\_V0216

MAPP:JAN\_15\_V0222

Copyright (C) 1994 - 2015 Mitchell International

Software Version: 7.1.175

All Rights Reserved