



PUNCH LIST

To: Synergy Builders of Texas, LLC **Date:** January 29, 2018
From: Juan de Dios Chávez **AVO:** 31806 WA01
Email: jchavez@halff.com **Project:** Recovery and Motor Pool Improvements
Contract for: Hidalgo County Precinct 4

The following items require the attention of the Contractor for completion or correction. This list may not be all-inclusive, and the failure to include any items on this list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

| ITEM NO. | LOCATION (AREA) | DESCRIPTION | COMPLETION DATE | A/E CHECK DATE |
|----------|----------------------------|---|-----------------|----------------|
| 1. | PEMB | Correct hose bib installation so that back of hose bib flange is flush with CMU wall, caulk penetration to weather seal. | | |
| 2. | PEMB | Re-wire 3-way switch nearest southwest entry door so that all switches are in the same orientation when lights are in operation. | | |
| 3. | PEMB | In general, provide caulking at all penetrations into PEMB, i.e., hose bibs, conduit, and etcetera to weather seal. | | |
| 4. | PEMB Tire changing station | Bolts at steel column connections to piers have started to develop rust, per structural drawings exposed fasteners were to be hot dipped galvanized. Please contact PEMB manufacturer's engineer and have them provide their assessment/recommendation to correct this condition. | | |
| 5. | | | | |
| 6. | | | | |



5000 West Military, Ste 100
McAllen, Texas 78503
(956) 664-0286
Fax (956) 664-0282

ATTACHMENTS:

SIGNED: Juan de Dios Chávez

COPIES: OWNER CONTRACTOR

FILE