

PAYMENT NO 1 01 705233 J
PAYMENT AMOUNT \$2,493.50
ISSUE DATE 03-21-2018
AUTHORIZED BY PAUL, JAMEY
PHONE (844) 292-8615

CLAIM NO 13-2043-Z11
LOSS DATE 11-13-2017
POLICY NO D989-732-13B
INSURED KALLENBACH, CAROL

HILDAGO COUNTY
9805 N 10TH ST
MCALLEN TX 78504-9529

REMARKS pymnt per SF estimate

COVERAGE DESCRIPTION	ON BEHALF OF	AMOUNT
PROPERTY DAMAGE LIABILITY	HILDAGO COUNTY	2,493.50

RETAIN STUB FOR RECORDS

State Farm STATE FARM MUTUAL AUTOMOBILE INSURANCE COMPANY 1 01 705233 J
AUTO INJURY JPMORGAN CHASE BANK, NA 56-1544/441
INJ-D1 OFFICE AU PAGECNTQ.P07 COLUMBUS, OH
CLAIM NO 13-2043-Z11 INSURED KALLENBACH, CAROL DATE 03-21-2018
LOSS DATE 11-13-2017
EXACTLY TWO THOUSAND FOUR HUNDRED NINETY-THREE AND 50/100 DOLLARS \$***2,493.50
Pay to the Order of: HILDAGO COUNTY
Michael Flynn AUTHORIZED SIGNATURE
Jon Jamey AUTHORIZED SIGNATURE

GREEN DROPOUT APPEARS ON FACE OF DOCUMENT

VOID IF GREEN COLORED BACKGROUND IS MISSING

SECURED DOCUMENT WATERMARK APPEARS ON BACK, HOLD AT 45° ANGLE FOR VIEWING

⑈0117705233⑈ ⑈044115443⑈ 627118268⑈

State Farm Insurance Companies
Itemized supplement requests, photos and any applicable invoices should be
emailed to Suppteam12@StateFarm.com and must be approved by State Farm.
A Supplement Request form may be found on b2b.statefarm.com.
If email is unavailable, you may fax to 866-418-5736.

*** ESTIMATE ***

02/09/2018 02:45 PM

Owner

Owner: HILDAGO COUNTY
Address: 813 S ABRAM RD
City State Zip: PALMVIEW, TX 78572

Control Information

Claim # : 13-2043-Z1102
Loss Date/Time: 11/13/2017 06:00 AM

Insured Policy # :
Loss Type: Liability

Ins. Company: State Farm

Insured: State Farm Insured

Claimant: HILDAGO COUNTY
Address: 813 S ABRAM RD
City State Zip: PALMVIEW, TX 78572

Claim Rep: Express Team D
Address:

Work/Day: (855)341-8184

Inspection

Inspection Date: 02/09/2018 02:54 PM
Inspection Location: Hidalgo Precinct 3 motor pool
Address: 8310 Mile 7 1/2 North Road
City State Zip: Mission, TX 78574
Primary Impact: Left Front Corner
Driveable: No

Inspection Type: Field
Contact:
Home/Day: (956)533-4527

Secondary Impact:
Rental Assisted:

Assigned Date/Time:
First Contact Date/Time:

Received Date/Time: 02/08/2018 04:14 PM
Appointment Date/Time: 02/09/2018 10:39 AM

Appraiser Name: Greg(AYV7)

Appraiser License # :

Vehicle

2007 Ford F-150 XL 2 DR Standard Cab Long Bed
6cyl Gasoline 4.2
4 Speed Automatic

Lic.Plates: 1258086
Lic Expire:
Prod Date:
Veh Insp# :
Condition:
Ext. Color: Oxford White Solid C/C

Lic State: TX
VIN: 1FTRF122X7NA14737
Mileage: 0
Mileage Type: Non Readable
Code: P8013D
Int. Color:

Ext. Refinish: Two-Stage
 Ext. Paint Code: 4WFA

Int. Refinish: Two-Stage
 Int. Trim Code:

Options - AudaVIN Information Received

AM/FM CD Player	Air Conditioning	Anti-Lock Brakes
Automatic Trans	Black Grille	Chrome Step Bumper
Dual Airbags	Full Size Spare Tire	Halogen Headlights
Hinged Fourth Door	Hinged Third Door	Intermittent Wipers
Power Brakes	Power Steering	Privacy Glass
Running Boards	Split Front Bench Seat	Styled Steel Wheels
Tachometer	Theft Deterrent System	Tilt Steering Wheel
Tinted Glass	Vinyl Seats	Xtra Storage Cmprtmnt(s)

AudaVIN options are listed in bold-italic fonts

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Front Bumper									
1	PC	121		Bumper,Front	RECOND PART	\$281.00		2.9	SM
2	L	121		Bumper,Front	Refinish			1.7	RF
					1.4 Surface				
					0.3 Two-stage				
3	PC	4		Cvr,Front Bumper Upr	RECOND PART	\$229.57		INC	SM
4	OE	39		Spoiler,Lower Front	Replace PXN OE Srpls	\$82.15		INC	SM
				>> Russell and Smith Auto Group 800-392-1983					
				>> 1107 South Loop West					
				>> Houston TX 77054					
				>> Quote# 111518150711176, Stock# 6L3Z17626AAACP					
5	OE	6		Brkt,Front Bumper Mtg LT	Replace PXN OE Srpls	\$26.74		0.1	SM
				>> Russell and Smith Auto Group 800-392-1983					
				>> 1107 South Loop West					
				>> Houston TX 77054					
				>> Quote# 111518150711176, Stock# 4L3Z17B983ABCP					
6	E	8		Brkt,Front Bumper Mtg LT	6L3Z17755AA	\$9.47		INC	SM
7	OE	282		Brkt,Front Bumper Mtg LT	Replace PXN OE Srpls	\$15.66		INC	SM
				>> Russell and Smith Auto Group 800-392-1983					
				>> 1107 South Loop West					
				>> Houston TX 77054					
				>> Quote# 111518150711176, Stock# 4L3Z17C973AA					
Front End Panel And Lamps									
8	EU	41		Headlamp Assy,Halogen LT	RECYCLED PART	\$135.00	+30.00	INC	SM
				>> All Star Auto Lights TX 877-529-6789					
				>> 2934 N Panam Expy					
				>> San Antonio TX 78208					
				>> Quote# 111518150711176, Stock# EP191893, Matt					
9	N	973		Headlamps Aim	ADDITIONAL OPERATION			0.4	SM
Front Body And Windshield									
10	I	83		Panel,Hood	Repair			2.2*	SM
				Aluminum					
11	L	83	#	Panel,Hood	Refinish			3.5*	RF
					2.0 Surface				
					0.6 Two-stage setup				
					0.6 Two-stage				
					0.3 Feather, Prime & Block				
				# = 10, 13					
12	EU	103		Fender,Front LT	RECYCLED PART	\$125.00	+30.00	1.2	SM

		>> R and R Auto Parts TX 956-461-6733			
		>> S W Corner Exp 83 and Val Verde Rd			
		>> Donna TX 78537			
		>> Quote# 111518150711176, Stock# RR7065, Roy			
13	L	103	Fender,Front LT	Refinish	3.1 RF
				2.1 Surface	
				0.5 Edge	
				0.5 Two-stage	

Front Body Interior Sheetmetal

14	OE	111	Skirt,Inner Fender LT	Replace PXN OE Srpls	\$34.80	INC	SM
				>> Russell and Smith Auto Group 800-392-1983			
				>> 1107 South Loop West			
				>> Houston TX 77054			
				>> Quote# 111518150711176, Stock# 8L3Z16103A			

Front Suspension

15	I	974	Suspension Align,Frt	Repair		1.1*	ME
----	---	-----	----------------------	--------	--	------	----

Front Doors

16	BR	209	Pnl,Front Door Outer LT	Blend Refinish		1.3	RF
				0.9 Blend			
				0.4 Two-stage			
17	N	205	W/Strip,Belt Outer LT	ADDITIONAL OPERATION		0.6	SM
18	RI	205	W/Strip,Belt Outer LT	R & I Assembly		INC	SM
19	N	284	Mirror,Outer Standard LT	ADDITIONAL OPERATION		0.3	SM
20	RI	284	Mirror,Outer Standard LT	R & I Assembly		INC	SM
21	N	253	Handle,Front Door Otr LT	ADDITIONAL OPERATION		0.2	SM
22	RI	253	Handle,Front Door Otr LT	R & I Assembly		INC	SM

Manual Entries

23	L		Corrosion Protection	Refinish		0.3*	RF*
24	N		Hazardous Waste Removal	ADDITIONAL OPERATION	\$3.00*		SM
25	EC		Defender LTX MS LF	** NON-OEM PART	\$228.24		SM
			>> MICHELIN 245/75R17 48588 BSW 0 13 E 121R				
			>> Discount Tire 78503				
			>> McAllen TX (956) 668-9789				

25 Items

MC	Message
10	INCLUDES AUDATEX TIME TO CLEAR ENTIRE PANEL
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts		\$9.47	
OE Surplus Parts		\$159.35	
Other Parts		\$1,001.81	
Paint & Materials	9.6 Hours @ \$30.00	\$288.00	
Line Item Markup		\$78.00	
Parts & Material Total			\$1,536.63
Tax on Parts & Material	@ 8.250%		\$126.77

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$42.00	4.2	3.7	7.9	\$331.80
Mech/Elec (ME)	\$75.00		1.1	1.1	\$82.50
Frame (FR)	\$50.00				
Refinish (RF)	\$42.00	9.9		9.9	\$415.80

Labor Total	18.9 Hours	\$830.10
Gross Total		\$2,493.50
Net Total		\$2,493.50



For more information regarding State Farm's promise of satisfaction relating to new non-original equipment manufacturer (non-OEM) and recycled parts, please visit: <http://st8.fm/7X4> or QR code.

Register online to check the status of your claim and stay connected with State Farm®. To register, go to statefarm.com and select Check the Status of a Claim. If you are already registered, thank you!

Alternate Parts Y/02/02/00/00/00 CUM 02/02/00/00/00 Zip Code: 78574 Default
Rate Name (02551) Mission/McAllen


Audatex Estimating 8.0.414 ES 02/09/2018 03:55 PM REL 8.0.414 DT 01/01/2018 DB 02/08/2018
© 2018 Audatex North America, Inc.

0.3 HOURS OF REPAIR TIME WERE ALLOCATED TO FEATHER, PRIME & BLOCK AS INDICATED BY THE ESTIMATE PREPARER'S LABOR ITEMIZATION. FEATHER, PRIME & BLOCK LABOR IS REFLECTED UNDER THE REFINISH OPERATION FOR THE APPLICABLE DAMAGE ENTRY.

2.4 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = New Part
NG = Replace NAGS	EC = ** NON-OEM PART	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = ** NON-OEM PART
EU = RECYCLED PART	TE = Partial Replace Price	PM = REMAN/REBUILT PART
UM = REMAN/REBUILT PART	L = Refinish	PC = RECOND PART
UC = RECOND PART	TT = Two-Tone	SB = Sublet Repair
N = ADDITIONAL OPERATION	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	RP = RP-RELATED PRIOR	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2018 Audatex North America, Inc.
AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

