

PAYMENT NO 1 25 305418 J  
PAYMENT AMOUNT \$6,854.67  
ISSUE DATE 07-17-2018  
AUTHORIZED BY CALOWAY, DONNA  
PHONE (844) 292-8615

CLAIM NO 53-2595-P32  
LOSS DATE 12-22-2017  
POLICY NO 3275-555-53  
INSURED ESCOBAR, BLANCA D & ROLANDO

COUNTY OF HIDALGO  
9805 N 10TH ST  
MCALLEN TX 78504-9529

REMARKS damage to county vehicle - 2017 Ford Escape, VIN #1FMCU0F75H  
UA95757

COVERAGE DESCRIPTION  
PROPERTY DAMAGE LIABILITY

ON BEHALF OF  
COUNTY OF HIDALGO

AMOUNT  
6,854.67

RETAIN STUB FOR RECORDS

**State Farm** STATE FARM MUTUAL AUTOMOBILE INSURANCE COMPANY 1 25 305418 J  
AUTO INJURY INJ DT OFFICE AU PAGECNTQ.P07 JPMORGAN CHASE BANK, NA 56-1544/441 COLUMBUS, OH  
CLAIM NO 53-2595-P32 INSURED ESCOBAR, BLANCA D & ROLANDO DATE 07-17-2018  
LOSS DATE 12-22-2017  
\*\*\*EXACTLY SIX THOUSAND EIGHT HUNDRED FIFTY-FOUR AND 67/100 DOLLARS \$\*\*\*\*\*6,854.67  
Pay to the Order of: COUNTY OF HIDALGO  
Michael F. Lopez AUTHORIZED SIGNATURE  
Jan C. Farney AUTHORIZED SIGNATURE  
GREEN DROPOUT APPEARS ON FACE OF DOCUMENT  
VOID IF GREEN COLORED BACKGROUND IS MISSING  
SECURED DOCUMENT WATERMARK APPEARS ON BACK, HOLD AT 45° ANGLE FOR VIEWING

1 25 17305418

044115443

627119209



Pan American Auto, LLC  
 1001 E Whitewing Ave. Ste. C  
 McAllen, TX 78501 US  
 (956) 322-3194  
 panam.billing@gmail.com

# INVOICE

**BILL TO**  
 HIDALGO COUNTY - HEALTH  
 DEPARTMENT  
 1304 S 25TH AVE  
 EDINBURG, TX 78542

**INVOICE #** 2169  
**DATE** 07/03/2018  
**DUE DATE** 08/02/2018  
**TERMS** Net 30

ACTIVITY	SKU	QTY	RATE	AMOUNT
<b>LABOR</b> BODY WORK. INITIAL REPAIRS TO FORD ESCAPE. SEE ATTACHMENT		1	4,752.79	4,752.79
<b>LABOR</b> SUPPLEMENT - ADDITIONAL WORK REQUIRED. SEE ATTACHMENT		1	2,101.88	2,101.88

2016 FORD ESCAPE	UNIT# HD60	BALANCE DUE	<b>\$6,854.67</b>
VIN# 1FMCU0F75HUA95757			
LICENSE# 1337650	MILES - 5180		

Damage Assessed By: MITCHELL MITCHELL  
 Classification: None

Deductible: UNKNOWN

Owner: PAN AMERICAN AUTO

Mitchell Service: 911465

Description: 2017 Ford Escape S  
 Body Style: 4D Ut Drive Train: 2.5L Inj 4 Cyl FWD  
 VIN: 1FMCU0F75HUA95757  
 OEM/ALT: O Search Code: None  
 Options: PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, REAR WINDOW DEFOGGER  
 AIR CONDITION, REAR WINDOW WIPER, CRUISE CONTROL, TILT STEERING COLUMN  
 AM/FM STEREO, DRIVER AIRBAG, FRONT SIDE AIRBAG WITH HEAD PROTECTION  
 ANTI-LOCK BRAKE SYS., TRACTION CONTROL, REARVIEW CAMERA  
 TIRE INFLATION/PRESSURE MONITOR, AUXILIARY INPUT  
 BLUETOOTH WIRELESS CONNECTIVITY, CD PLAYER, POWER ADJUSTABLE EXTERIOR MIRROR  
 TRIP COMPUTER, FIRST ROW BUCKET SEAT, TELEMATIC SYSTEMS, CLOTH SEAT  
 SIDE AIRBAGS, AUTOMATIC HEADLIGHTS, SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION  
 MP3 PLAYER, DAYTIME RUNNING LIGHTS, ELECTRONIC STABILITY CONTROL  
 KEYLESS ENTRY SYSTEM, REAR BENCH SEAT, REAR SPOILER  
 STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	103495	BDY	REPAIR	Frnt Upr Bumper Cover	Existing		5.0* #
2	AUTO	BDY	REMOVE/INSTALL	R Fender Wheel Opening Mldg			0.3
3	AUTO	REF	REFINISH	Frnt Upr Bumper Cover			C 2.8
4	103508	BDY	REMOVE/REPLACE	Frnt Lwr Bumper Cover	GJ5Z 17D957 AA	147.07	2.0 #
5	AUTO	BDY	REMOVE/INSTALL	Frnt Bumper Cover			1.4 #
6	103517	BDY	REMOVE/REPLACE	Frnt Bumper License Plate Bracket	GJ5Z 17A385 AA	44.87	INC #
7	104129	BDY	REMOVE/REPLACE	R Upr Frnt Combination Lamp Assembly	GJ5Z 13008 J	942.13	0.6 #
8	AUTO	BDY	CHECK/ADJUST	Headlamps			0.4
9	104130	BDY	REMOVE/REPLACE	L Upr Frnt Combination Lamp Assembly	GJ5Z 13008 K	942.13	0.6 #
10	101507	BDY	REMOVE/INSTALL	R Hood Washer Nozzle			0.2 #
11	101508	BDY	REMOVE/INSTALL	L Hood Washer Nozzle			0.2 #
12	103949	BDY	REPAIR	Hood Panel	Existing		6.0*
13	AUTO	REF	REFINISH	Hood Outside			C 2.8
14	100693	BDY	REMOVE/REPLACE	Hood Latch	CV6Z 16700 B	73.68	0.3
15	104102	BDY	REPAIR	L Fender Panel	Existing		4.0* #
16	AUTO	REF	REFINISH	L Fender Outside			C 1.6
17	100028	BDY	REMOVE/INSTALL	L Fender Wheel Opening Mldg			0.3
18	101786	MCH	REMOVE/REPLACE	Disable & Enable Air Bag System -M			0.5
19	101788	MCH	REMOVE/REPLACE	Add To Initialize Occupant Detection ECU			0.4
20	104200	BDY	REMOVE/REPLACE	R Frnt Seat Belt	CJ5Z 78611B08 AC	346.35	0.8 #
21	104201	BDY	REMOVE/REPLACE	L Frnt Seat Belt	GJ5Z 78611B09 AA	310.23	0.8 #
22	104205	BDY	REMOVE/REPLACE	R Frnt Seat Belt Buckle	EJ5Z 9961202 AC	158.55	0.2 #
23	AUTO	BDY	REMOVE/INSTALL	R Frnt Seat Assy			0.3
24	104219	BDY	REMOVE/REPLACE	L Frnt Seat Belt Buckle	EJ5Z 9961203 AA	85.98	0.2 #
25	AUTO	BDY	REMOVE/INSTALL	L Frnt Seat Assy			0.3
26	AUTO	REF	ADD'L OPR	Clear Coat			2.0

ESTIMATE RECALL NUMBER: 02/08/2018 15:42:38 203

Mitchell Data Version: OEM: MAY\_17\_V

27 AUTO ADD'L COST Paint/Materials

\* - Judgment Item  
 # - Labor Note Applies  
 C - Included in Clear Coat Calc

### Estimate Totals

						II. Part Replacement Summary		Amount
I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals		Taxable Parts	3,050.99
Body	23.9	42.00	0.00	0.00	1,003.80	T		
Refinish	9.2	42.00	0.00	0.00	386.40	T		
Mechanical	0.9	60.00	0.00	0.00	54.00	T	Total Replacement Parts Amount	3,050.99
	Taxable Labor				1,444.20			
Labor Summary	34.0				1,444.20			
III. Additional Costs						Amount	IV. Adjustments	
					257.60		Customer Responsibility	0.00
					257.60			
Paint Material Method: Rates Init Rate = 28.00 , Init Max Hours = 99.9, Add'l Rate = 0.00								
						I.	Total Labor:	1,444.20
						II.	Total Replacement Parts:	3,050.99
						III.	Total Additional Costs:	257.60
							Gross Total:	4,752.79
						IV.	Total Adjustments:	0.00
							Net Total:	4,752.79

This is a preliminary estimate.  
Additional changes to the estimate may be required for the actual repair.

Damage Assessed By: MITCHELL MITCHELL  
 Classification: None

Deductible: UNKNOWN

Owner: PAN AMERICAN AUTO

Mitchell Service: 911465

Description: 2017 Ford Escape S  
 Body Style: 4D Ut Drive Train: 2.5L Inj 4 Cyl FWD  
 VIN: 1FMCU0F75HUA95757  
 OEM/ALT: O Search Code: None  
 Options: PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, REAR WINDOW DEFOGGER  
 AIR CONDITION, REAR WINDOW WIPER, CRUISE CONTROL, TILT STEERING COLUMN  
 AM/FM STEREO, DRIVER AIRBAG, FRONT SIDE AIRBAG WITH HEAD PROTECTION  
 ANTI-LOCK BRAKE SYS., TRACTION CONTROL, REARVIEW CAMERA  
 TIRE INFLATION/PRESSURE MONITOR, AUXILIARY INPUT  
 BLUETOOTH WIRELESS CONNECTIVITY, CD PLAYER, POWER ADJUSTABLE EXTERIOR MIRROR  
 TRIP COMPUTER, FIRST ROW BUCKET SEAT, TELEMATIC SYSTEMS, CLOTH SEAT  
 SIDE AIRBAGS, AUTOMATIC HEADLIGHTS, SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION  
 MP3 PLAYER, DAYTIME RUNNING LIGHTS, ELECTRONIC STABILITY CONTROL  
 KEYLESS ENTRY SYSTEM, REAR BENCH SEAT, REAR SPOILER  
 STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	101507	BDY	REMOVE/INSTALL	R Hood Washer Nozzle			INC #
2	101508	BDY	REMOVE/INSTALL	L Hood Washer Nozzle			INC #
3	103949	BDY	REMOVE/REPLACE	Hood Panel	GJ5Z 16612 A	560.10	1.6
4	AUTO	REF	REFINISH	Hood Outside			C 2.8
5	AUTO	REF	REFINISH	Add For Hood Underside			C 1.4
6				TORN HOOD COULD NOT BE REPAIRED			
7	103956	BDY	REMOVE/REPLACE	R Hood Hinge	GJ5Z 13796 A	35.00 *	0.3 #
8	AUTO	BDY	REMOVE/INSTALL	R Fender Assy			1.5 #
9	AUTO	REF	REFINISH	R Hinge			C 0.5
10	AUTO	BDY	REMOVE/INSTALL	Hood Assy			INC
11	103957	BDY	REMOVE/REPLACE	L Hood Hinge	GJ5Z 13797 A	35.00 *	0.3 #
12	AUTO	BDY	REMOVE/INSTALL	L Fender Assy			0.7 #
13	AUTO	REF	REFINISH	L Hinge			C 0.5
14	103368	BDY	REMOVE/REPLACE	Frt Body Radiator Shutter	GV4Z 8475 A	705.98	0.6 #
15	AUTO	BDY	REMOVE/INSTALL	Frt Bumper Cover			1.4 #
16	AUTO	REF	ADD'L OPR	Clear Coat			1.9
17	AUTO		ADD'L COST	Paint/Materials		198.80 *	

\* - Judgment Item  
 # - Labor Note Applies  
 C - Included in Clear Coat Calc

## Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	6.4	42.00	0.00	0.00	268.80 T	Taxable Parts	1,336.08
Refinish	7.1	42.00	0.00	0.00	298.20 T		
						<b>Total Replacement Parts Amount</b>	<b>1,336.08</b>
					<b>Taxable Labor</b>		
					<b>567.00</b>		
<b>Labor Summary</b>	<b>13.5</b>				<b>567.00</b>		
<b>III. Additional Costs</b>					<b>Amount</b>	<b>IV. Adjustments</b>	<b>Amount</b>
Taxable Costs					198.80	Customer Responsibility	0.00
<b>Total Additional Costs</b>					<b>198.80</b>		
Paint Material Method: Rates Init Rate = 28.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I. Total Labor:	567.00
						II. Total Replacement Parts:	1,336.08
						III. Total Additional Costs:	198.80
						Gross Total:	2,101.88
						IV. Total Adjustments:	0.00
						Net Total:	2,101.88

This is a preliminary estimate.  
Additional changes to the estimate may be required for the actual repair.