

PROGRESSIVE  
PO BOX 2930  
CLINTON, IA 52733-2930

**PROGRESSIVE**<sup>®</sup>

COUNTY OF HIDALGO  
9805 N 10TH ST  
MCALLEN, TX 78504-9529

DRAFT NUMBER: **2042594619**


AMOUNT:

**\$\*\*\*\*\*1,554.60**

ISSUE DATE: **March 21, 2022**

Form Z721 (06/15)

KEEP THIS TOP PORTION FOR YOUR RECORDS

<b>PROGRESSIVE</b> <sup>®</sup>		VOID IF NOT PRESENTED WITHIN 90 DAYS		DRAFT NUMBER:	56-389
PAYABLE THROUGH PNC BANK, N.A. 070 ASHLAND, OH 1-877-448-9544		CLAIM NUMBER: 20-6905946 NAME: COUNTY OF HIDALGO		<b>2042594619</b>	412
				<b>March 21, 2022</b>	
				PAY EXACTLY	<b>\$*****1,554.60</b>
<b>ONE THOUSAND, FIVE HUNDRED FIFTY-FOUR AND 60/100 *****</b>					
PAY TO THE ORDER OF:	COUNTY OF HIDALGO			Progressive County Mutual Insurance Company	
				BY:	
				AUTHORIZED SIGNATURE	


⑈ 204 2594619⑈ ⑆ 04 203895⑆ 4 239694516⑈

PD 47

Date: 5/15/2020 09:59 AM  
Estimate ID: 123  
Estimate Version: 0  
Preliminary  
Profile ID: \* Mitchell  
Quote ID: 67426641

### Betancourt's Collision Center

1226 N Clooner Blvd, Edinburg, TX 78541  
(956) 316-2084  
Fax: (956) 316-2048  
Email: betancourts\_collision@yahoo.com

NO TAX  


Damage Assessed By: Juan Betancourt  
Classification: None

Deductible: UNKNOWN  
File Number: 123

Owner: Unit # PD47 Hidalgo County #4  
Address: 1051 N. Dollittle Rd., Edinburg, TX 78541  
Telephone: Home Phone: (383) 311-2

Mitchell Service: 911674

Description: 2016 Chevrolet Silverado 2500HD WT  
Body Style: 4D PkUpCrw 7' Bed 154" WB  
VIN: 1G1KUEGXGF102022  
OEM/ALT: A  
Options: PASSENGER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING, AIR CONDITION  
CRUISE CONTROL, TILT STEERING COLUMN, AM/FM STEREO, DRIVER AIRBAG  
FRONT SIDE AIRBAG WITH HEAD PROTECTION, ANTI-LOCK BRAKE SYS., TRACTION CONTROL  
TIRE INFLATION/PRESSURE MONITOR, AUXILIARY INPUT, FIRST ROW SPLIT BENCH SEAT  
TELEMATIC SYSTEMS, VINYL SEAT, 4 WHEEL DRIVE, SIDE AIRBAGS  
SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION, MP3 PLAYER, DAYTIME RUNNING LIGHTS  
ELECTRONIC STABILITY CONTROL, LIMITED SLIP DIFFERENTIAL, REAR BENCH SEAT

Drive Train: 6.0L Inj 8 Cyl 4WD

Search Code: B1011831

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Hood</u>							
1	100005	REF	BLEND	Hood Outside			C 1.2
<u>Front Fender</u>							
2	100919	BDY	REMOVE/REPLACE	R Fender Panel	** QRP Certified	572.00	6.0 #
3		REF	REFINISH	R Fender Outside			C 2.4
4		REF	REFINISH	R Add To Edge Fender			C 1.2
<u>Front Door</u>							
5	102685	REF	BLEND	R Frt Door Outside			C 1.1
6	101056	BDY	REMOVE/INSTALL	R Frt Rear View Mirror			INC #
7	101081	BDY	REMOVE/INSTALL	R Frt Otr Door Belt Moulding			0.9 #
8	101177	BDY	REMOVE/INSTALL	R Frt Otr Door Handle			0.3
<u>Additional Operations</u>							
9		REF	ADD'L OPR	Clear Coat			2.0
<u>Additional Costs &amp; Materials</u>							
10			ADD'L COST	Paint/Materials		252.00 *	
11			ADD'L COST	Hazardous Waste Disposal		5.00 *	

ESTIMATE RECALL NUMBER: 05/15/2020 09:52:50 123

Mitchell Data Version: OEM: MAY\_20\_V

MAPP: MAY\_20\_V

Software Version: 7.1.230

Copyright (C) 1994 - 2020 Mitchell International  
All Rights Reserved

Date: 5/15/2020 09:59 AM  
 Estimate ID: 123  
 Estimate Version: 0  
 Preliminary  
 Profile ID: \* Mitchell  
 Quote ID: 67426641

\* - Judgment Item  
 # - Labor Note Applies  
 \*\* QRP Certified - Quality Replacement Parts - Certified  
 C - Included In Clear Coat Calc

KEYSTONE-INS QUALITY PRT  
 5001 TANYA AVE.  
 MC ALLEN  
 TX 78503  
 (800) 580-0663 (956) 797-4430

2 \*\* GM1241386C 572.00

### Estimate Totals

						II. Part Replacement Summary		
						Amount		
I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	Taxable Parts	572.00	
Body	7.2	48.00	0.00	0.00	345.60			
Refinish	7.9	48.00	0.00	0.00	379.20			
Non-Taxable Labor					724.80	Total Replacement Parts Amount	572.00	
Labor Summary	15.1				724.80			
III. Additional Costs						IV. Adjustments		
						Amount		
Taxable Costs						257.80	Customer Responsibility	0.00
Total Additional Costs						267.80		
Paint Material Method: Rates								
Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00								
						I. Total Labor:	724.80	
						II. Total Replacement Parts:	572.00	
						III. Total Additional Costs:	257.80	
						Gross Total:	1,554.60	
						IV. Total Adjustments:	0.00	
						Net Total:	1,554.60	

This is a preliminary estimate.  
Additional changes to the estimate may be required for the actual repair.

*NO TAX*  
