WILLIAMSON COUNTY, TEXAS CHANGE ORDER NUMBER: 2



1. CONTRACTOR: J.C. Evans Construction		Project: 11WC902
2. Change Order Work Limits: Sta. 290+00 to	Sta1160+00	Ronald Reagan Roadway: <u>Blvd N Ph. 3</u>
. Type of Change(on federal-aid non-exempt projects):	minor (Major/Minor)	
. Reasons: 1A (3 Max In order o	f importance - Primary first)	CSJ:
Describe the work being revised:		
A: Design Error or Omission. Incorrect PS&E. This Change	Order corrects the quantity for t	the length of the bridge beams at
erry Creek and adds a pay item for drill shaft cores.		
	Attached	
New or revised plan sheet(s) are attached and numbered		a No.
New Special Provisions to the contract are attached:	☐ Yes ⊡	⊡ No
. New Special Provisions to Item N/A No. N/A , Sp	ecial Specification Item N	/A are attached.
ach signatory hereby warrants that each has the authority	to execute this Change Orde	r (CO).
he contractor must sign the Change Order and, by doing so, agrees to waive	The following informa	ntion must be provided
ny and all claims for additional compensation due to any and all other		
penses; additional changes for time, overhead and profit; or loss of impensation as a result of this change.	Time Ext. #: N/A	Days added on this CO: 0
THE CONTRACTOR Date 9/12/2011	Amount added by this char	nge order: \$1,314.05
56 & O .		
By Open Corn		
Typed/Printed Name		
2 111-		
Typed/Printed Title POJECT MANAGER		
ECOMMENDED FOR EXECUTION:		
	County Commissi	oner Precinct 1 Date
Jamo D To P.E. 9/12/11	☐ APPROVED	☐ REQUEST APPROVAL
Project Manager Date		
NVA	County Commissi APPROVED	oner Precinct 2 Date REQUEST APPROVAL
N/A Design Engineer Date	- ATTROVED	- REGOEST AT THO THE
, 1		
M / U = 1	County Commissi	ioner Precinct 3 Date
/// Why 1/13/2011	☐ APPROVED	REQUEST APPROVAL
Program Manager Date		
Sanisa Fara Sanis		
Design Engineer's Seal:	County Commiss	ioner Precinct 4 Date
N/A	☐ APPROVED	☐ REQUEST APPROVAL
		a
	☐ County APPROVED	Judge Date

WILLIAMSON COUNTY, TEXAS

CHANGE ORDER NUMBER: 2

Project# 11W

TABLE A: Force Account Work and Materials Placed into Stock

IABLE A: O'CO NOOVER VIOLENING HEAVENING THE TENTON TO THE TENTON	I ABOR					

	14.1								
TABLE B: Contract Items	ract tiems			ORIGINAL	ORIGINAL + PREVIOUSLY REVISED	ADD or (DEDUCT)	N	NEW	
	DESCRIPTION	TINU	UNIT PRICE	QUANTITY	ITEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUN/ UNDERRUN
2000 300	DEECTDESCED CONCDETE BEAM (TVDE C.)	1	\$135.00	2,357.00	\$318,195.00	6.03	2,363.03	\$319,009.05	\$814.05
425-2003	DRILL SHAFT CORES	EA	\$125.00	00:00	\$0.00	4.00	4.00	\$500.00	\$500.00
									-
									-
								The second secon	
		1							
		1	A STREET, SALL OF THE PARTY OF			The state of the s	The state of the s		
			Annual desiration of the Contract of the Contr		The state of the s		- Constitution of the last of	-	The same of the sa
Commence of the Commence of th							-		-
Name and Address of the Owner, when the Party of the Owner, when the Owner, which the Owner, when the Owner, which the						and the second s			
								-	The same of the sa
The same and the s								STATE OF THE PARTY	-
							-	-	
The same of the sa								The same of the sa	-
			AMERICA DE L'OTTO PERO PERO DE LA COMPANSION DE L'ACTUAL DE L'ACTU						
		1		The state of the s	NEW STREET, WITHOUT STREET, STREET, WILLIAM STREET, ST				
					And the second s				
		Ī							
			and the second s		£348 195 00			\$319,509.05	\$1,314.05
The same of the sa	OIALS				20101100	The same of the sa	The second secon		

CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E
1. Design End of Offission	1B. Other
	ib. Other
2. Differing Site Conditions	2A. Dispute resolution (expense caused by conditions and/or resulting delay)
(unforeseeable)	2B. Unavailable material
,	2C. New development (conditions changing after PS&E completed)
	2D. Environmental remediation
	2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9)
	2F. Site conditions altered by an act of nature
	2G. Unadjusted utility (unforeseeable)
	2H. Unacquired Right-of-Way (unforeseeable)
	21. Additional safety needs (unforeseeable)
	2J. Other
	EJ. Olici
3. County Convenience	3A. Dispute resolution (not resulting from error in plans or differing site conditions)
d. Sourity Convenience	3B. Public relations improvement
	3C. Implementation of a Value Engineering finding
	3D. Achievement of an early project completion
	3E. Reduction of future maintenance
	3F. Additional work desired by the County
	3G. Compliance requirements of new laws and/or policies
	3H. Cost savings opportunity discovered during construction
	Implementation of improved technology or better process
	3J. Price adjustment on finished work (price reduced in exchange for acceptance)
	3K. Addition of stock account or material supplied by state provision
	Revising safety work/measures desired by the County Other
	SW. Other
Third Party Accommodation	4A. Failure of a third party to meet commitment
4. Third Party Accommodation	4B. Third party requested work
	A STATE OF THE STA
	4D. Other
Contractor Convenience	5A. Contractor exercises option to change the traffic control plan
5. Contractor Convenience	
	5C. Payment for Partnering workshop
	5D. Additional safety work/measures desired by the contractor
	5E. Other
C. Halimak DOM III BURGA	CA. Dight of May not aloge (third party responsibility for DOM)
Untimely ROW/Utilities	6A. Right-of-Way not clear (third party responsibility for ROW)
	6B. Right-of-Way not clear (County responsibility for ROW)
	6C. Utilities not clear
	6D. Other

Williamson County Road Bond Program

Ronald Reagan Blvd North, Phase 3 Williamson County Project No. 11WC902

Change Order No. 2

Reason for Change

This Change Order corrects the quantity for the length of the bridge beams at Berry Creek and adds a pay item for drill shaft cores. After reevaluation of the design, six inches of length was added to each of the twelve Type C beams, so that the length of the beams matched the designed span width.

A drill shaft core is a 6 inch diameter, 5 feet deep hole, which is drilled beyond the finished elevation of the drill shaft to confirm that the shaft is founded on solid material. Specification Item 416 specifies the cost of a core as \$125.00 each. One core is will be taken on the first drill shaft of each bent.

Following is a description of the new items required for this Change Order.

ITEM	DESCRIPTION	QTY	UNIT
416-2005	DRILL SHAFT CORES	4.00	EA

This Change Order results in a net increase of \$1,314.05 to the Contract amount, for an adjusted Contract amount of \$9,483,646.71. The original Contract amount was \$9,449,782.66. As a result of this and all Change Orders to-date, \$33,864.05 has been added to the Contract, resulting in a 0.4% net increase in the Contract Cost. No additional days will be added to or deducted from the Contract as a result of this Change Order.

HNTB Corporation

James Klotz, P.E.