WILLIAMSON COUNTY, TEXAS CHANGE ORDER NUMBER: _2_

. CONTRACTOR: Westar Construction, Inc.		Project: Splashpad
2. Change Order Work Limits: Sta to	Sta.	ParkProject 07WC501
3. Type of Change(on federal-aid non-exempt projects):	(Major/Minor)	Purchase Order Number:
. Reasons: 2E; 3F; 3J (3 Max In order c	f importance - Primary first)	
Describe the work being revised: changes necessary due to unforeseeable site conditions; a andscaping due to drought. (Please see attached)	iditional work requested by the	e County; price adjustment on
Work to be performed in accordance with Items: New or revised plan sheet(s) are attached and numbere. New Special Provisions to the contract are attached: New Special Provisions to Item N/A No. N/A Sach signatory hereby warrants that each has the authority	☐ Yes ☑ pecial Specification Item <u>N</u>	
	The following informati	
ne contractor must sign the Change Order and, by doing so, agrees to waive ny and all claims for additional compensation due to any and all other penses; additional changes for time, overhead and profit; or loss of Impensation as a result of this change.		ays added on this CO: 0
THE CONTRACTOR Date 1122 2011	Amount added by this chang	ge order: \$12,809.35
Зу		
Typed/Printed Name NAN WILLIAMSON VOKANA VI		
Typed/Printed Title \(\begin{align*} \text{ICSDEO} \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\		
ECOMMENDED FOR EXECUTION:		
Project Manager Date	County Commissio APPROVED	ner Precinct 1 Dar REQUEST APPROVAL
Construction Observer		
Design Engineer Date	County Commissio APPROVED	ner Precinct 2 Da REQUEST APPROVAL
Program Manager Date	County Commissio	ner Precinct 3 Da REQUEST APPROVAL
esign Engineer's Seal:		
ANDSCAPE	County Commissio	ner Precinct 4 Da REQUEST APPROVAL
CHAIN COL	☐ County Ji APPROVED	udge Da

Changes for Discussion-REVISED September 19, 2011

Tebra depth of WW line trench- plan grades incorrect Sauces Carry Genth Unit Price Sauces Carry Genth Sauces Carry Genth Sauces Carry Genth Sauces Carry Genth Sauces			
Extra depth of WW line trench- plan grades incorrect Extra depth of WW line trench- plan grades incorrect **Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for 55,200.00 WW line crossing RR line not shown on plan Extra time for tencher and operator at the line (delay and extra time working) 1 HR Extra time for tencher and operator at the line (delay and extra time working) 1 HR Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra fraction crossing Borho Dr disovered waterline (to pond) not shown on plan Extra Gravel added 30" RCP Storm pipe was installed with gravel not stra working around line 1 HR Originally asked for \$3,700.00 Uf Originally asked for \$3,700.00 Uf Originally asked for \$3,750.00 Extra Gravel added and water against to Extra equipment/ Originally asked for \$3,750.00 Uf Originally asked for \$3,750.00 Uf Originally asked f	ahamelii koodiini (ee tiimeladdali is edhiila	taliations and tabulation documents	EXTRA MOBILIZATION FOR THE STEEL ERECTOR
Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan *Originally osked for \$5,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) Gravel, hand digging, resetting the tracks-equipment, labor, and material *Originally osked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working) *Originally osked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working) time *Originally osked for \$5,000.00 Extra fine lost standard work around line 1 HR *Originally asked for \$5,700.00 Extra Gravel added- 30" RCP Storm pipe was installed with gravel to Spring Line per spec. UDG Engineer was on-site & advised WCI that pipe needed 12" of gravel over top of pipe. Later confirmed UDG was incorrect. Re-excavate, realign pipes, add extra gravel, re-backfill, recompact. Extra equipment/ Originally osked for \$3,750.00/ Unit Price for 30" RCP was \$35.00 LF *This price is directly from Invoice of the welder with no mark up. *This price is directly from Invoice of the welder with no mark up. *Originally asked for \$32,550.00 line *This price is directly from Invoice of the welder with no mark up.		A THE TAXABLE STATES OF THE ST	
Extra depth of WW line trench- plan grades incorrect Difference per Bid Unit Price Sheet to go from 4-6 Depth to 6-9 depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR 5 Originally asked for \$5,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR Gravel, hand digging, resetting the tracks-equipment, labor, and material Paper. Unit Price Shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR 6 Paper. Dr discovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time 1 HR 6 Paper. Dr discovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time 1 HR 7 Paper. Dr discovered waterline (to pond) not shown on plan Extra Gravel added - 30" RCP Storm pipe was installed with gravel to Spring Line per 1 HR 8 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 1 HR 1 Paper. Dr discovered water and digging and hand work around line 2 HR 1 Paper. Dr discovered water and digging and hand work around line 3 HR 1 Paper. Dr discovered water and	in April 2011) WC 1014	32,650.00	
Extra depth of wW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator *Originally osked for \$6,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working ime 1 1 HR *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working ime 1 1 HR *Originally asked for \$5,700.00 We line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working ime 1 1 HR *Originally asked for \$5,700.00 Extra Gravel added - 30" RCP Storm pipe was installed with gravel to Spring Line per spec. UDG Engineer was on-site & advised WCI that pipe needed 12" of gravel over top of pipe. Later confirmed UDG was incorrect. Re-excavate, realign pipes, add extra gravel, re-backfili, recompact- Extra equipment/ Operator, Labor, Material *Originally asked for \$3,750.00/ Unit Price for 30" RCP was \$95.00 LF ELECTRICAL- Add welded mounting plates for lights in pavilion. Welding/ Labor 12.5 HR Welding/ Labor 12.5 HR	sheered to company and	**************************************	
Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR Setra time for trencher and labor 1 HR Setra time for trencher and labor 1 HR Setra time for trencher and labor 25,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR Setra time for trencher and operator at the line (delay and extra time working) 1 HR Setra time for trencher and operator at the line (delay and extra working time 1 HR Setra time for trencher and operator at the line (delay and extra working time 1 HR Setra time for trencher and operator at the line (delay and extra working time 1 HR Setra time for trencher and operator at the line (delay and extra working time 1 HR Setra Gravel added - 30" RCP Storm pipe was installed with gravel to RR Owner for Tracks 1 HR Setra Gravel added - 30" RCP Storm pipe was installed with gravel to Spring Line per spring Line per Security of gravel over top Operator, Labor, Material Operator, Labor, Material Security of gravel over top Operator, Labor, Material Setra Gravel for \$3,750.00 Unit Price for 30" RCP was \$95.00 LF Setra Gravel, Installed with gravel to Spring Line per Setra gravel, Installed for \$50.00 Unit Price for 30" RCP was \$95.00 LF Setra Gravel, Labor, Material Setra Gravel, Installed for Setra Gravel, Labor, Material Set HR Setra Gravel, Labor Se	-	-	Material- angle iron for 10 plates
Changes/ Issues Changes/ Issues Odty. Unit VI Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR 5 *Originally asked for \$6,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR 5 *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR 5 *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time 1 HR 5 *Originally asked for \$5,000.00 Extra Gravel added 30" RCP Storm pipe was installed with gravel to Spring Line per 1 HR 1 H	╁	-	Annie de Francis de Santos de Caracterís de
Extra depth of WW line trench- plan grades incorrect *Difference Der Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR \$ *Originally asked for \$5,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR Gravel, hand digging, resetting the track-equipment, labor, and material 0.5 HR Payment to RR Owner for Tracks 1 LS \$ *Originally asked for \$5,000.00 WW line installation crossing Borho Dr discovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR Payment to RR Owner for Tracks 1 LS \$ *Originally asked for \$5,000.00 Extra Gravel added-30" RCP Storm pipe was installed with gravel to Spring Line per per spec. UDG Engineer was on-site & advised WCI that pipe needed 12" of gravel over top of pipe. Later confirmed UDG was incorrect. Extra confirmed UDG was incorrect. Coperator, Labor, Material 0.0 LF Price for 30" RCP was \$95.00 LF			ELECTRICAL- Add welded mounting plates for lights in pavilion.
Changes/ Issues Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-5' Depth to 6'-9' depth *WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR Sorginally asked for \$5,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR Sorginally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (delay and extra working around line 1 HR Extra Gravel added- 30" RCP Storm pipe was installed with gravel to Spring Line per spec. UDG Engineer was on-site & advised WCI that pipe needed 12" of gravel over top for pipe. Later confirmed UDG was incorrect. Changes/ Issues A00 LF Extra time for trencher and sperator at the line (delay and extra time working) 1 HR Back Hoe for working around line 1 HR Back Hoe for working around line 3 HR Actra Gravel added- 30" RCP Storm pipe was installed with gravel to Spring Line per spec. UDG Engineer was on-site & advised WCI that pipe needed 12" of gravel over top Extra confirmed UDG was incorrect. Operator, Labor, Material		The state of the s	*Originally asked for \$3,750.00/ Unit Price for 30" RCP was \$95.00 LF
Changes/ Issues Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-5' Depth to 6'-9' depth *Difference per Bid Unit Price Sheet to go from 4'-5' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR S *Originally asked for \$5,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR S *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (delay and extra working around line 1 HR Back Hoe for working around line 1 HR Back Hoe for working around line 1 HR Labor Gravel added-30" RCP Storm pipe was installed with gravel to Spring Line per spec. UDG Engineer was on-site & advised WCI that pipe needed 12" of gravel over top of pipe. Later confirmed UDG was incorrect.	-		Operator, Labor, Material
Changes/ Issues Changes/ Issues Changes/ Issues Auty Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator in the line (delay and extra time working) Avoiginally asked for \$5,000.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) Avoiginally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time installation crossing borho Dr disovered waterline (to pond) not shown on plan Extra Gravel added - 30" RCP Storm pipe was installed with gravel to Spring Line per 100 LF page. UDG Engineer was on-site & advised WCI that pipe needed 12" of gravel over top 100 LF page. UDG Engineer was incorrect.	-		Re-excavate, realign pipes, add extra gravel, re-backfill, recompact- Extra equipment/
Changes/ Issues Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4.6' Depth to 6'.9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR 5 *Originally asked for \$5,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR 5 *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time Extra time for trencher and operator at the line (delay and extra working time 1 HR 5 *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time 1 HR 1 H			of pipe. Later confirmed UDG was incorrect.
Changes/ issues Qty. Unit Extra depth of WW line trench- plan grades incorrect 400 LF *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth 80 LF *WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR * Originally asked for \$6,200.00 Extra time for backfilling in confined area- equipment and labor 1 HR 5 * Originally asked for \$5,200.00 Extra time for trencher and operator at the line (delay and extra time working) 1 HR 5 *Originally asked for \$5,000.00 Fayment to RR Owner for Tracks 1 LS 5 *Originally asked for \$5,000.00 Fayment to RR Owner for Tracks 1 LS 5 *Originally asked for \$5,000.00 Back Hoe for working around line 1 HR HR *Originally asked for \$5,700.00 Labor for hand digging and hand work around line 1 HR *Originally asked for \$5,700.00 Labor for hand digging and hand work around line 1 HR *Originally asked for \$5,700.00 LB HR HR			spec. UDG Engineer was on-site & advised WCi that pipe needed 12" of gravel over top
Extra depth of WW line trench- plan grades incorrect Qty. Unit Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth 400 LF **Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth 80 LF **WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR **Originally asked for \$5,200.00 Extra time for backfilling in confined area- equipment and labor 1 HR 5 **Originally asked for \$5,200.00 Extra time for trencher and operator at the line (delay and extra time working) 1 HR 5 **Originally asked for \$5,000.00 Fastra time for trencher and operator at the line (delay and extra time for Tracks 1 LS \$ **Originally asked for \$5,000.00 Labor for hand digging and hand work around line 1 HR HR **Originally asked for \$5,700.00 Labor for hand digging and hand work around line 1 HR HR		-	Extra Gravel added- 30" RCP Storm pipe was installed with gravel to Spring Line per
Extra depth of WW line trench- pian grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth *WW line running directly along batting cages not shown on plan Extra time for backfilling in confined area- equipment and labor *Originally asked for \$6,200.00 *WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working around line the line line (delay and extra working around line the line line line line line line line lin		With the state of	HIGHRIY OSKERJIH 33,700.00
Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4*-6" Depth to 6*-9" depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator at the line (delay and extra time for Tracks and material payment to RR Owner for Tracks and material payment to RR Owner for Tracks and more for trencher and operator at the line (delay and extra time for trencher and operator at the line (delay and extra time for Tracks and material payment to RR Owner for Tracks and REXTra time for trencher and operator at the line (delay and extra working time and the line (delay and extra working around line and l		1	
Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4.6' Depth to 6.9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR 5 *Originally asked for \$6,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR 6 *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time 1 HR 6 Back Hoe for working around line 1 HR 1 HR 1 *HR 1 HR 1 *Originally asked for \$5,000.00		_	Labor for hand digging and hand work around line
Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR 5 *Originally asked for \$6,200.00 WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR 6 *Originally asked for \$5,000.00 WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan Extra time for trencher and operator at the line (delay and extra working time 1 HR 6 *Originally asked for \$5,000.00	_	_	Back Hoe for working around line
Changes/ Issues Qty. Unit U Extra depth of WW line trench- plan grades incorrect 400 LF *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth 80 LF WW line running directly along batting cages not shown on plan 80 LF Extra time for trencher and operator 1 HR * Originally asked for \$6,200.00 1 HR WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR * Originally asked for \$5,000.00 Payment to RR Owner for Tracks 1 LS \$ *Originally asked for \$5,000.00 1 LS \$			Extra time for trencher and operator at the line (delay and extra working time)
Changes/ Issues Qty. Unit U Extra depth of WW line trench- plan grades incorrect 400 LF *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth 80 LF WW line running directly along batting cages not shown on plan 80 LF Extra time for trencher and operator 1 HR * Originally asked for \$6,200.00 1 HR WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR * Originally asked for \$5,200.00 Payment to RR Owner for Tracks 1 HR *Originally asked for \$5,000.00 Payment to RR Owner for Tracks 1 LS			WW line installation crossing Borho Dr disovered waterline (to pond) not shown on plan
Changes/ Issues Qty. Unit U Extra depth of WW line trench- plan grades incorrect 400 LF **Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth 5 LF **WW line running directly along batting cages not shown on plan 80 LF Extra time for trencher and operator 1 HR **Originally asked for \$6,200.00 5 HR **WW line crossing RR line not shown on plan 5 HR **WW line crossing RR line not shown on plan 5 HR **Water a time for trencher and operator at the line (delay and extra time working) 1 HR **Gravel, hand digging, resetting the tracks-equipment, labor, and material 0.5 HR **Batter time for Tracks 1 LS \$			*Originally asked for \$5,000.00
Extra depth of WW line trench- plan grades incorrect Qty. Unit U **Difference per Bid Unit Price Sheet to go from 4-6' Depth to 6'-9' depth 400 LF **WW line running directly along batting cages not shown on plan 80 LF **Extra time for trencher and operator 1 HR **Originally asked for \$6,200.00 56,200.00 1 HR **WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR **WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR **Extra time for trencher and operator at the line (delay and extra time working) 1 HR **Batter time for trencher and operator at the line (delay and extra time working) 1 HR	 		Payment to RR Owner for Tracks
Extra depth of WW line trench- plan grades incorrect Qty. Unit U *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth 400 LF WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR * Originally asked for \$6,200.00 Extra time for backfilling in confined area- equipment and labor 1 HR \$ WW line crossing RR line not shown on plan Extra time for trencher and operator at the line (delay and extra time working) 1 HR	-		Gravel, hand digging, resetting the tracks-equipment, labor, and material
Changes/ Issues Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator *Originally asked for \$6,200.00 WW line crossing RR line not shown on plan Changes/ Issues #Extra time for trencher and operator ### \$5 ### \$5 ### \$5			Extra time for trencher and operator at the line (delay and extra time working)
Changes/ Issues Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator Extra time for backfilling in confined area- equipment and labor 1 HR \$ *Originally asked for \$6,200.00			WW line crossing RR line not shown on plan
Changes/ Issues Extra depth of WW line trench- plan grades incorrect *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth *WW line running directly along batting cages not shown on plan Extra time for trencher and operator Extra time for backfilling in confined area- equipment and labor 1 HR 5		-	* Originally asked for \$6,200.00
Changes/ Issues Qty. Unit U Extra depth of WW line trench- plan grades incorrect 400 LF *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth WW line running directly along batting cages not shown on plan Extra time for trencher and operator 1 HR			Extra time for backfilling in confined area- equipment and labor
Changes/ Issues Qty. Unit Unit Extra depth of WW line trench- plan grades incorrect 400 LF **Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth			Extra time for trencher and operator
Changes/ Issues Qty. Unit Unit Extra depth of WW line trench- plan grades incorrect 400 LF *Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth			WW line running directly along batting cages not shown on plan
Changes/ Issues Qty. Unit Unit Extra depth of WW line trench- plan grades incorrect 400 LF	-		*Difference per Bid Unit Price Sheet to go from 4'-6' Depth to 6'-9' depth
Changes/ Issues Qty. Unit		-	Extra depth of WW line trench- plan grades incorrect
	Acceptants.		Changes/ issues

	5	-	No. DEDUCES	
	Landscape/ Irrigation	8 Concrete Sidewalks	No. DEBUCTS- ITEMS LEFT ON PAY APPLICATION	
SALONO	-58,800 00	-\$2,250.80		

NET TOTAL CHANGE ORDER 2 \$12,809.35