

Williamson County

Asset Status Change Form

The following asset(s) is(are) considered for: (select one)

- ☐ TRANSFER bet ween county departments
☐ SALE at the earliest auction *
☐ TRADE-IN for new assets of similar type for the county
- ☐ DONATION to a non-county entity
☒ DESTRUCTION due to Public Health / Safety
☐ SALE to a government entity / civil or charitable organization in the county at fair market value

Asset List:

Quantity	Description (year, make, model, etc.)	Manufacturer ID# (serial, service tag, or VIN)	County Tag#	Condition of Assets (Working, Non-Working)
1	Stryker Model 6500 Ambulance Cot	101239588		Working
	* NOTE: SALE TO INSURER; AMBULANCE COT BEING SENT TO TAC FOR INSURANCE REIMBURSEMENT			

Parties involved:

FROM (Transferor Department): EMS - 0540 - See attached letters from Stryker and Williamson County EMS.

**Transferor - Elected Official/Department Head/
Authorized Staff:**

Mike Knipstein
Print Name

Signature

Contact Person:

Mike Knipstein
Print Name

5/15/12 +1 (512) 943-1224
Date Phone Number

TO (Transferee Department/Auction/Trade-in/Donee): SALE TO INSURER

**Transferee - Elected Official/Department Head/
Authorized Staff OR Donee - Representative:** (If being approved for Sale or Trade-in, no signature is necessary.)

Print Name

Signature

Date

Contact Person:

Print Name

Phone Number

RECEIVED

MAY 25 2017

AUDITOR'S OFFICE
WILLIAMSON COUNTY, TEXAS

* If the above asset(s) is (are) listed for sale at auction and no bids are made, the Purchasing Director may dispose of or donate this (these) asset(s). A list of the (these) asset(s) to be donated or disposed of will be sent to the Auditor's Office with a date of donation or disposal.

Forward to County Auditor's Office

This Change Status was approved as agenda item # _____ in Commissioner's Court on _____

If for Sale, the asset(s) was(were) delivered to warehouse on _____ by _____

WILLIAMSON COUNTY EMS*To Respect, Care & Serve*

To: Whom It May Concern
From: Mike Knipstein *MK*
Date: 05/15/2017
Re: Salvage of Stryker Model 6500 Ambulance Cot

On 04/18/2017 a Williamson County EMS ambulance was involved in a collision. The Stryker Model 6500 Ambulance Cot serial number 101239558 was secured in the back of the ambulance.

Per manufacturer recommendations the collision was reported to Stryker Medical Regulatory Affairs. As stated in the attached memos it is recommended that this ambulance cot be replaced. An insurance claim was filed with Texas Association of Counties (TAC), and TAC will take possession of the ambulance cot once approved by the Williamson County Commissioner's Court.





Williamson County EMS

Attn: Kirk Becker

508 Holly Street

Georgetown, TX 78626-5115

Dear: Mr. Becker

This letter is written in regard to the status of your Model 6500 Ambulance Cot serial number 101239588 and associated cot fastening system (collectively the "Products"), manufactured by Stryker Corporation's Medical division ("Stryker" or "we"). We understand that the Products have been involved in an ambulance accident.

Under normal use conditions Stryker products are warranted to perform to their specifications for the duration of their expected service life; however, there are extenuating circumstances and events that may alter the performance of the products. Such is the case when the product is involved in an ambulance accident.

Stryker has received information related to the circumstances surrounding the ambulance accident which involved the Product(s) listed above. In reference to this ambulance accident, one or more of the following occurred:

- The ambulance accident and/or Product(s) exceeded the criteria for qualifying for a post-ambulance accident inspection*
- The Product(s) failed the post-ambulance accident inspection
- The mandatory repairs following the post-ambulance accident inspection were not completed

As a result, Stryker recommends that you replace the Product(s). If the Product(s) involved in this ambulance accident are put back into service, Stryker will consider the product as being subject to unusual stress and improperly maintained. Products which are subject to unusual stress and improper maintenance are not subject to Stryker's Standard Limited Warranty. In addition, Stryker will not indemnify any customer for any third-party claims related to injuries caused by products that have been involved in accidents.

If you have any questions, please, contact me.

Sincerely,

Brian Thompson
Stryker Medical
Regulatory Affairs

Stryker Medical

3800 E. Centre Ave, Portage, MI. 49002 USA | P +1 269 389 2100 | F +1 269 389 2213 | stryker.com

*For additional information regarding Stryker's ambulance accident policy and inspections offered please refer to Stryker's "Ambulance Accident Policy Explained" memo (Mkt Lit - 1414).

Mkt Lit-1007 12 SEP 2014 Rev B.4



MEMO

To: Whom It May Concern

Re: **Ambulance Accident Policy Explained**

The purpose of this memo is to detail Stryker's post ambulance accident policy.

The Manual on Classification of Motor Vehicle Traffic Accident, provided by American National Standard ANSI D16.1-2007 indicates that an accident is "an unstabilized situation which includes at least one harmful event" where harmful event is "an occurrence of injury or damage". For the purposes of ambulance accident investigation, Stryker Medical's definition of damage excludes superficial damage (scratches, dents, cracked or broken plastic parts) to bumpers, fenders, lights, mirrors, and other non-structural ambulance components. If you experience an ambulance accident where only superficial vehicle damage occurs (as defined above) you can continue to use the product and do not need to report the accident to Stryker.

Following an accident, Stryker can evaluate Product(s) in order to recommend their continued use¹. This requires the customer to complete Stryker's Ambulance Accident Attestation Form. This form can be obtained by contacting your local Stryker sales representative or by emailing ambulanceaccidents@stryker.com.

A member of Stryker's Service Team can perform two types of post-ambulance accident inspections:

A basic post-ambulance accident inspection can be performed if the following criteria is met:

- The ambulance accident has <5g deceleration or maximum combined speed of 8mph
- There is no patient on the Product(s)
- There was no damage done to structural components of the Product(s)

If the above criteria is exceeded the customer can request an expanded post-ambulance accident inspection, when the following conditions are met²:

- The vehicle must not have been involved in a roll-over accident
- The vehicle must not have been totaled in the accident
- The ambulance cot remained in the fastener during the accident
- Product restraints were attached to the cot as described in the appropriate Stryker Operations Manual

Following the post-ambulance accident inspection and Product(s) evaluation, Stryker will recommend if the Product(s) can continue to be used. This is contingent on the Product(s) passing the inspection, recommended repairs be completed, and the Product(s) meeting the specifications outlined in the Product's Operations and Maintenance Manuals.

Sincerely,

Brian Thompson
Stryker Medical
Regulatory Affairs

Stryker Medical

3800 E. Centre Ave, Portage, MI. 49002 USA | P +1 269 389 2100 | F +1 269 389 2213 | stryker.com

¹Product(s) must be within their expected service life and Product(s) involved cannot include Power-PRO IT cots.

²Product(s) involved must be Power-PRO XT used with Power-LOAD or Performance-LOAD.