## WILLIAMSON COUNTY, TEXAS

CHANGE ORDER NUMBER: 14

1. CONTRACTOR: James Construction Group	ASI	Project: 22IFB139
2. Change Order Work Limits: Sta. 481+00 to	Sta. 492+00	Roadway: FM 3349
3. Type of Change(on federal-aid non-exempt projects):	<u>Minor</u> (Major/Minor)	CSJ Number: Williamson Co
4 Reasons: 2 C (3 Max In order	of importance - Primary first)	
5 Describe the work being revised: 2C. New Development ( Conditions Changing After PS&E Co Contractor for relocating box culvert No. 4 on the southbound fro Hutto street (Spine Road). The culvert and crossover to FM 3349 centerline of the Spine Road.	ontage road, to accommodate the	e location of the new City of
	e Attached	
7. New or revised plan sheet(s) are attached and numbered	d: <u>31, 35C, 164,165, 1</u>	197, 213, 230, 241A, 354, 642
8. New Special Provisions/Specifications to the contract are	e attached:	✓ No
9. New Special Provisions to Item_N/A_No. No. N/A_, Speci	al Specification Item N/A	are attached.
Each signatory hereby warrants that each has the authority	to execute this Change Order	· (CO).
The contractor must sign the Change Order and, by doing so, agrees to waive any and all claims for additional compensation due to any and all other expenses; additional changes for time, overhead and profit; or loss of compensation as a result of this change.	The following information Time Ext. #:	tion must be provided  Days added on this CO:
THE CONTRACTOR Date 4-3-2024  By Williams  Typed/Printed Name Wey Williams		ge order: <u>\$101,248.22</u>
Typed/Printed Name  Typed/Printed Title  DIVISION Mana  RECOMMENDED FOR EXECUTION:	gev	
	County Commissio	ner Precinct 1 Date
Project Manager Date	☐ APPROVED	☐ REQUEST APPROVAL
	County Commissio	ner Precinct 2 Date
N/A Design Engineer Date	☐ APPROVED	REQUEST APPROVAL
Christen Eichberger 4/10/2024 Program Manager Date	County Commissio  APPROVED	ner Precinct 3 Date  REQUEST APPROVAL
Design Engineer's Seal:	00004:000001:1	and Descripted A
	County Commissio  APPROVED	ner Precinct 4 Date  REQUEST APPROVAL
	County Ju	udge Date

## WILLIAMSON COUNTY, TEXAS

## CHANGE ORDER NUMBER: 14

Project #	22IFB139	

TABLE A: Force Account Work and Materials Placed into Stock

 LABOR	HOURLY RATE	HOURLY RAT
	<del> </del>	
		·

#### TABLE B: Contract Items:

			19,78	ORIGINAL + PRE	VIOUSLY REVISED	ADD or (DEDUCT)	52.5	NEW	
ITEM	DESCRIPTION	UNIT	UNIT PRICE	QUANTITY	ITEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUN/ UNDERRUN
464 6018	RC PIPE (CL IV) (24 IN) - 008	LF	\$ 116.59	484.00	\$ 56,429.56	120.00	604.00	\$ 70,420.36	
530 6004	DRIVEWAYS (CONC) 008	SY	\$ 123.29	3,177.00	\$ 391,692,33	397.50	3,574.50		
618 6023	CONDT (PVC) (SCH 40) (2") - 008	LF	\$ 11.00	21,721.00	\$ 238,931.00	(30.00)	21,691.00		
620 6007	ELEC CONDR (NO.8) BARE - 008	LF	\$ 1.75	16,664.00	\$ 29,162.00	(30.00)	16,634.00		
620 6008	ELEC CONDR (NO.8) INSULATED - 008	LF	\$ 2.25	33,328.00	\$ 74,988.00	(60.00)	33,268.00		
462 6012.1	REMOVE AND RE-LAY CONC BOX CULV (5FTX6FT) - 008	LF	\$ 376.38	0.00		103.00	103.00		
							7047-1		
244176146								N: 42	2750
					***			1	
							1		
							200	Sec.	
						A 1		1000	
111000000							- Jan-02		
	250						34	1410	
				31743	- Silva:			UI I	
	1 22 2						125		
		+							
		_							
	TOTAL	.s			\$ 791,202.89			\$ 892,451.11	\$ 101,24

# CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E
	1B. Other
2 Differing Site Conditions	2A Dispute resolution (expense sound by and the second by
Differing Site Conditions	2A. Dispute resolution (expense caused by conditions and/or resulting delay)
(unforeseeable)	2B. Unavailable material
	2C. New development (conditions changing after PS&E completed)
	2D. Environmental remediation
	2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9)
	2F. Site conditions altered by an act of nature
	2G. Unadjusted utility (unforeseeable)
	2H. Unacquired Right-of-Way (unforeseeable)
	2I. Additional safety needs (unforeseeable)
	2J. Other
2 Causti Canuaniana	2A District marketing (and markling from a series of the control o
County Convenience	Dispute resolution (not resulting from error in plans or differing site conditions)
	3B. Public relations improvement
	3C. Implementation of a Value Engineering finding
	3D. Achievement of an early project completion
	3E. Reduction of future maintenance
	3F. Additional work desired by the County
	3G. Compliance requirements of new laws and/or policies
	3H. Cost savings opportunity discovered during construction
	3). Implementation of improved technology or better process
	3J. Price adjustment on finished work (price reduced in exchange for acceptance)
	3K. Addition of stock account or material supplied by state provision
	3L. Revising safety work/measures desired by the County
	3M. Other
4 Third Doch, Assessed 2'	AA Failure of a Abird and the month of a month of a state of the state
Third Party Accommodation	4A. Failure of a third party to meet commitment
	4B. Third party requested work
	4C. Compliance requirements of new laws and/or policies (impacting third party)
	4D. Other
E Contractor Convenience	EA Contractor avarages autients the testing to
5. Contractor Convenience	5A. Contractor exercises option to change the traffic control plan
	5B. Contractor requested change in the sequence and/or method of work
	5C. Payment for Partnering workshop
	5D. Additional safety work/measures desired by the contractor
	5E. Other
6 Untimely POW// Hilitian	6A Dight of Way not clear (third nath, respectibility for COVA)
6. Untimely ROW/Utilities	6A. Right-of-Way not clear (third party responsibility for ROW)
	6B. Right-of-Way not clear (County responsibility for ROW)
	6C. Utilities not clear
	6D. Other

### **Williamson County Road Bond Program**

# FM3349 at US 79 Williamson County Project No. 22IFB139

## Change Order No. 14

## **Reason for Change**

This Change Order provides compensation to the Contractor for relocating Box Culvert No. 4 on the southbound frontage road, to accommodate the location of the new City of Hutto street (Spine Road). The culvert and the crossover to FM3349 were moved approximately 36 feet to the north to align with the centerline of the Spine Road.

Following is summary of new items required for this Change Order.

ITEM	DESCRIPTION	QTY	UNIT
462 6012.1	REMOVE AND RE-LAY CONC BOX CULV (5FTX6FT)	103	LF

This Change Order results in a net increase of \$101,248.22 to the Contract amount, for an adjusted Contract total of \$84,003,793.32. The original Contract amount was \$81,941,038.13. As a result of this and all Change Orders to-date, \$2,062,755.19 has been added to the Contract, resulting in an 2.52% net increase in the Contract cost. No additional days will be added to or deducted from the Contract as a result of this Change Order.

### **HNTB Corporation**

Oscar Salazar-Bueno, P.E.

						SUMMARY OF	ILLUMINATION QU	ANTITIES						
		0416 6029	0432 6001	0610 6106	0610 6200	0610 6216	0618 6023	0618 6064	0620 6005	0620 6006	0628 6007	0620 6008	0624 6002	0628 604
LAN SHEET NO.	STATION TO STATION	DRICE SHAFT (ROWY LLL POLE) (30 IW)	RIPRAP (CONC) (6 [H)	EN MD EL (U/P) 17Y 23 1150W EQ3 LED	EN RO (L (TY SA) 405-10 (250W EQ) LEO	EM RO (% (TY SA) 401-10 (250% £Q) LEO	CONOT (PVC) (SCH 40) (2*)	COHOT IRMS (I*)	ELEC COMOR (NO. 10) BARE	ELEC COMDR (MO.10) INSULATED	ELEC CONDR 100, 8) BARE	ELEC CONOR INO. 8) (MSULATED	GROUND BOX TY A (122311) WAPRON	ELC SRY TY 240/480 060 (NS) SS (T):
	!	LF.	£4	ξA	EA	ĒA	LF	(IE)	LF	Lf	LFS	LF	£A	EA
[ULUM] N	ATION SHEETS				Ĺ			-						
698	BEGIN TO 426+00	32	1,68			4	844				874	1748	ı	
699	426+00 10 437+00	24	1.61			3	1281				1316	2612	2	
700	437+00 TO 448+00	32	1.96			5.5	~~1544~~	$\triangle$			-00-1578-000	~~~	2	1
701	481+00 TO 492+00	16	1,26	Δ.			1045				1065	2130	2	$\Lambda$
702	492+00 TO 503+00	48	2. 66			6 /2	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~			2	THE STATE OF THE S	2656	J	1.
703	503+00 TO \$14+00	0	0.91		7	.21	566a		2277	4554	3526	7052	2	
704	514+00 TO 525+00				37		3007		1316	2632	1841	3682		
705	525+00 TO 536+00	0	0.91			2d	4180		\$119	4238	2191	4382	S	1
106	536-00 TO 547-00	64	3. 64				2370				2445	4890	4	- 1
707	\$47+00 TO 558+00	32	2, 24			4	1339				1379	2758	3	1
708	558+00 TO END	24	1,05			2	461				476	952		
109	UNDERPASS			0	4			518	578	1156				
710	UNDERP455			0	<u> </u>	[.		475	535	1970				1
										- 150	~~~~	~~~~~		
ILLUMIN.	ZJATOT MOJILS	280	17,92	16	27	36	23506	993	6825	13650	18504	37008	V1\ ≥1	4



FM 3349

#### SUMMARY OF QUANTITIES

SHEET 13 OF 1

			SHEEL	3 01 17			
GRM	614.40.	FE069	LEDENNY VLD WOONECL HO!				
DEPARTE?	6			FM 3349			
GRM	51610	DISTRICT	EDUNTY	SHEET NG.			
PKD	TEXAS	AUS	WILLTAMSON				
CHECK	CONTROL	5ECT204	J08	31			
PKD	3486	01	008, ETC				

TYN	OESCRIPTION	CO WE SELTA	MEASURE
462 ****	REMOVE AND RE-LAY CONC BOX CULV (6FTX5FT)	103.00	LF
464 6018	RC PIPE (CL IV) (24 IN)	120 168.99	LF
497-0500	SET HEMOV & RESISTABLE	7.90	
530 6005	DRIVEWAYS (ACP)	397.50	SY
618 6023	CONDT (PVC) (SCH 40) (2")	(30,00)	LF
620 6007	ELEC CONDR (NO. 8) BARE	(30.00)	LF
620 6008	ELEC CONDR (NO. 8) INSULATED	(80.00)	LF

Texas Department of Transportation


FM 3349


# SUMMARY OF QUANTITIES CHANGE ORDER #5


SHEET 1 OF 1


GESTON ET	DIV. NO.	resea	PERENAL ATO PROJECT NO.			
ENDHIC2	6			FM 3349		
LG	11412	03548361	COUNTY	SMEET IOU.		
CHECK	TEXAS	AUS	WILL!AMSON			
CMC I	J0911003	stellow	101	35C		
	3486	01	008, ETC	]		


SHEET 35C














Kyle Oktham

And Personals, Gary Couch: Joshue Hardenood: Delmar Russino 61277\_PH336566575 Open Salatar Benny, Steven Shull: Devel Thomast. Trevor Date: Bran Chaffe RE: FM3349: COH Megastre Spine Road - Revised Criveway Plans Monday, March 11, 2024 415:29 PM

mage007.10g mage010.png mage011.pgc mage012.png mage013.png

#### External Email, Use caution when clicking on links, replying, or opening attachments.

#### Asif-

With HNTB's verbal direction earlier today, we will proceed with OPTION B stated below at 96' LF total relocated. PSC crews began this morning on the work. Please confirm,

12 ea 6' middle boxes= 72' 4 ea 6' end boxes= 16' =96' x \$376.38 = \$36,132.48

Please proceed with Change Order so we can potentially get on this month's estimate.

Thanks

-Kyle

From: Kyle Oldham

Sent: Tuesday, March 5, 2024 12:07 PM

To: Asif Mirzazada <amirzazada@hntb.com>; Gary Couch <gcouch@prim.com>; Joshua Hazlewood <jhazlewood@prim.com>; Dal mar Rosario <drosario@prim.com> Cc: 61272\_FM3349AtUS79 <61272\_FM3349AtUS79@HNTB.com>, Oscar Salazar Bueno <osalazarbueno@HNTB.com>; Steven Shull <sshull@HNTB.com>, David Thornhill <dthornhill@HNTB.com>; Trevor Dare <tdare@HNTB.com>; Brian Chaffe <bchaffe@prim.com>

Subject: RE: FM3349: COH Megasite Spine Road - Revised Driveway Plans

Importance: High

Asif-

#### OPTION A

New 6x5 RCB install \$760/LF (same as CO#7 price) \$760x96' = \$72,960 total 6 week lead time on boxes

#### **OPTION B**

Relocate existing boxes (estimated 112 LF (96' straight boxes & 16' end pcs))

\$376.38/LF

\$376.38x112' = \$42.154.97 total

Crews can begin this upon completion of Culvert 3 (3-4 days)

Please advise.

Thanks

Kyle Oldham Project Manager 12365 US 79 S. Taylor, TX 76574 O: (254) 939-8610 C: (254) 444 0974

www.prim.com

PSC\_Email\_2016



"No business objective is so important that it will be pursued at the sacrifice of safety."

From: Asif Mirzazada <amirzazada@hntb.com>

Sent: Saturday, February 24, 2024 10:37 AM

To: Kyle Oldham < koldham@orim.com>; Gary Couch < ecouch@orim.com>

Cc: 61272\_FM3349AtUS79 <61272\_fM3349AtUS79@HNTB.com>; Oscar Salazar-Bueno <osalazar-Bueno@HNTB.com>; Steven Shull <sshull@HNTB.com>; Oavid Thornhill <dthcrnhill@HNTB.com>; Trevor Dare <tdare@HNTB.com>

Subject: RE: FM3349: COH Megasite Spine Road - Revised Driveway Plans

CAUTION: This email originated from outside the organization. Do not click links or open attachments unless you have verified the sender and know the content is safe! If this message is suspicious, please use the Report Phish button to notify IT.

#### Kyle

We've considered this eption, but on-site evaluation determined that it's best not to disturb the south end since it's already grouted. Although this option seems quick and cost-effective, I'll check with the EOR to get his recommendation if you believe we should proceed in this direction. Excavating on the sides and remove the flowable fall so that the boxes can be pulled off and moved to the north end of the line would not be too challenging I believe.

Thank you,

Asif Mirzazada

Sr. Field Engineer Williamson County Road Bond Program

Mobile (512) 987-9179 Email programada@hotb.com

From: Kyle Oldham < koldham@orim.com>

Sent: Friday, February 23, 2024 5:04 PM

To: Asif Mirzazada <amirzazada@hntb.com>; Gary Couch <acouch@prim.com>

Cc: 61272\_FM3349AtUS79 <61272\_FM3349AtUS79@HNTB.com>; Oscar Salazar-Bueno <osalazar-Bueno @HNTB.com>; Steven Shull <sshull@HNTB.com>; David Thornhill <dthornhill@HNTB.com>; Trevor Dare <tdare@HNTB.com>

Subject: RE: FM3349; COH Megasite Spine Road - Revised Driveway Plans

External Email: Use caution when clicking on links, replying, or opening attachments.

Simple illustration....

From: Kyle Oldham

Sent: Friday, February 23, 2024 5:01 PM

To: Asif Mirzazada <amirzazada@hnth.com>; Gary Couch <a href="couch@prim.com">com</a>

Cc: 61272\_FM3349AtUS79 <61272\_FM3349AtUS79@HNTB.com>, Oscar Salazar-Bueno <osalazar-Bueno@HNTB.com>; Steven Shull <osshull@HNTB.com>; David Thornhill <dthornhill@HNTB.com>; Trevor Dare <tdare@HNTB.com>

Subject: RE: FM3349: COH Megasite Spine Road - Revised Driveway Plans

Asif-

Is HNBT appared to the idea of removing the south end boxes by the needed 35' and relocating them to the north end? Reusing the end pieces on both sides. Essentially eliminating the need to purchase new boxes... perhaps

I have not put any calls to paper on if it would work with the spacing yet, just thinking out loud to see if it is an option. I have spoke to Perry, the foreman installing it, and he said it can be done.

Something to think about and let me know your thoughts.

From: Asif Mirzazada <amirzazada@hntb.com>

Sent: Friday, February 23, 2024 2:17 PM

To: Kyle Oldham <a href="mailto:kolcham@prim.com">kolcham@prim.com</a>; Gary Couch <a href="mailto:kolcham@prim.com">gcouch@prim.com</a>>

Cc: 61272\_FM3349AtUS79 <61272\_FM3349AtUS79@HNTB.com>; Oscar Salazar Bueno <osalazar Bueno <osalazar Bueno <salazar Bueno Steven Shull Steven Sh

Subject: FM3349: COH Megasite Spine Road - Revised Driveway Plans

**CAUTION:** This email originated from outside the organization. Do not click links or open attachments unless you have verified the sender and know the content is safel If this message is suspicious, please use the **Report Phish** button to notify IT.

Kvle.

Attached is the preliminary plans for the revised COH spine road driveway. We have estimated installing two runs of 48 feet, totaling 96 linear feet (12 segments of 8-

footers). The plans contain sufficient information for box ordering. Please review and let us know if you have any questions. I am expecting to get the final plans early next week.

Thank you,

#### Asif Mirzagada

Sr. Field Engineer

Williamson County Road Bond Program
Mobile (512) 987-9179 Email amazarda Control

101 E. Old Settlers Blvd. Ste. 225 | Round Rock, TX 78664 | https://doi.org/

#### 100+ YEARS OF INFRASTRUCTURE SOLUTIONS

Twitter | Linkedin | Facebook | Instagram

This e-mail and any files transmitted with it are confidential and are intended solely for the use of the individual or entity to whom they are addressed. If you are NOT the intended recipient and receive this communication, please delete this message and any attachments. Thank you.

Note: This email originated from outside our organization. Be cautious when opening Links and Attachments that you were not expecting.

This e-mail and any files transmitted with it are confidential and are intended solely for the use of the individual or entity to whom they are addressed. If you are NOT the intended recipient and receive this communication, please delete this message and any attachments. Thank you.

Note!: This email originated from outside our organization. Be cautious when opening Links and Attachments that you were not expecting.