



Vegetative Management

Roadside Landscape Specifications

Road Bond Program Projects

June 9, 2009



PRIME
STRATEGIES,
INC.

HNTB

June 9, 2009



History

- Review bond program practices/procedures
- Review bond program specifications
- Utilize County Resources

One Size Does Not Fit All



PRIME
STRATEGIES,
INC.

HNTB

June 9, 2009



Another Problem Occurred



PRIME
STRATEGIES,
INC.

HNTB

June 9, 2009



PRIME
STRATEGIES,
INC.

HNTB

June 9, 2009



PRIME
STRATEGIC,
INC.

HNTB

June 9, 2009



PRIME
STRATEGIC,
INC.

HNTB

June 9, 2009



PRIME
STRATEGIES,
INC.

HNTB

June 9, 2009



PRIME
STRATEGIES,
INC.

HNTB

June 9, 2009



The Problem

- Drainage Design
 - Soil Retention Blanket Failure
 - Un-reinforced vegetation
- Engineering Solutions
 - Work with County Engineer & AECOM (TC&B)
 - Produce plan sheets & correct erosion control plan and install higher level of controls
 - Plan Sheets – no cost to the County



The Problem

- Specification
 - TxDOT Grass Mix
 - Standard for All projects
- Installation
 - Timing
 - Contractor interpretation of specification
- Inspection
 - Lack of supervision



PRINCIPAL
STRATEGIES,
INC.

HNTB

June 9, 2009



Next Steps

- Develop a new specification for Road Bond Projects
 - Recognize 4 diverse eco-regions in Williamson County
- Develop recommendations for Reagan Blvd. restoration
- Preparing a proposal for Commissioners Court Review/Approval



PRINCIPAL
STRATEGIES,
INC.

HNTB

June 9, 2009