		FY 09 Year End Projects		
Priority	Biulding	Item	Justification	<b>Estimated Cost</b>
			The sewer line in the detention area was found	
2	Juv Justce Cntr	Repair sewer line	to be broken between two ceils	\$5,850
			The mechanical dampers allow the wind to	
			blow back down the ductwork putting hot or	
			cold air into the internal areas. This makes it	
			difficult to maintane temperature which in turn	
			increases energy consumption \$700 Design,	
1	Jail North	Replace mechanical fire damper with motorinzed dampers	\$12,680 Dampers	\$19,680
			Fixtures are worn out. The primary causes are	
			the hard water and repeated rebuiding of	24 ea @ \$1300
3	Jail South	Replace hot/cold water mixing valves valve	valves.	Total \$31,000
			The concept of the use of this room has	
			changed. It was primarily going to be a phone	
			room with minimal servers. Do to the increase	
	Juv Justice		in the amount of equipment the HVAC system	
4	Center	Replace HVAC with larger unit	can no long maintain the proper temperature.	\$12,309
		·	One wing has already been converted. It was	. ,
			more cost effective than replacing the units	
	Central Texas		that were no longer repairable. It also reduced	\$19,335 per
	Treatment	Replace individual through the wall units in the clients rooms	the main hours it takes to maintain the	wing. Total
5	Center	with a centralized HVAC system.	indivdual system	\$58,000
			It allows us to monitor and control the	
	Central Texas		temperature through out the ficitliy. They have	
	Treatment		their policy on the temperature setting that	
6	Center	Automated Logic Controls	they want to maintian.	\$30,000 est.
			Roof is a rubber type roof, 15 yrs old and at the	
7	Innerloop annex	Replace roof over Probation	end of it life (leaking) with numerous repairs	\$62,000
<u> </u>				