narroived

JUL 19 2011

JUL 18 2011

## HNTB Corporation Rowletchamson County, TEXAS CHANGE ORDER NUMBER: 4

Hit 15 Corporation Round Rock

ING ROCK	
1. CONTRACTOR: Chasco Constructors	Project: 10WC812
2. Change Order Work Limits: Sta. <u>52+50</u> to	Sta. 72+50 Roadway: CR 104 Phase II
Type of Change(on federal-aid non-exempt projects):	Minor (Major/Minor) CSJ Number: 0914-05-141
Reasons: 4B, 3E (3 Max In order of	of importance - Primary first)
eanks of Mankins Branch. 3E: County Convenience. Reduction Schroeder property, and use of 18" stone riprap in lieu of 12" store	
<ol> <li>Work to be performed in accordance with Items: Se</li> <li>New or revised plan sheet(s) are attached and numbered</li> </ol>	e attached. d: 53C
New Special Provisions to the contract are attached:	Yes No
9. New Special Provisions to Item N/A No. N/A, Special	
Each signatory hereby warrants that each has the authority	
The contractor must sign the Change Order and, by doing so, agrees to waive any and all claims for additional compensation due to any and all other	The following information must be provided
iny and an claims for additional compensation due to any and an other expenses; additional changes for time *, overhead and profit; or loss of compensation as a result of this change.	Time Ext. #: N/A Days added on this CO: 0
THE CONTRACTOR Date 7-14-11	Amount added by this change order: \$17,706.17
By Mroff	
Typed/Printed Name BILLBAMBRICK	
Typed/Printed Title PROSTSCT MGR	
Project Manager Construction Observer	County Commissioner Precinct 1 Dat  APPROVED REQUEST APPROVAL
Design Familians	County Commissioner Precinct 2 Dat APPROVED REQUEST APPROVAL
Design Engineer Date	
7/18/2011 Program Manager Date	County Commissioner Precinct 3 Dat  APPROVED  REQUEST APPROVAL
Design Engineer's Seal:	
See Revised Sheets	County Commissioner Precinct 4 Dat  APPROVED REQUEST APPROVAL
4	67-27-11
	County Judge Dat

# WILLIAMSON COUNTY, TEXAS

CHANGE ORDER NUMBER: 4

Project # 10WC812

TABLE A: Force Account Work and Materials Placed into Stock

HOURLY RATE					
HOURLY RATE				,	
LABOR					

BLE B: Contract Items

				ORIGINAL	ORIGINAL + PREVIOUSLY REVISED	ADD or (DEDUCT)	_	NEW	
ITEM	DESCRIPTION	UNIT	UNIT PRICE	QUANTITY	ITEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUN/ UNDERRUN
132-2003	EMBANKMENT (FINAL)(ORD COMP)(TY B)	ζ	\$6.50	7,442.00	\$48,373.00	20.00	7,492.00	\$48,698.00	\$325.00
169-2002	SOIL RETENTION BLANKETS (CL 1) (TY B)	λs	\$1.65	00.0	\$0.00	1,299.00	1,299.00	\$2,143.35	\$2,143.35
169-2008	SOIL RETENTION BLANKETS (CL 2) (TY H)	λS	\$14.83	0.00	\$0.00	674.00	674,00	\$9,995.42	\$9,995,42
432-2033	RIPRAP (STONE COMMON) (DRY) (12 IN)	ζ	\$9.70	698.00	\$6,770.60	(00.869)	00'0	\$0.00	(\$6,770.60)
432-2041	RIPRAP (STONE COMMON) (DRY) (18 IN)	ბ	\$11.70	00.00	\$0.00	90'69'	769.06	\$8,998.00	\$8,998.00
460-2004	CMP (GAL STL 24 IN)	占	\$38.00	36.00	\$1,368.00	92:00	91.00	\$3,458.00	\$2,090.00
467-2465	SET (TY II) (24 IN) (CMP) (3:1) (P)	4	\$625.00	0.00	\$0.00	1.00	1.00	\$625.00	\$625.00
9104-2001	REMOVING CONC (SET)	EA	\$300.00	0.00	\$0.00	1.00	1.00	\$300.00	\$300.00
					3.00				
					113				
		TOTALS			556 511 60			574 217 77	\$17,706.17

# CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E
	1B. Other
Differing Site Conditions	2A. Dispute resolution (expense caused by conditions and/or resulting delay)
(unforeseeable)	2B. Unavailable material
	2C. New development (conditions changing after PS&E completed)
	2D. Environmental remediation
	2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9)
	2F. Site conditions altered by an act of nature
	2G. Unadjusted utility (unforeseeable)
	2H. Unacquired Right-of-Way (unforeseeable)
	2I. Additional safety needs (unforeseeable)
	2J. Other
3. County Convenience	3A. Dispute resolution (not resulting from error in plans or differing site conditions)
	3B. Public relations improvement
	3C. Implementation of a Value Engineering finding
	3D. Achievement of an early project completion
	3E. Reduction of future maintenance
	3F. Additional work desired by the County
	3G. Compliance requirements of new laws and/or policies
	3H. Cost savings opportunity discovered during construction
	Implementation of improved technology or better process
	,
	3K. Addition of stock account or material supplied by state provision
	3L. Revising safety work/measures desired by the County
	3M. Other
4. Third Party Accommodation	4A. Fallure of a third party to meet commitment
	4B. Third party requested work
	4C. Compliance requirements of new laws and/or policies (impacting third party)
	4D. Other
5. Contractor Convenience	5A. Contractor exercises option to change the traffic control plan
	5B. Contractor requested change in the sequence and/or method of work
	5C. Payment for Partnering workshop
	5D. Additional safety work/measures desired by the contractor
	5E. Other
6. Untimely ROW/Utilities	6A. Right-of-Way not clear (third party responsibility for ROW)
	6B. Right-of-Way not clear (County responsibility for ROW)
	6C. Utilities not clear
	6D. Other

### Williamson County Road Bond Project

### CR 104 – Phase II Williamson County Project No. 10WC812

### Change Order No. 4

### Reason for Change

This Change Order provides payment to the contractor for additional work requested by the County and TxDOT to minimize future maintenance. The additional work includes TxDOT requested soil retention blankets installed at the Mankins Branch Bridge in order to protect the slopes from erosion, redesign of the ditch in front of the Schroeder property, and use of 18" stone riprap in lieu of 12" stone riprap to create more stable slopes along the creeks.

The back slope of the ditch in front of the Schroeder property was steep and proved difficult to maintain. At the request of the adjacent property owner, this ditch was redesigned to lower future maintenance costs and provide a more aesthetically pleasing appearance, requiring extension of a driveway culvert, removal of an existing SET, and installation of a new SET.

Following is a description of the new items required for this Change Order.

ITEM	DESCRIPTION	QTY	UNIT
169-2002	SOIL RETENTION BLANKETS (CL 1)(TY B)	1,299.00	SY
169-2008	SOIL RETENTION BLANKETS (CL 2)(TY H)	674.00	SY
432-2041	RIPRAP (STONE COMMON) (DRY) (18 IN)	769.06	CY
467-2465	SET (TY II) (24 IN) (CMP) (3:1) (P)	1.0	EA
9104-2001	REMOVING CONC (SET)	1.0	EA

This Change Order results in a net increase of \$17.706.17 to the Contract amount, for an adjusted Contract total contract amount of \$2,277,214.12. The original Contract amount was \$2,247,002.60. As a result of this and all Change Orders to date, \$30,211.52 has been added to the Contract, resulting in a 1.34% net increase in the Contract Cost. No additional days will be added to or deducted from the Contract as a result of this Change Order.

Huitt~Zollars, Inc.

Kenneth L. 'Zeke' Zieschang, P.E.