

WILLIAMSON COUNTY, TEXAS CHANGE ORDER NUMBER: 3

1. CONTRACTOR: DNT Construction Project: 10WC823 2. Change Order Work Limits: 40+50 Roadway: Sta. to Sta. Hero Way 3. Type of Change(on federal-aid non-exempt projects): Minor (Major/Minor) Purchase Order Number: (3 Max. - In order of importance - Primary first) Reasons: 1A, 5E 5. Describe the work being revised: 1A: Design Error or Omission. Incorrect PS&E. This Change Order corrects the contract quantity of rip rap to match the designed quantity on the plans and summary sheet. 3H: County Convenience. Cost savings opportunity discovered during construction. The standard for curb inlets was changed from the specified TxDOT San Antonio District Standards to the TxDOT Austin District Standards. The City of Leander concurs with the change in inlet standards. 6. Work to be performed in accordance with Items: See Attached. 7. New or revised plan sheet(s) are attached and numbered: 8. New Special Provisions to the contract are attached: Yes [] No 9. New Special Provisions to Item N/A No. N/A , Special Specification Item N/A Each signatory hereby warrants that each has the authority to execute this Change Order (CO). The following information must be provided The contractor must sign the Change Order and, by doing so, agrees to waive any and all claims for additional compensation due to eny and all other expenses; additional changes for time, overhead and profit; or loss of Time Ext. #: Days added on this CO: 0 ompensation as a result of this change. \$16,661.05 Amount added by this change order: 7/26/11 THE CONTRACT Typed/Printed Name Typed/Printed Title RECOMMENDED FOR EXECUTION: County Commissioner Precinct 1 Date ☐ APPROVED ☐ REQUEST APPROVAL Project Manager Construction Observer County Commissioner Precinct 2 Dale ☐ APPROVED ☐ REQUEST APPROVAL N/A Date Design Engineer County Commissioner Precinct 3 Date ☐ APPROVED □ REQUEST APPROVAL Program Manager Design Engineer's Seal: County Commissioner Precinct 4 Date ☐ APPROVED ☐ REQUEST APPROVAL See Revised Plan Sheet County Judge APPROVED

WILLIAMSON COUNTY, TEXAS

CHANGE ORDER NUMBER: 3

Project # 10WC823

TABLE A: Force Account Work and Materials Placed into Stock

LABOR	HOURLY RATE	ОН	HOURLY RATE

TABLE B: Contract Items

				ORIGINAL	ORIGINAL + PREVIOUSLY REVISED	ADD or (DEDUCT)	Ž	NEW	
ITEM	DESCRIPTION	TIND	UNIT PRICE	ООМИТТ	TTEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUN
450-2066	RIPRAP (CONC) (CLB)	չ	\$245.00	44.00	\$10,780.00	128.00	128.00	\$31,360.00	\$31,360.00
465-2020	INLET (COMPL) (CURB) (TY II)	Ą	\$5,252.00	20.00	\$105,040.00		0.00	\$0.00	(\$105,040.00)
465-2020	(INLET (COMPL.) (CURB) (TY II)	Ą	\$4,620.53	00'0	00.0\$	20.00	20.00	\$92,410.60	\$92,410.60
465-2195	INLET (COMPL) (CURB) (TY ()	Ą	\$4,700.00	2.00	'6\$		0.00	\$0.00	(\$9,400.00)
465-2195	(INLET (COMPL) (CURB) (TY I)	2	\$4,569.85	0.00	\$0.00		2.00	\$9,139.70	\$9,139.70
XXXXXX	INLET (COMPL) (CURB) (TY II) (SPL)	2	\$4,500.00	5.00	\$22.	(2.00)	0.00	\$0.00	(\$22,500.00)
465-XXXX	INLET (COMPL) (CURB) (TY II) (SPL)	EA	\$4,138.15	0.00	\$0.00	5.00	2.00	\$20,690.75	\$20,690.75
		_							
	TOTALS				\$147,720.00			\$153,601.05	\$16,661.05

CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E
 	1B. Other
Differing Site Conditions	2A. Dispute resolution (expense caused by conditions and/or resulting delay)
(unforeseeable)	2B. Unavailable material
	2C. New development (conditions changing after PS&E completed)
	2D. Environmental remediation
	2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9)
	2F. Site conditions altered by an act of nature
	2G. Unadjusted utility (unforeseeable)
	2H. Unacquired Right-of-Way (unforeseeable)
	2l. Additional safety needs (unforeseeable)
	2J. Other
3. County Convenience	3A. Dispute resolution (not resulting from error in plans or differing site conditions)
	3B. Public relations Improvement
	3C. Implementation of a Value Engineering finding
	3D. Achievement of an early project completion
	3E. Reduction of future maintenance
	3F. Additional work desired by the County
	3G. Compliance requirements of new laws and/or policies
	3H. Cost savings opportunity discovered during construction
	3I. Implementation of improved technology or better process
	Price adjustment on finished work (price reduced in exchange for acceptance)
	3K. Addition of stock account or material supplied by state provision
	3L. Revising safety work/measures desired by the County
	3M. Other
	JW. Oute
4. Third Party Accommodation	4A. Failure of a third party to meet commitment
	4B. Third party requested work
	4C. Compliance requirements of new laws and/or policies (impacting third party)
	4D. Other
5. Contractor Convenience	5A. Contractor exercises option to change the traffic control plan
	5B. Contractor requested change in the sequence and/or method of work
	5C. Payment for Partnering workshop
	5D. Additional safety work/measures desired by the contractor
	5E. Other
·	
6. Untimely ROW/Utilities	6A. Right-of-Way not clear (third party responsibility for ROW)
	6B. Right-of-Way not clear (County responsibility for ROW)
	6C. Utilities not clear
	6D. Other
	IOD. Other

Williamson County Road Bond Program

Hero Way Williamson County Project No. 10WC823

Change Order No. 3

Reason for Change

This Change Order corrects the contract quantity of rip rap to match the designed quantity on the plans and summary sheet. This error was acknowledged and verified by the Engineer.

A cost savings opportunity for Williamson County was identified due to a change in the TxDOT standards for curb inlets from the San Antonio District Standards to the Austin District Standards. After reviewing the proposal from the contractor and with concurrence from the City of Leander, it was decided that the Austin District Standards will be used, which are the same standards used on the typical Williamson County Road Bond project. This Change Order will provide new contract prices for the curb inlets.

Following is a summary of the new items required for this change order.

ITEM	DESCRIPTION	QTY	UNIT
465-2020	INLET (COMPL) (CURB) (TY II)	20.0	EA
465-2195	INLET (COMPL) (CURB) (TY I)	2.0	EA
465-XXXX	INLET (COMPL) (CURB) (TY II) (SPL)	5.0	EA

This Change Order results in a net increase of \$16,661.05 to the Contract amount, for an adjusted Contract amount of \$4,164,831.31. The original Contract amount was \$4,232,522.80. As a result of this and all Change Orders to date, \$67,691.49 has been deducted from the Contract, resulting in a 1.6% net decrease in the Contract Cost. No additional days will be added to or deducted from the Contract as a result of this Change Order.

HNTB Corporation

James Klotz, P.E.