

# WILLIAMSON COUNTY, TEXAS CHANGE ORDER NUMBER: \_ 7\_

1. CONTRACTOR: Chasco Constructors	Project: 1603-062	
2. Change Order Work Limits: Sta. 155+00 to	Sta. 161+00 Roadway: CR 258	
3. Type of Change(on federal-aid non-exempt projects):	Minor (Major/Minor) CSJ Number:	
4. Reasons: 2F (3 Max In order of	of importance - Primary first)	
ne east end of the project while excavating to subgrade on the pumping, cutting trenches, excavating, and reworking subgrade trater that was causing the issues with the subgrade.  Work to be performed in accordance with Items:  New or revised plan sheet(s) are attached and numbered.  New Special Provisions/Specifications to the contract are.  New Special Provisions to Item N/A No. N/A, Special ach signatory hereby warrants that each has the authority the contractor must sign the Change Order and, by doing so, agrees to waive	e Attached d: N/A e attached:   Yes  No al Specification Item N/A are attached.	
ny and all claims for additional compensation due to any and all other spenses; additional changes for time, overhead and profit; or loss of impensation as a result of this change.	Time Ext. #:1 Days added on this CO:4	
THE CONTRACTOR Date 5-22:17	Amount added by this change order: \$48,426.44	
Typed/Printed Name  Typed/Printed Title  Pm		
ECOMMENDED FOR EXECUTION:		
Project Manager Date	County Commissioner Precinct 1 [	Date AL
N/A Design Engineer Date	County Commissioner Precinct 2	Date AL
Program Manager Date	County Commissioner Precinct 3  APPROVED REQUEST APPROV	Date AL
Design Engineer's Seal	County Commissioner Precinct 4	Date AL
N/A	She he hat 06-0.	7-20
	County Judge I	Date

# WILLIAMSON COUNTY, TEXAS

CHANGE ORDER NUMBER: 7

2
ဖွ
Ó
က်
0
29
-
##
ect
'=
9
~
щ

TABLE A: Force Account Work and Materials Placed into Stock

LABOR	HOURLY RATE	HOURLY RATE

DESCRIPTION	TABLE B: Contract Items:	ract Items:								
STRAW SOIL RET BLANKET   CANADITY   TEM COST   QUANTITY   QUANTI					ORIGINAL + F	REVIOUSLY SED	ADD or (DEDUCT)	NEW		
STRAW SOIL RET BLANKET         SY         \$1.21         64,600.00         \$78,045.00         (64,500.00)           FORCE ACCOUNT FOR GROUND WATER ISSUE         LS         \$25,794.44         0.00         \$0.00         64,500.00         64,500.00         64,500.00         64,500.00         64,500.00         64,500.00         64,500.00         64,500.00         64,500.00         66,500.00	ITEM	DESCRIPTION	LIND	UNIT PRICE	QUANTITY	ITEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUNI UNDERRUN
FORCE ACCOUNT FOR GROUND WATER ISSUE   LS \$25,794.44   0.000 \$0.00 \$0.00 \$4,500.00 \$64,500.00 \$64,500.00 \$64,500.00 \$64,500.00 \$60.00 \$60.00 \$64,500.00 \$60.00 \$60.00 \$64,500.00 \$60.00 \$60.00 \$64,500 \$60.00 \$64,500 \$60.00 \$64,500 \$60.00 \$64,500 \$60.00 \$64,500 \$60.00 \$64,500 \$60.00 \$64,500 \$60.00 \$64,500 \$60.00 \$64,500 \$60.00 \$64,50	999-WC03	STRAW SOIL RET BLANKET	λS	\$1.21	64,500.00	\$78,045.00	(64,500.00)	0.00		(\$78,045.00)
STRAW SOIL RET BLANKET         SY         \$1.21         0.00         \$0.00         64,500,00           PIPE UNDERDRAIN         LF         \$37.72         0.00         \$0.00         600,00           MISSING AND STRAIN	999-WC05	Т	SJ	\$25,794.44	0.00	\$0.00	1.00	1.00	\$25,794.44	\$25,794.44
PIPE UNDERDRAIN   LF	169-WC01	Π	λS	\$1.21	0.00	\$0.00	64,500.00	64,500.00		\$78,045.00
	556-WC01	PIPE UNDERDRAIN	2	\$37.72	0.00	\$0.00	00.009	00.009	\$22,632.00	\$22,632.00
S			_							
2		TOTA	rs			\$78,045.00			\$126,471.44	\$48,426.44

# CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E 1B. Other
2. Differing Site Conditions	2A. Dispute resolution (expense caused by conditions and/or resulting delay)
(unforeseeable)	2B. Unavailable material
(dinoresecubic)	2C. New development (conditions changing after PS&E completed)
	2D. Environmental remediation
	2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9)
	2F. Site conditions altered by an act of nature
	2G. Unadjusted utility (unforeseeable)
	2H. Unacquired Right-of-Way (unforeseeable)
	21. Additional safety needs (unforeseeable)
	2J. Other
·	
3. County Convenience	3A. Dispute resolution (not resulting from error in plans or differing site conditions)
	3B. Public relations improvement
	3C. Implementation of a Value Engineering finding
	3D. Achievement of an early project completion
	3E. Reduction of future maintenance
	3F. Additional work desired by the County
	3G. Compliance requirements of new laws and/or policies
	3H. Cost savings opportunity discovered during construction
	3I. Implementation of improved technology or better process
	3J. Price adjustment on finished work (price reduced in exchange for acceptance)
	3K. Addition of stock account or material supplied by state provision
	3L. Revising safety work/measures desired by the County
	3M. Other
4. Third Party Accommodation	4A. Failure of a third party to meet commitment
	4B. Third party requested work
	4C. Compliance requirements of new laws and/or policies (impacting third party)
	4D. Other
5. Contractor Convenience	5A. Contractor exercises option to change the traffic control plan
	5B. Contractor requested change in the sequence and/or method of work
	5C. Payment for Partnering workshop
	5D. Additional safety work/measures desired by the contractor
	5E. Other
6. Untimely ROW/Utilities	6A. Right-of-Way not clear (third party responsibility for ROW)
	6B. Right-of-Way not clear (County responsibility for ROW)
	6C. Utilities not clear
	6D. Other

# **Williamson County Road Bond Program**

# CR 258 Williamson County Project No. 1603-062

### Change Order No. 7

# **Reason for Change**

This Change Order provides payment for additional work by the Contractor due to encountering groundwater at the east end of the project. The groundwater was discovered while excavating for the proposed eastbound half of the roadway. Additional work was recorded on the force account, as a tracking measure, until the groundwater issue was resolved. The Contractor pumped water, excavated relief trenches, excavated and placed rock in wet areas, and reworked subgrade numerous times. This additional work did help to minimize the ground water, but it became necessary to install a French Drain along the south side of the roadway so that the groundwater would continue to flow out of the subgrade area. The Contractor installed 600' of 6" perforated pipe with 1" gravel and encased with filter fabric. The pipe was extended to the existing ditch that runs parallel to Ronald Reagan Blvd. The location and elevations of the French Drain will be marked in the as-built plans.

This Change Order also corrects a duplicated line item number which was used on a prior change order. The new item number for the soil retention blanket is listed below. No additional cost is related to this change.

Following is a summary of new items required for this Change Order.

ITEM	DESCRIPTION	QTY	UNIT
999-WC05	FORCE ACCOUNT WORK FOR GROUND WATER	1	LS
169-WC01	STRAW SOIL RET BLANKET	64,500	SY
556-WC01	PIPE UNDERDRAIN	600	LF

This Change Order results in a net increase of \$48,426.44 to the Contract amount, for an adjusted Contract total of \$6,029,442.71 The original Contract amount was \$5,808,856.58. As a result of this and all Change Orders to-date, \$220,586.13 has been added to the Contract, resulting in a 3.8% net increase in the Contract cost. Four (4) additional days will be added to the Contract as a result of this Change Order.

### **HNTB Corporation**

James Klotz, P.E.