

HNTB Colporation

WILLIAMSON COUNTY, TEXAS CHANGE ORDER NUMBER: _6_

CONTRACTOR: Jordan Foster Construction	Project: Koujag-202ck
2. Change Order Work Limits: Sta. 192+75 to	Sta. 254+00 Roadway: Seward Junction
3. Type of Change(on federal-aid non-exempt projects):	Minor (Major/Minor) CSJ Number:
4. Reasons: 2C, 2E (3 Max In order of	of importance - Primary first)
5. Describe the work being revised: 2C: Differing Site Conditions (unforseable) New development Order adds the latest Guardrail End Treatment (MSKT) standard difference in site conditions (unforeseable)(Item 9). This Chalpe on some SET's from 4:1 to 3:1 (RFI 28), due to a change in the contract to address groundwater encountered during constructive on the project were deleted from the contract. This Change	at (conditions changing after PS&E completed). This Change to the contract. 2E: Differeing Site Conditions. Miscellaneous ange Order adds work to extend a storm sewer pipe, revises the in the PGL of the roadway. A pipe underdrain system was added to ction of the roadway (RFI #29). Construction Exit Items that were not Order is for work in the Southeast portion of the project. The attached. The attached. This Change of the Conditions. Miscellaneous angle of the project. The attached. This Change of the Change of the Conditions. The Change of the Change
Typed/Printed Name John Goodrich, P.E. Typed/Printed Title Executive Vice President	
RECOMMENDED FOR EXECUTION:	
9/30/2020 Date	County Commissioner Precinct 1 Date APPROVED REQUEST APPROVAL
N/A Design Englneer Date	County Commissioner Precinct 2 Date APPROVED REQUEST APPROVAL
Program Mar ger Date	County Commissioner PrecInct 3 Date APPROVED REQUEST APPROVAL
Design Engineer's Seal: / N/A	County Commissioner Precinct 4 Date APPROVED REQUEST APPROVAL County Judge Date APPROVED

WILLIAMSON COUNTY, TEXAS

CHANGE ORDER NUMBER:	6	Project #	1812-282
		· -	

TABLE A: Force Account Work and Materials Placed into Stock

LABOR	HOURLY RATE		HOURLY RATE

TABLE B: Contract Items:

				ORIGINAL + PRE	/IOUSLY REVISED	ADD or (DEDUCT)		NEW	
ITEM	DESCRIPTION	UNIT	UNIT PRICE	QUANTITY	ITEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUN/ UNDERRUN
464-WC01	PIPE EXTENSION AT STRUCTURE I	LS	\$2,067.95	0.00	\$0.00	1.00	1.00	\$2,067.95	\$2,067.95
467-6417	SET (TY II) (30IN) (RCP) (3:1) (C)	EA	\$1,850.00	0.00	\$0.00	2.00	2.00	\$3,700.00	\$3,700.00
467-6419	SET (TY II) (30IN) (RCP) (4:1) (C)	EA	\$1,850.00	2.00	\$3,700.00	(2.00)	0.00	\$0.00	(\$3,700.00)
506-6020	CONSTRUCTION EXITS (INSTALL) (TY 1)	SY	\$12.00	400.00	\$4,800.00	(400.00)	0.00	\$0.00	(\$4,800.00)
506-6024	CONSTRUCTION EXITS (REMOVE)	SY	\$9.00	400.00	\$3,600.00	(400.00)	0.00	\$0.00	(\$3,600.00)
544-6001	GUARDRAIL END TREATMENT	EA	\$2,600.00	9.00	\$23,400.00	(9.00)	0.00	\$0.00	(\$23,400.00)
544-6001A	GUARDRAIL END TREATMENT (INSTALL) (MSKT)	EA	\$2,755.40	0.00	\$0.00	9.00	9.00	\$24,798.60	\$24,798.60
999-013	UNDERDRAIN (GROUNDWATER)	LS	\$5,614.49	0.00	\$0.00	1.00	1.00	\$5,614.49	\$5,614.49
							·		
							·		
TOTALS					\$35,500.00			\$36,181.04	\$681.04

CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E 1B. Other
Differing Site Conditions (unforeseeable)	2A. Dispute resolution (expense caused by conditions and/or resulting delay) 2B. Unavailable material 2C. New development (conditions changing after PS&E completed) 2D. Environmental remediation 2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9) 2F. Site conditions altered by an act of nature 2G. Unadjusted utility (unforeseeable) 2H. Unacquired Right-of-Way (unforeseeable) 2I. Additional safety needs (unforeseeable)
3. County Convenience	2J. Other 3A. Dispute resolution (not resulting from error in plans or differing site conditions) 3B. Public relations improvement 3C. Implementation of a Value Engineering finding 3D. Achievement of an early project completion 3E. Reduction of future maintenance 3F. Additional work desired by the County 3G. Compliance requirements of new laws and/or policies 3H. Cost savings opportunity discovered during construction 3I. Implementation of improved technology or better process 3J. Price adjustment on finished work (price reduced in exchange for acceptance) 3K. Addition of stock account or material supplied by state provision 3L. Revising safety work/measures desired by the County
4. Third Party Accommodation	 3M. Other 4A. Failure of a third party to meet commitment 4B. Third party requested work 4C. Compliance requirements of new laws and/or policies (impacting third party) 4D. Other
5. Contractor Convenience	 5A. Contractor exercises option to change the traffic control plan 5B. Contractor requested change in the sequence and/or method of work 5C. Payment for Partnering workshop 5D. Additional safety work/measures desired by the contractor 5E. Other
6. Untimely ROW/Utilities	 6A. Right-of-Way not clear (third party responsibility for ROW) 6B. Right-of-Way not clear (County responsibility for ROW) 6C. Utilities not clear 6D. Other

Williamson County Road Bond Program

Seward Junction Improvements Williamson County Project No. 1812-282

Change Order No. 6

Reason for Change

This Change Order adds the latest TxDOT Guardrail End Treatment (MSKT) standard to the Contract, adds items to for extending a storm sewer pipe, revises the slope for safety end treatments (SET) from 4:1 to 3:1 (RFI 28) and adds a pipe underdrain to address groundwater encountered during construction near the PEC Driveway (RFI 29).

The new TxDOT Standard for the Guardrail End Treatment was updated and issued after the project was designed and will be implemented during construction.

The response to RFI 28 revised the profile grade line (PGL) of the proposed roadway from the south tie-in to the existing CR 266. Due to the change in the PGL, side slopes changed which required changes to Structure "I". Field changes include changes for two (2) SET's from 4:1 to 3:1 and an extension to the length of the storm sewer pipe.

The response to RFI 29 required the installation of an underdrain to allow runoff for groundwater encountered during construction and to stabilize the roadway foundation.

The work being addressed in this Change Order applies to the Seward Junction Southeast portion of the project. Following is a summary of new items required.

ITEM	DESCRIPTION	QTY	UNIT
464-WC01	PIPE EXTENSION AT STRUCTURE I	LS	1
467-6417	SET (TY II) (30IN) (RCP)(3:1) (C)	EA	2
544-6001A	GUARDRAIL END TERMINAL (INSTALL) (MSKT)	EA	9
999-013	UNDERDRAIN (GROUNDWATER)	LS	1

This Change Order results in a net increase of \$681.04 to the Contract amount, for an adjusted Contract total of \$13,686,434.61. The original Contract amount was \$13,270,258.10. As a result of this and all Change Orders to-date, \$416,176.51 has been added to the Contract, resulting in an 3.14% net increase in the Contract cost. No additional days will be added to or deducted from the Contract as a result of this Change Order.

HNTB Corporation

James Klotz, P.E.



15603 North IH 35 Pflugerville, TX 78660 P: 512.990.8313 F: 512.990.3785

A Foundation of Excellence,

August 6, 2020

HNTB 101 E. Old Settlers Blvd., Ste. 100 Round Rock, TX 78664

Attn: Eddie Church, P.E.

Re: Project No. 1812-282

Seward Junction Improvements

Williamson County

Dear Mr. Church:

The following is the lump sum price for the additional work as directed in the RFI #28 response of extending the reinforced concrete pipe installed at Structure I on the above referenced project.

 Item 000-0000
 INSTALL RCP EXTENSIONS

 \$2,067.95

 1
 LS
 \$2,067.95
 = \$2,067.95

A cost breakdown is enclosed for review. If you have any questions, please contact me at (512) 364-3540.

Very Truly Yours,

JORDAN FOSTER CONSTRUCTION

JC Kindel Project Manager

Enclosure: Cost Breakdown.

Kunda

JORDAN FOSTER CONSTRUCTION COST BREAKDOWN

Project: 1812-282 Seward Junction Improvements JFC Job #: 20103

Install RCP Extension per RFI #28 Located at Structure I Estimated Quantity 1 LS

<u>51601.</u>		Hourly Wages	Overtime Factor 37.5%	Payroll Taxes/Insur. 55%	Contractor Compensation 25%	Total Hourly Rate	Number of Hours			Total Cost
Spot Existing Utility										
1 Foreman 1 Excavator (1 Pipe Layer 1 Pipe Layer	•	26.00 22.00 18.00 17.00	9.75 8.25 6.75 6.38	19.66 16.64 13.61 12.86	8.94 7.56 6.19 5.84	64.35 54.45 44.55 42.08	6.00 6.00 6.00 6.00	= = = =	\$ \$ \$	386.10 326.70 267.30 252.45 1,232.55
MATERIAL:										
		Quantity	Unit	Material Rate	Material Compensation 25%	Total Material Rate				
RCP, 30" Concrete, C	lass C	8.00 1.00		34.65 93.50	8.66 23.38	43.31 116.88		=	\$ \$ \$	346.50 116.88 463.38
EQUIPMENT:										
		Quantity	Unit	Equipment Rate	Equipment Compensation 15%	Total Equipment Rate				
Backhoe, D Pickup	eere 310G	6.00 6.00		30.11 20.84	4.52 3.13	34.63 23.97		= =	\$ \$	207.76 143.80 351.56
SUBTOTAL COST									\$	2,047.48
Bond Cost	1%								\$	20.47
TOTAL COST									\$	2,067.95
UNIT PRICE							\$2,067.95	/LS		



15603 North IH 35 Pflugerville, TX 78660 P: 512.990.8313 F: 512.990.3785

A Foundation of Excellence

July 23, 2020

HNTB 101 E. Old Settlers Blvd., Ste. 100 Round Rock, TX 78664

Attn: Eddie Church, P.E.

Re: Project No. 1812-282

Seward Junction Improvements

Williamson County

Dear Mr. Church:

TxDOT has upgraded the standards for guardrail end treatments to MASH compliance. As a result, the SKT guardrail end treatment that was specified on the project at time of bid has changed to the new MSKT. Consequently, the material cost has increased. The following is the unit price difference for the material change to the guardrail end treatments on the above referenced project.

 Item 544-6001
 GUARDRAIL END TREATMENT (Material Change)

 Contractor Cost per Unit
 \$155.40

 Approx.
 9
 EA
 \$155.40
 = \$1,398.60

A cost breakdown and quotes are enclosed for review. If you have any questions, please contact me at (512) 364-3540.

Very Truly Yours,

JORDAN FOSTER CONSTRUCTION

JC Kindel Project Manager

JC Kindel

Enclosure: Cost Breakdown, Quotes.

ROADWAY SPECIALTIES, INC.

P.O. BOX 90309, AUSTIN, TEXAS 78709 512-280-6666 PHONE 512-280-6066 FAX CERTIFIED DBE/HUB

CHANGE ORDER PROPOSAL

Project: SEWARD JUNCTION IMPROVEMENTS	Date:	July 23, 2020
WILLIAMSON COUNTY	RSI Job#:	5742

For: JORDAN FOSTER CONSTRUCTION Proposal No.: 200725P

J.C. KINDEL

We propose to furnish all labor, materials, equipment and supervision to perform the following scope of work that we have been requested to perform at the above referenced project.

Item	Change Order Item Description	Unit	C. O.	Unit	Amount
			Quantity	Price	
5446001	GUARDRAIL END TREATMENT (INSTALL)(SKT)	EA	-9.00	2,475.00	-22,275.00
5446001	GUARDRAIL END TREATMENT (INSTALL)(MSKT)	EA	9.00	2,623.00	23,607.00
	T	otal A	mount of Cha	nge Order:	\$1,332.00

If any additional information is required, please feel free to contact us at (512) 280-6666.

Sincerely,

Lenny Bobrowski

PLEASE NOTE: ALL NOTES AND EXCLUSIONS OF SUBCONTRACT APPLY.

- * This change order is necessary to bring the guardrail end treatments up to current TxDOT standards
- * (MASH Compliant)

Respectfully submitted by: Danette Shelton, President	Accepted by:
	Date:

TEXAS CORRUGATORS

P.O. Box 938 Round Rock, TX 78680 (512)388-0588 (512)388-0417 Fax www.txcorr.com

Quotation

Grates
Sign Posts
Geotextiles
Bridge Railing
Metal Fabrication
Safety Pipe Runners
Corrugated Steel Pipe
Cast Iron Rings & Covers
Metal Beam Guard Fence

ROADWAY SPECIALTIES, INC.

PROJECT

SEWARD JUNCTION IMPROVEMENTS WILLIAMSON COUNTY

ATTN: TERESA

DESCRIPTION

UNIT PRICE

325 LF

QUANTITY

8 EA 9 EA METAL BEAM GUARD FENCE (12 GA)(TIMBER POST)(BLOCK OUT) MTL BEAM GD FEN TRANS (THRIE BEAM) GUARDRAIL END TREATMENT (TY I) 11.46 LF

848.00 EA 1,527.00 EA

TERMS OF PAYMENT: NET 30 DAYS PRICES VALID FOR 30 DAYS SALES TAX NOT INCLUDED

Subject to being awarded the contract, we accept your proposal to furnish the job requirements at the unit prices quoted above

Company Name

/

Print Name Levy 12050

Signature Lenny Williams.

Date <u>4-24-19</u>

DELIVERY: 2-3 WEEKS

F.O.B. POINT: JOBSITE - OUR TRUCKS

PRICES INCLUDE FREIGHT FOR 1 LOAD DELIVERED TO JOBSITE. ADDITIONAL LOADS DUE TO CUSTOMER REQUESTING LESS THAN TRUCKLOAD QUANTITIES WILL BE CHARGED AT \$100.00 PER LOAD.

Respectfully submitted, TEXAS CORRUGATORS-AUSTIN DIVISION, INC

BY COURTNEY YOUNG

Date: 01/14/2019



P.O. Box 938 Round Rock, TX 78680 (512)388-0588 (512)388-0417 Fax www.txcorr.com Grates
Sign Posts
Geotextiles
Bridge Railing
Metal Fabrication
Safety Pipe Runners
Corrugated Steel Pipe
Cast Iron Rings & Covers
Metal Beam Guard Fence

ROADWAY SPECIALTIES, INC.

PROJECT

SEWARD JUNCTION IMPROVEMENTS WILLIAMSON COUNTY

ATTN: LENNY

DESCRIPTION

UNIT PRICE

9 EA

QUANTITY

GUARDRAIL END TREATMENT (MSKT)

1,675.00 EA

PRICES VALID FOR 30 DAYS SALES TAX NOT INCLUDED				
Subject to being awarded the con to furnish the job requirements at				
Company Name				
Print Name				
Signature	Date			

TERMS OF PAYMENT: NET 30 DAYS

DELIVERY: 2-3 WEEKS

F.O.B. POINT: JOBSITE - OUR TRUCKS W/A

FULL ORDER

PRICES INCLUDE FREIGHT FOR 1 LOAD DELIVERED TO JOBSITE. ADDITIONAL LOADS DUE TO CUSTOMER REQUESTING LESS THAN TRUCKLOAD QUANTITIES WILL BE CHARGED AT \$100.00 PER LOAD.

Respectfully submitted, TEXAS CORRUGATORS-AUSTIN DIVISION, INC

BY COURTNEY YOUNG

Date: 7/23/20



15603 North IH 35 Pflugerville, TX 78660 P: 512.990.8313 F: 512.990.3785

A Foundation of Excellence.

August 18, 2020

HNTB 101 E. Old Settlers Blvd., Ste. 100 Round Rock, TX 78664

Attn: Eddie Church, P.E.

Re: Project No. 1812-282

Seward Junction Improvements

Williamson County

Dear Mr. Church:

The following is the lump sum price for the additional work of install an underdrain to address the existing ground water, referenced in RFI #29, at approximate STA 208+50 near the PEC driveway on the above referenced project.

 Item 000-0000
 INSTALL UNDERDRAIN

 S5,614.49

 1
 LS
 @
 \$5,614.49
 =
 \$5,614.49

A cost breakdown is enclosed for review. If you have any questions, please contact me at (512) 364-3540.

Very Truly Yours,

JORDAN FOSTER CONSTRUCTION

JC Kindel Project Manager

Enclosure: Cost Breakdown.

Project: 1812-282 Seward Junction Improvements JFC Job #: 20103

Install Underdrain Near PEC Driveway

Estimated Quantity

1 LS

- 1 /	۸R	ND.	
	<u> ٦</u>	UIV.	

<u> </u>			Hourly Wages	Overtime Factor 37.5%	Payroll Taxes/Insur. 55%	Contractor Compensation 25%	Total Hourly Rate	Number of Hours			Total Cost
Excavation	n										
1 1 1	Name Foreman Excavator Operator Common Laborer ersize Rock		26.00 18.00 16.00	9.75 6.75 6.00	19.66 13.61 12.10	8.94 6.19 5.50	64.35 44.55 39.60	4.00 4.00 4.00	= = =	\$ \$ \$	257.40 178.20 158.40 594.00
1 1 1	Name Foreman Motorgrader Operator Loader Operator		26.00 26.00 22.00	9.75 9.75 8.25	19.66 19.66 16.64	8.94 8.94 7.56	64.35 64.35 54.45	4.00 4.00 4.00	= = =	\$ \$ \$	257.40 257.40 217.80 732.60
<u>MATERIAL</u>	<u>i</u>		Quantity	Unit	Material Rate	Material Compensation 25%	Total Material Rate				
	3x5 Rock Filter Fabric		160.00 1.00		10.00 407.02	2.50 101.76	12.50 508.78		=	\$ \$	2,000.00 508.78 2,508.78
EQUIPMEN	IT:										
			Quantity	Unit	Equipment Rate	Equipment Compensation 15%	Total Equipment Rate				
	Excavator, Caterpillar 308 Motorgrader, Caterpillar 140M3 Loader, Volvo L90F Pickup Dump Truck		4.00 4.00 4.00 8.00 4.00	HR HR HR	50.48 142.84 59.68 20.84 80.00	7.57 21.43 8.95 3.13 12.00	58.05 164.27 68.63 23.97 92.00		= = = =	\$ \$ \$ \$	232.21 657.06 274.53 191.73 368.00 1,723.53
SUBTOTAL	COST									\$	5,558.90
	Bond Cost	1%								\$	55.59
TOTAL CO							,			\$	5,614.49
UNIT PRIC	E							\$5,614.49	/LS	┛	