Ft. Pierce 1705 Sunset Isles Rd.
CB street -> outfall
Reinforced Concrete Pi Circular 18
Joint Separated Large, Start
137.30


Ft. Pierce 1705 Sunset Isles Rd.
CB street -> outfall
Reinforced Concrete Pi Circular 18
Crack Longitudinal, at 10 o'clock,
within 8 inches of joint: YES,
infiltration stain
096.10