



Freightliner/Elgin 2020 Street Sweeper Cost Breakdown

Model M2 106 Class 7- Contract Price	71,344.58
Chassis Upgrades	18,855.42
Elgin Road Wizard Street Sweeper	176,700.00
Unit Price	266,900.00
Less Trade Allowance	16,000.00
Net Amount	250,900.00
Sales Tax	19,570.20
Total Vehicle Sales Price	270,470.20 X 2 units = 540,940.40

Chassis Upgrades Includes:

Factory Chassis Prep for RH Sit-down Secondary Steering Location, Fontaine Modification Installation of RH Steering location with Instrument Cluster, Positive and Negative Jumpstart Posts, Vertical B-Pillar Mounted Tailpipe w/ 10' Exhaust System Height, Detroit 10K Front Axle, 12K Taperleaf Front Suspension, Meritor 23K Rear Axle, Hendrickson 23K Rear Air Suspension, Manual Dump Valve, Single Leveling Valve, Air Dryer with Heater, Upgraded Steel Frame Rails, Dual Bright Heated Electric Mirrors w/ 8' Convex Mirrors and RH and LH Fender Mounted Mirrors, LH and RH Air Side Seats w/ Armrests and LH and RH Adjustable Tilt Steering Columns.

Street Sweeper Body and Equipment, see attached.

9899 W. Roosevelt St., Tolleson, Arizona 85353 T (623) 907-9900 [www.velocityvehiclegroup.com](http://www.velocityvehiclegroup.com)

• LA Freightliner • South Bay Truck Center • San Diego Freightliner • Silver State Truck & Trailer • High Desert Truck & Trailer • Crossroads Equip. Lease & Finance • Performance Truck & Trailer • Olay Truck & Trailer • TransWest • BusWest • Velocity Truck Rental & Leasing • Velocity Truck Center Ventura County • Freightliner of Arizona



## PRODUCT DESCRIPTION

· Conveyor Squeegee, dual, hydraulically driven side brooms, variable height, right side dumping hopper. Sweeper is powder coated from powder coatings chart 2003/N with powder coated gray undercarriage.

## STANDARD FEATURES

- Aux-engine; Cummins
- Two-stage dry type with restriction indicator (at engine) and precleaner
- Broom side, 46" steel vertical digger 4 or 5 segment
- Broom side, hydraulic floating suspension, hydraulic deploy
- Broom, main, 34" diameter, 60" wide prefab disposable
- Camera, Rear with in-cab monitor
- Conveyor chain, hardened with polyurethane sprockets
- Conveyor, 11 flight squeegees with rubber edging
- Conveyor, lift independent from main broom
- Conveyor, three-piece replaceable wear plates
- Conveyor flush out system
- Conveyor raise in reverse
- Conveyor stall alarm
- Dirt shoes, heavy duty single row carbide steel (rubber isolated)
- Electric backup alarm
- Engine, sweeper, diesel, tier 4 FINAL, 74 HP
- Hopper inspection door
- Hopper, 5.4 cu yd with window and skylight
- Hopper up visual audible indicator
- Hopper, variable high dump, 10', 5.4 yard
- Hose, hydrant fill, 16'8" (5080 mm) with strainer and coupling
- Hydraulic oil level gauge w/ external thermometer and in-cab level light
- Lights, automatic backup
- Lights, combination tail/stop, separate amber signal
- Lights, flood light, one per broom (3)
- Manuals, operator and parts
- Rear broom cover and anti-carryover wrap
- Rear broom spray bar
- Rear right hand flood light
- Reflectors, set of 2
- Side broom speed control, external to cab
- Sweep resume / raise in reverse
- Tactile controls for all sweep functions
- Tool storage
- Variable speed brooms (external)
- Water fill, anti-siphon
- Water level indicator in-cab
- Water Pump, electric diaphragm
- Water tank, molded polyethylene, 360-gallon total nominal capacity
- Sweeper Painted Standard White
- Chassis Painted Standard White
- Red Logo

- PM-10 Complaint
- Extended Side broom Reach Right Hand
- Side broom Tilt Option Left Hand
- Side broom Tilt Option Right Hand
- Air Purge for Water System
- Washdown System
- In Cab Air Restriction Gauge for Auxiliary Engine
- SyKlone Pre Cleaner
- (1) Extra Key - Auxiliary Engine
- Package A : LED Stop/Tail/Turn Lights
- Package B : Rear Mounted Arrow stick
- Package C : (2) Rear Low Mounted Oval Amber LED Flashers
- Package D : (2) Rear High Mounted Oval Amber LED Flashers
- (4) LED Work Lights

Two sets of the following books

- Sweeper Service Manual
- Sweeper - Operator Manual
- Sweeper Parts Manual
- Cummins Operators Manual
- Cummins Troubleshooting Manual

One set digital

Left side camera system

Right side camera system

Hopper Window now aligned with chassis rear window