

LINDSAY GENERAL INSURANCE AGENCY
P.O. BOX 100051
DULUTH, GA 30097-0051

KEYWORTH BANK
DULUTH, GA 30097

AC 1140011617

01/11/2013

DATE

PAY TO THE ORDER OF: HIDALGO COUNTY SAFETY DIVISION

PAY Seventeen Thousand Seventy-Four & 76/100 Dollars

\$ 17074.76

M
A
I
L
T
O

HIDALGO COUNTY SAFETY DIVISION
PO BOX 1356
EDINBURG, TX 78540-

Policy: 1026440.013. Adjuster: CMILLER . Req: CMILLER
Claim: 93483. Coverage: PDM
SUBRO SETTLEMENT FULL/FINAL

Donna Williams W Grewe

⑈ 1140011617 ⑈ ⑆ 061121054 ⑆ 2007516 ⑈

CHARLES CLARK CHEVROLET
911 W BUSINESS HIGHWAY 83, MCALLEN, TX
78501
Phone: (956) 578-0489
FAX: (956) 682-2385

Workfile ID: 60e2a86d
Federal ID: 740545450

Preliminary Supplement 1 with Summary

Customer: HIDALGO PCT #4

Job Number:

Written By: Adan Purata

Insured: HIDALGO PCT #4
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
HIDALGO PCT #4

Inspection Location:
CHARLES CLARK CHEVROLET
911 W BUSINESS HIGHWAY 83
MCALLEN, TX 78501
Repair Facility
(956) 578-0489 Day

Insurance Company:

VEHICLE

Year: 2012
Make: CHEV
Model: K2500 4X4 SILVERADO
CREW WORK
Color: WHITE Int:

Body Style: 4D SHORT
Engine: 8-6.0L-FI
Production Date:
Condition:

VIN: 1GC1KVCG9CF143843
License:
State:
Job #:

Mileage In: 3260
Mileage Out:
Vehicle Out:

TRANSMISSION

Automatic Transmission
4 Wheel Drive
Overdrive

POWER

Power Steering
Power Brakes
Power Locks

DECOR

Tinted Glass

Dual Mirrors

CONVENIENCE

Air Conditioning
Tilt Wheel
Cruise Control
Intermittent Wipers

Keyless Entry

Alarm

Message Center

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

SAFETY

Anti-Lock Brakes (4)

Driver Air Bag

Passenger Air Bag

4 Wheel Disc Brakes

Traction Control

Stability Control

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

TRUCK

Rear Step Bumper

Preliminary Supplement 1 with Summary

Customer: HIDALGO PCT #4

Job Number:

Vehicle: 2012 CHEV K2500 4X4 SILVERADO CREW WORK 4D SHORT 8-6.0L-FI WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		REAR BUMPER					
2	Repl	Bumper assy w/o dual rr wheels w/o reverse sensor	25832210	1	981.93	1.1	
3	Repl	Trailer hitch	25843936	1	311.42	0.6	
4	S01 Repl	Connector towing receptical	15932302	1	81.49	Incl.	
5		REAR LAMPS					
6	Repl	LT Combo lamp assy Chevrolet	25958482	1	137.75	Incl.	
7	Repl	RT Combo lamp assy Chevrolet	25958483	1	157.52	Incl.	
8		PICK UP BOX					
9	Repl	Box assy Chevrolet	25969364	1	6,181.71	4.0	15.4
10		Set back box assy				1.5	
11	Repl	Tail gate w/o tail gate assist	20885080	1	699.27	1.3	3.3
12		Overlap Major Non-Adj. Panel					-0.2
13	Repl	Handle bezel w/o lock control	15927251	1	41.32		
14	R&I	Handle all				Incl.	
15	Repl	RT Latch	94715028	1	65.85	Incl.	
16	Repl	LT Latch	94715027	1	65.85	Incl.	
17	Repl	LT Stone guard front Chevrolet	15952189	1	22.00	0.2	
18	Repl	RT Stone guard front Chevrolet	15952188	1	23.11	0.2	
19	Repl	LT Stone guard rear Chevrolet	25783543	1	20.74	0.2	
20	Repl	RT Stone guard rear Chevrolet	25783544	1	22.19	0.2	
21	Repl	LT Decal "4x4"	25798301	1	46.78	0.3	
22	Repl	RT Decal "4x4"	25798301	1	46.78	0.3	
23	Repl	Edge molding	25844299	1	72.20	0.2	
24	Repl	Emblem "BOWTIE"	22829422	1	62.83	0.2	
25	Repl	Nameplate "SILVERADO"	15129652	1	34.80	0.3	
26	Repl	Nameplate "LS"	15925505	1	12.76	0.2	
27	S01 Repl	Guide tube	15078833	1	21.23		
28		CAB					
29	* Rpr	LT Uniside assy				5.0	2.0
		NOTE: REPAIR LT CORNER CAB					
30		Overlap Major Adj. Panel					-0.4
31	* Rpr	RT Uniside assy				4.0	2.0
		NOTE: RT CORNER CAB REPAIR					
32		Overlap Major Adj. Panel					-0.4
33		BACK GLASS					
34	Repl	Back glass GM, w/deep tint w/o heated	25778780	1	198.62	1.5	
35	#	Setup time		1		1.5	
36	#	Rear frame repair		1		5.0	
		NOTE: REAR END FRAME SWAYED NEED TO REPAIR					
37		FRONT BUMPER					
38		O/H front bumper				2.8	

Preliminary Supplement 1 with Summary

Customer: HIDALGO PCT #4

Job Number:

Vehicle: 2012 CHEV K2500 4X4 SILVERADO CREW WORK 4D SHORT 8-6.0L-FI WHITE

39		Repl	Bumper w/o fog lamps	25832522	1	477.19		
40		Repl	Upper cap chrome	25883355	1	244.90		Incl.
41		Repl	Air deflector w/o Z71	22755086	1	176.80		Incl.
42		Repl	Lower extrn	20845670	1	48.31		Incl.
43		Repl	RT Outer bracket	25883351	1	94.33		Incl.
44		Repl	LT Outer bracket	25883350	1	94.33		Incl.
45		Repl	RT Outer filler 6.0 liter	25883357	1	15.57		Incl.
46		Repl	LT Outer filler 6.0 liter	25883356	1	15.57		Incl.
47		Repl	RT Outer reinf	25883348	1	22.45		Incl.
48		Repl	LT Outer reinf	25883347	1	22.45		Incl.
49		Repl	Center reinf	25996794	1	16.77		Incl.
50		Repl	LT Outer bracket anchor plate	25996793	1	13.82		
51		Repl	RT Outer bracket anchor plate	25996793	1	13.82		
52		Repl	RT Mount bracket	20966182	1	28.28		0.3
53	S01	Repl	RT Inner bracket	25883353	1	24.81		Incl.
54	S01	Repl	LT Inner bracket	25883352	1	24.81		Incl.
55			GRILLE					
56		Repl	Grille assy chrome	20966058	1	271.56		Incl.
57			FRONT LAMPS					
58		Repl	RT Headlamp assy	25962805	1	260.68		0.3
59			Alm headlamps					0.5
60	#	R&I	Brush Guard					2.0
61	S01	Repl	LT Headlamp assy	25962804	1	261.83		0.3
62			HOOD					
63	*	Repl	Hood	20952312	1	350.00		1.5
64			Overlap Major Adj. Panel					3.2
65			Add for Underside(Complete)					-0.4
66			Add for Clear Coat					1.6
67		Repl	Front molding chrome	20963700	1	77.08		0.3
68	#		Frame repair					0.2
			NOTE: TIME IS TO REPAIR FRONT EXTENTIONS					5.0 F
69	S01	Repl	RT Emblem "VORTEC"	25909695	1	25.48		Incl.
70	S01	Repl	LT Emblem "VORTEC"	25909695	1	25.48		Incl.
71	S01	Repl	RT Rear molding	22753693	1	58.04		0.3
72	S01	Repl	LT Rear molding	22753694	1	58.04		0.3
73			RESTRAINT SYSTEMS					
74		Repl	LT Belt & retractor ebony	19210385	1	137.04		0.5
75		Repl	Diagnostic unit w/head air bag	13580451	1	214.35	m	0.4 M
76			System diagnosis				m	0.5 M
77		Repl	Ft impact sensor	13502744	1	75.21	m	0.3 M
78	#	Repl	Corrosion protection			10.00		
79	#	Repl	Cover car			5.00		
80	#	Subl	Hazardous waste removal			3.00		
81	S01	Repl	RT Belt & retractor titanium	19210390	1	158.33		0.5
82			FRAME					

Preliminary Supplement 1 with Summary

Customer: HIDALGO PCT #4

Job Number:

Vehicle: 2012 CHEV K2500 4X4 SILVERADO CREW WORK 4D SHORT 8-6.0L-FI WHITE

83	*	S01	Repl	LT Mount bracket 6.5 ft box	20910361	1	45.12	2.0	
84	*	S01	Repl	RT Mount bracket 6.5 ft box	20910360	1	45.12	2.0	
85	FENDER								
86	*	S01	Rpr	RT Fender Chevrolet				3.0	2.0
87		S01		Overlap Major Adj. Panel					-0.4
88	*			Clear Coat					3.5
89	#	S01	Repl	Emblem		1	36.63		
90	#	S01	Subl	Reprogram Air bag module		1	103.99 X		
SUBTOTALS							12,864.34	50.5	31.5

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			12,760.35
Body Labor	44.3 hrs @	\$ 38.00 /hr	1,683.40
Paint Labor	31.5 hrs @	\$ 38.00 /hr	1,197.00
Mechanical Labor	1.2 hrs @	\$ 75.00 /hr	90.00
Frame Labor	5.0 hrs @	\$ 48.00 /hr	240.00
Paint Supplies			999.99
Miscellaneous			103.99
Subtotal			17,074.73
Grand Total			17,074.73
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			17,074.73

Preliminary Supplement 1 with Summary

Customer: HIDALGO PCT #4

Job Number:

Vehicle: 2012 CHEV K2500 4X4 SILVERADO CREW WORK 4D SHORT 8-6.0L-FI WHITE

SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Changed Items							
58		Overlap Major Non-Adj. Panel					0.2
64	S01	Overlap Major Adj. Panel					-0.4
Added Items							
4	S01	Repl Connector towing receptical	15932302	1	81.49	Incl.	
27	S01	Repl Guide tube	15078833	1	21.23		
53	S01	Repl RT Inner bracket	25883353	1	24.81	Incl.	
54	S01	Repl LT Inner bracket	25883352	1	24.81	Incl.	
61	S01	Repl LT Headlamp assy	25962804	1	261.83	0.3	
69	S01	Repl RT Emblem "VORTEC"	25909695	1	25.48	Incl.	
70	S01	Repl LT Emblem "VORTEC"	25909695	1	25.48	Incl.	
71	S01	Repl RT Rear molding	22753693	1	58.04	0.3	
72	S01	Repl LT Rear molding	22753694	1	58.04	0.3	
81	S01	Repl RT Belt & retractor titanium	19210390	1	158.33	0.5	
82	FRAME						
83	*	S01 Repl LT Mount bracket 6.5 ft box	20910361	1	45.12	2.0	
84	*	S01 Repl RT Mount bracket 6.5 ft box	20910360	1	45.12	2.0	
85	FENDER						
86	*	S01 Rpr RT Fender Chevrolet				3.0	2.0
87	S01	Overlap Major Adj. Panel					-0.4
89	#	S01 Repl Emblem		1	36.63		
90	#	S01 Subl Reprogram Air bag module		1	103.99 X		
SUBTOTALS					970.40	8.4	1.4

TOTALS SUMMARY

Category	Basis	Rate	Cost \$
Parts			866.41
Body Labor	8.4 hrs @	\$ 38.00 /hr	319.20
Paint Labor	1.4 hrs @	\$ 38.00 /hr	53.20
Paint Supplies	1.7 hrs @	\$ 28.00 /hr	47.60
Additional Supplement Materials/Supplies			-16.41
Miscellaneous			103.99
Subtotal			1,373.99
Total Supplement Amount			1,373.99
NET COST OF SUPPLEMENT			1,373.99

Preliminary Supplement 1 with Summary

Customer: HIDALGO PCT #4

Job Number:

Vehicle: 2012 CHEV K2500 4X4 SILVERADO CREW WORK 4D SHORT 8-6.0L-FI WHITE

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	15,700.74	Adan Purata
Supplement S01	1,373.99	Adan Purata
Job Total:	\$ 17,074.73	
INSURANCE PAY:	\$ 17,074.73	

We at Charles Clark Chevrolet highly recommend the use of OEM (manufacturer parts only). It is by your choice or insurance recommendation that we will use other than factory specific parts. We will not be held responsible for the choice of using these parts or events there-after. I (the customer) understand that only the work listed will be done and there may be hidden damage that may require more labor or parts to repair.

IMPORTANT INFORMATION ABOUT THE NAMED INSURANCE COMPANY'S CHOICE OF PARTS POLICY.

THIS ESTIMATE MAY LIST PARTS FOR USE IN THE REPAIR OF YOUR VEHICLE THAT ARE MANUFACTURED BY A COMPANY OTHER THAN THE ORIGINAL MANUFACTURER OF YOUR VEHICLE. THESE PARTS ARE COMMONLY REFERRED TO AS AFTERMARKET PARTS OR COMPETITIVE PARTS, AND MAY INCLUDE COSMETIC OUTER BODY CRASH PARTS SUCH AS HOODS, FENDERS, BUMPER COVERS, ETC. THE INSURANCE COMPANY GUARANTEES THE FIT AND CORROSION RESISTANCE OF ANY AFTERMARKET/COMPETITIVE OUTER BODY CRASH PARTS THAT ARE LISTED ON THIS ESTIMATE AND ACTUALLY USED IN THE REPAIR OF YOUR VEHICLE FOR AS LONG AS YOU OWN IT. IF A PROBLEM DEVELOPS WITH THE FIT OR CORROSION RESISTANCE OF THESE PARTS, THEY WILL BE REPAIRED OR REPLACED AT THE INSURANCE COMPANY'S EXPENSE. THIS GUARANTEE IS LIMITED TO THE REPAIR OR REPLACEMENT OF THE PART. HOWEVER, IF YOU CHOOSE NOT TO USE ONE OR MORE OF THE AFTERMARKET/COMPETITIVE OUTER BODY CRASH PARTS THAT MAY BE LISTED ON THIS ESTIMATE IN THE REPAIR OF YOUR VEHICLE, THE INSURANCE COMPANY WILL SPECIFY THE USE OF ORIGINAL EQUIPMENT MANUFACTURER PARTS, EITHER NEW OR RECYCLED AT THE INSURANCE COMPANY'S OPTION, AT NO ADDITIONAL COST TO YOU. THE INSURANCE COMPANY DOES NOT SEPARATELY GUARANTEE THE PERFORMANCE OF ORIGINAL EQUIPMENT MANUFACTURER PARTS, AND MAKES NO REPRESENTATION ABOUT THE AVAILABILITY OF ANY MANUFACTURER'S GUARANTEE.

Estimate calculated using a preset user threshold amount for the paint and material cost.