

# Lumatec Lighting Service

Tel: 956-664-1854  
Fax: 956-664-9981  
Date: 1/5/2017

4110 N. Jackson Raod

Pharr TX 78577

[www.lumateclighting2000@yahoo.com](http://www.lumateclighting2000@yahoo.com)

YEAR	MAKE	MODEL	MILEAGE	SERIAL NUMBER	LICENSE PLATE	PRICE
2000	Ford	F-350 Super Duty	205,957	1FDWF36S5YEC12521	GLW4698	\$18,500.00

\*Mileage complete (10) miles on motor (Engine Overhaul)

## Vehicle Description As Follow Below:

Oxford white/tires BSW all season ((Tire Store)  
4 speed auto O/D  
Reach Axle - 4.11 Ratio  
Air condition  
Power steering  
Ladder rack  
Rear steel bumper and reciever hitch  
Trailer female plug  
Rear wheel chucks

## Standard Equipment As Follows Below:

Exterior Emergency becon flashers  
Interval wipers water key rack  
Tinted glass  
16" chrome style wheel covers  
LT245/75/16 tires (Firestone)  
Front push bumper guard  
Rear back up warning alarm

## Interior As Follows Below:

Full seat (Vinyl cover)  
Black vinyl floor covering  
Dome lamp radio  
Front floor matts

(Continuacion on Page 2)

BORDER ENGINE REBUILDERS & DIESEL SERVICES  
 100 INTERNATIONAL BLVD  
 MISSION TX 78572  
 (956) 585-4866  
 THANK YOU FOR YOUR BUSINESS!!!!

page 1

Invoice #94406

LUMATECH LIGHTING  
 46014 N. JACKSON RD.  
 PHARR TX 78577

Day Phone : 956-664-1854  
 Fax Number : 956-664-9981

Vehicle : 2000 Ford Truck F350 Super Duty 1 Ton - Pickup  
 VIN : 1FDWF36S5YEC12521

Tag/State : GLW4698 / TX  
 Color : White  
 Last Mileage: 205942  
 Odometer In : 205942  
 Odometer Out: 205942

Created : 1/4/2016 2:31:21 PM  
 Contact : VICTOR RIOS  
 Srv WriterOR

Qty	Code/Tech	Reference	Description	Condi	Unit	Price	Price
1	OR*	LABOR	R & R COMPLETE ENGINE			\$650.00	\$650.00
1	--	PART	6.8 FORD V10 REBUILT ENGINE			\$2,695.00	\$2,695.00
TO INCLUDE: PISTONS, RINGS, MAIN BEARINGS, ROD BEARINGS, GASKET SET, OIL PUMP, TIMING COMPONENTS, BORE & HONE CYLINDER BLOCK, REGRIND CRANKSHAFT, POLISH CAMSHAFTS, VALVE JOB ON CYLINDER HEADS, HONE BIG END ON CON ROD, MOUNT PISTONS ON CON RODS, ALIGN HONE MAIN WEB ON CYLINDER BLOCK, DEGREASE & INSPECT ALL INTERNAL ENGINE COMPONENTS, ASSEMBLE AS A DROP IN ENGINE. ENGINE CORE MUST BE REBUIDABLE OR A CORE CHARGE MAY BE INCURRED. DUE TO ENGINE BEING OF COMMERCIAL USE A 6 MONTH WARRANTY WILL ALLOWED. NO EXTERNAL ENGINE HARD PARTS OR SENSORS WILL BE REPLACED AT THIS TIME.							
1	--	PART	6.8 FORD V-10 CRANKSHAFT			\$375.00	\$375.00
6	NOL	75530	Motor Oil - NAPA Synthetic - SAE 5W20 - 1 Qt			\$9.97	\$59.82
10	ASP	AP103	Spark Plug - Platinum			\$9.57	\$95.70
1	SFL	36418	Air Filter (Silver)			\$41.75	\$41.75
1	FIL	3296	Fuel Filter (Gold)			\$24.42	\$24.42
1	FIL	1372	Oil Filter (Gold)			\$15.74	\$15.74
1	TFW	42079	Water Pump - New			\$167.10	\$167.10
1	THM	162	Thermostat - Regular			\$27.71	\$27.71
1	THM	1107	Thermostat Housing Seal			\$4.53	\$4.53
10	NCE	7353589	Spark Plug Boot (Coil On Plug)			\$29.10	\$291.00
2	NAF	1GAL	Antifreeze - Regular Green - Gallon			\$39.36	\$78.72
Labor							\$650.00
Parts							\$3,876.49
Sublet/Misc.							\$0.00
Shop Supplies							\$0.00
Charges							\$0.00
Sales Tax							\$319.81
Tax @ \$3,876.49 * 8.2500%							\$319.81
Repair Total							\$4,846.30

Tech  
OR

Certification #