



Invoice

Date	Invoice #
8/15/2017	20027

P.O. Box 2724
 McAllen, Tx. 78502
 (956) 585-3773

Please send remittance with copy of invoice to:

Attn: Mrs. Aisha Gonzalez
 P.O. Box 2724
 McAllen, Tx. 78502

Bill To:
 Hidalgo County Precinct #2
 300 W. Hall Acres Rd.
 Pharr, TX 78577


Project Info:
 Hidalgo County Precinct #2
 Asbestos Testing Services for
 Palmer Pavilion
 B2Z JOB: 2105
 PO # 766041

Billing Period August 2017

Description	Contract	Previous Applications	Current Completed	Total Completed	% Complete
Asbestos Analysis & Report	\$ 1,076.79	\$ -	\$ 1,076.79	\$ 1,076.79	100%
Total For This Billing Period				\$1,076.79	

Work Authorization ~ Summary

WA No.	WA Amount	Previously Inv.	Percent Complete	Remaining Balance
6	\$1,076.79	\$0.00	100.0%	\$0.00


 Aisha Gonzalez - President

INVOICE RECEIVED BY:
 Elizabeth Casas ON 8/15/17
 GOODS/SERVICES RECEIVED BY:
 Eduardo Cantu ON 8-7-17

August 15, 2017

Hon. Eddie Cantu
Commissioner, Hidalgo County Pct. #2
300 W. Hall Acres Rd.
Pharr, TX 78577

**RE: Contract # 16-326-08-23 ~ Road and Bridge, CIP and Other Projects in General
(On Call)
Work Authorization #6 ~ Asbestos Testing for Palmer Pavilion
PO #766041**

Dear Commissioner Cantu:

Attached for your review and approval is our invoice for services rendered under Work Authorization #6 on the subject referenced project.

The following is attached:


- Invoice No. 20027

The following is a narrative of the progress for this period.

TASK:	
Asbestos Analysis & Report	
UPDATED: B2Z Engineering contracted a licensed asbestos inspector to conduct a limited survey on the Palmer Pavilion Site Structures to be demolished; main pavilion structure approximately 16,300 square feet, (3) adjacent storage sheds approximately 2,300 square feet (combined). All building structures are constructed of metal frame, sheet metal roof, sheet metal siding, and concrete foundations. No suspect materials were noted. B2Z prepared a report with the findings and recommendations. Furthermore, B2Z managed all aspects of this contract within the agreed time set forth by the client. This task is complete.	100%

Should you have any questions regarding this submittal, please do not hesitate to call me at (956) 585-3773.

Sincerely,



Carlos Del Angel
Senior Construction Manager – B2Z Engineering, LLC

AAMECC LLC

1327 E. Washington Ave. #242, Harlingen, TX 78550

August 7, 2017

Ms. Aisha Gonzalez
President
B2Z Engineering
900 S Stewart Rd
Mission, TX 78572
(956) 566-3421 (O)
aisha@b2zeng.com

Ref: Asbestos Survey
Palmer Pavilion & Associated Buildings
301 E Hackberry Ave
McAllen, TX 78501
AAMECC Project No. 17-1361

Dear Ms. Gonzalez:

AAMECC LLC, a Texas Department of State Health Services (DSHS) Licensed Asbestos Consultant Agency (DSHS No. 10-0495) has conducted a limited asbestos survey at the above referenced site.

Mr. Jose A. Arellano, a DSHS Licensed Asbestos Inspector No. 60-3340, conducted an asbestos survey at the above referenced site on July 24, 2017 for asbestos containing materials (ACM) for renovations.

The building's to be demolished include the Palmer Pavilion building (approximately 16,296 square feet) and three (3) adjacent storage sheds (approximately 2,328 combined square feet). The Palmer Pavilion building along with the three (3) storage sheds are constructed of metal frame, sheet metal roof and siding on a concrete foundation. Rest Room renovations are to take place in the Kitchen building area which is constructed of metal frame, sheet metal roof and siding on a concrete floor (approximately 3,720 square feet). No suspect materials were noted; therefore, no samples were collected or analyzed.

Prior to demolition (removal of structural support members), the DSHS Demolition/Renovation Notification form must be completed and postmarked at least 10 working days before the anticipated project start date (except for emergencies or ordered demolitions).

Should you have any questions, please do not hesitate to contact us.

Sincerely,

AAMECC LLC



Jose A. Arellano
DSHS Inspector License No. 60-3340



David A. Hanawa
DSHS Consultant License No. 10-5367