

PAYMENT NO 1 25 953451 J
PAYMENT AMOUNT \$4,896.10
ISSUE DATE 01-14-2020
AUTHORIZED BY WALKER, RABETH
PHONE (844) 292-8615

CLAIM NO 53-C683-5H6
LOSS DATE 01-10-2019
POLICY NO 2051-815-53G
INSURED CREATIVE IMAGING LLP

COUNTY OF HIDALGO
9805 N 10TH ST
MCALLEN TX 78504-9529

REMARKS 4896.10 for damages claim 19-01-10-1601 Sally Port Exit fo
r dmgs caused by Miguel Lopez

COVERAGE DESCRIPTION	ON BEHALF OF	AMOUNT
COLLISION	CREATIVE IMAGING LLP	4,896.10

RETAIN STUB FOR RECORDS

State Farm

STATE FARM MUTUAL AUTOMOBILE INSURANCE COMPANY

1 25 953451 J

PROPERTY DAMAGE

JPMORGAN CHASE BANK, NA 56-1544/441
COLUMBUS, OH

PROP D OFFICE - PAGECNTQ.P07E

DATE 01-14-2020
MM.DD.YY.YY

CLAIM NO: 53-C683-5H6
LOSS DATE 01-10-2019

INSURED CREATIVE IMAGING LLP

**EXACTLY FOUR THOUSAND EIGHT HUNDRED NINETY-SIX AND 10/100 DOLLARS

\$*****4,896.10

Pay to the
Order of: COUNTY OF HIDALGO

Michael J. Lynn
AUTHORIZED SIGNATURE
Jon C. Farney
AUTHORIZED SIGNATURE

SECURED DOCUMENT WATERMARK APPEARS ON BACK, HOLD AT 45° ANGLE FOR VIEWING

⑈ 2517953451⑈ ⑆044115443⑆

627119209⑈

GREEN DROPOUT APPEARS ON FACE OF DOCUMENT

VOID IF GREEN COLORED BACKGROUND IS MISSING



Lauro Torres <lauro.torres@co.hidalgo.tx.us>

Claim #53C6835H6

1 message

Lauro Torres <lauro.torres@co.hidalgo.tx.us>
To: statefarmclaims@statefarm.com

Mon, Jan 13, 2020 at 3:41 PM

Good Afternoon,

Attached is our demand letter in the amount of \$4,896.10 for the damages caused to our property on the above mentioned claim.


Also, attached is a detailed estimate for the repairs and photos of the damages.

If you have any questions or need additional information, please do not hesitate to contact me.


Thank you.

Lauro Torres
County of Hidalgo Safety Division
9805 N. 10th Street
McAllen, TX. 78504
(956) 292-7030 ext. 5464 - Office
(956) 318-2658 - Fax
lauro.torres@co.hidalgo.tx.us

11 attachments



IMG_0289.jpg
168K



IMG_0293.jpg
51K

IMG_0292.jpg
53K



February 6, 2019

Judge Mario E. Ramirez Jr. Juvenile Justice Center
1001 N. Doolittle Road
Edinburg, Texas 78542

Buy Board #510-16

RE: Repair Damaged Curtain Overhead Door

Dear Ralph,

Petroleum Solutions Inc. proposes to furnish the necessary labor, materials and equipment for the proposed scope of work:

- Service Slats
Wth 8.ft-3.,-1/2"ln) x Hgt:.ft-in) Product code: 1F22 Weight:68.42
Slat Quantity: 020 @ 8ft 3- 1/2" lg
Curtain: 1F 22ga stainless steel #4
Endlock: CP0035 Alternative molded nylon
Bottom Bar: Single angle stainless ST #4
Bar Size: (1) 1 3/4" x 1 3/4" x 12 GA @ 8FT 3-1/
Bottom Bar cutout 1- 5/8"
Bottom Bar Astragal
Padlockable Slide Bolts Oper Coll Side
- Removal of Damaged Slats and bottom Bar, Installation of new slats and bottom bar, Lube and adjust door. Readjust limit switches and check door for proper operation
- Clean up dispose of debris

Subtotal	\$ 4,522.96
Taxes	\$ 373.14
Total Price	\$ 4,896.10

Note: If Approved, Parts will be order and delivery approx. 2 weeks

Note: Pricing is only valid 30 days from date quote.

To accept this bid please sign one copy and return it to us. Thank you for the opportunity to submit this proposal for your consideration.

Respectfully yours,

Mike Molina

Petroleum Solutions Inc.

I (we) accept the equipment and/or installation prices as stated in this quotation on the

_____ day of _____, 20 _____

Accepted By:

Judge Mario E. Ramirez Jr. Juvenile Justice Center

Approved by:

Petroleum Solutions, Inc.