

LESO FEPMIS: Property Review User ID: HiCoSh

Inventory Search | Inventory Search Results | Inventory Item

Property Review | Shipping History | Change of Status Details | Certification Details | Acquisition Details | Access Documents

Property #: 14027TX00071
Commodity Type: UAH
Property Type: FFP
Status: ASSIGNED
Requisition #: H9DEB1-2065-5000
DTID: W51HNE-1348-3004A
Quantity: 1
Unit Cost: \$89,900.00
Inventory Certification Date: Mar 03, 2020
FSC: 2320 - Trucks and Truck Tractors, Wheeled
Item Name: TRUCK,UTILITY
Additional Description: DESC=TRUCK,UTILITY
NSN/LSN: 2320-01-346-9317
DMIL: C- USML ITEMS - DEMIL REQD. REMOVE/DEMIL INSTALLED KEY POINT(S).
DMIL Integrity Code: 1
State Property#:
State: TEXAS
Division: DEFAULT_DIV_TX
Subdivision: DEFAULT_SUBDIV_TX
Station: HIDALGO COUNTY SHERIFFS OFFICE
Part Number:
Make / Manufacturer: NA
Model: NA
Model Year: 0
Color:
Drive Type:
Tonnage:
Serial#: 144708
Unit of Issue: Each
Condition: Issuable, no Qualification - Serviceable (Issuable without Qualification) New, used, repaired, or reconditioned material which is serviceable and issuable to all customers without limitation or restriction. Includes material with more than 6 months of shelf life remaining.

Physical Storage

Location:
Ship Date: Mar 19, 2012

Additional Comments:

[Empty text box for additional comments]

rolling stock attributes

Vehicle License# :
Miles or Hours: 6335
Fuel Type:
Number of Cylinders:
Transmission Type:

Comment 1: NSN IS WRONG. CORRECT NSN IS
2320-01-348-9317
EJR01036 3.12.2015

Comment 2:

ITEM_ID=955045 DOC#=20655000

Comment 3:

Reactivation Comment:



Data Plate



Data Plate



Provide Description



Provide Description



Front



Back

Comment 1: NSN IS WRONG. CORRECT NSN IS
2320-01-348-9317
EJR01036 3.12.2015

Comment 2:

Comment 3: ITEM_ID=955045 DOC#=20655000

Reactivation Comment:



Front

Back

Comment 1: NSN IS WRONG. CORRECT NSN IS
2320-01-348-9317
EJR01036 3.12.2015

Comment 2:

Comment 3: ITEM_ID=955045 DOC#=20655000

Reactivation Comment:




Comment 1: NSN IS WRONG. CORRECT NSN IS
2320-01-348-9317
EJR01036 3.12.2015

Comment 2:

Comment 3: ITEM_ID=955045 DOC#=20655000

Reactivation Comment:



Provide Description



Provide Description



Front



Back


Comment 1: NSN IS WRONG. CORRECT NSN IS
2320-01-348-9317
EJR01036 3.12.2015

Comment 2:

ITEM_ID=955045 DOC#=20655000

Comment 3:

Reactivation Comment:



Data Plate



Provide Description



Provide Description



Front



Back

