



TEXAS DEPARTMENT OF LICENSING AND REGULATION

Regulatory Program Management Division/Architectural Barriers Program
P. O. Box 12157 • Austin, Texas 78711 • (512) 539-5669 • (877) 278-0999
Fax: (512) 539-5690 • techinfo@tdlr.texas.gov • www.tdlr.texas.gov

08/12/2021

HIDALGO COUNTY SHERIFFS OFFICE
711 E CIBOLO ROAD
EDINBURG TEXAS 78541

RE: Project Name: HCSO BUS BARN CONTRACT C-18-142-05-08
Facility Name: 711 E CIBOLO ROAD
Address: EDINBURG TX 78541
Project Number: TABS2020019791

Notice of Inspection Overdue

Attention Building Owner,

Our records show that the project number listed above was completed more than a year ago. Unfortunately, we have no record that the required inspection of the facility has occurred as required.

You are required to have a site inspection no later than the first anniversary of the date of completion per the Texas Architectural Barriers Act (TABA), Tex. Gov. Code §§469.101 and 469.105 in order to ensure compliance with the Texas Accessibility Standards (TAS).

You must complete the section below and return this notice to TDLR within 30 days from the date of this notice. Failure to comply or satisfy the requirements before the deadline could result in our forwarding this issue to our Enforcement Division to impose possible administrative penalties of up to \$5,000 per violation, per day not corrected and/or sanctions against you.

Check one of the following:

RAS* [name] A.Covacevich TDLR License Number 97 will inspect this project.; or

The referenced project is incomplete. The new estimated completion date is ___/___/___; or

The referenced project was canceled. The project was not and will NOT be constructed; or

The ownership of this building/facility has changed.

Owner Name (Printed): Judge Richard Cortez Date: _____, Phone: _____

Owner Signature: _____ Email address: _____
(please print)

Please include the project number listed above on all correspondence related to this project. Please visit the TDLR website at www.tdlr.texas.gov or contact the EAB Division at techinfo@tdlr.texas.gov or call us at 512-539-5669.

*The RAS must have an active license with TDLR. This notice is NOT considered a request for inspection. We will not send this notice to the RAS. You must contact the RAS directly to arrange for an inspection.