



Purchase Order COUNTY OF HIDALGO

PO# 892663

DATE: 02/06/2025

PAGE: 1 of 3

PO TYPE:

VENDOR: 524034

REQ: 00510839

PHONE:

BUYER: SHERIFF'S LAW ENFORCEMENT FACILITY PO

EMAIL:

SHIP TO: HIDALGO COUNTY JAIL

701 EL CIBOLO RD
EDINBURG Tx 78539

AMSTAR INC
1211 PLEASANTON ROAD
SAN ANTONIO TX 78214

VENDOR ACCOUNT:

CONTACT: P EILENBERGER (956) 393-6023

SITE: HIDALGO COUNTY JAIL

CONTRACT: BUYBOARD JOC 660-21

SPECIAL INSTRUCTIONS:

VENDOR NOTES

1. Do not add to, or alter this Purchase Order. This Order is not renewable.
2. TAX EXEMPTION. This Purchase Order may be accepted in lieu of Exemption Certificate.
3. This Order is also placed F.O.B. Destination. Vendor must repay all shipping costs.
4. Invoice each Purchase Order singly. Original invoices are required customer copy may be accepted. Out number must appear on all invoices, bills of lading, and packages.
5. Payment will be made only for bona fide and full completed orders, unless otherwise attached.

QTY	UOM	DESCRIPTION	UNIT PRICE	AMOUNT
1.00		DO NOT DUPLICATE ORDER JOC CONTRACT #660-21 AI-98126 APPROVED BY CC 1/28/2025 HVAC THERMNOSTAT & OTHER REPAIRS FOR THE WILLACY COUNTY DETENTION FACILITY CO This Proposal is offered as set forth in the terms and conditions of the contract and the statement of work: 1. Installed 29 T-Stats 2. Installed 16 T-Stats Guards 3. Relocated (11) T-Stats on RTU6,12,14,15,16,19,19-A,24,25,27,28 4. Replace Blower Housing Shaft Bearings Blower Wheel to RTU #10 5. RTU #14 Replaced both Condenser Coils and both 3/8 Filter Driers and Recharge with R-410 Refrigerant. Replaced Compressor from unit #9 and Condenser Fan Motor 6. RTU#15 Replaced Compressor #2 New and Recharge with R-410 7. RTU #16 Replace Condenser Fan Motor 8. RTU #17 Had replaced one Condenser Fan motor as 1st Contract. Then replaced other Condenser Fan Motor unit, it started to have bigger leak with Freon. Recommended to Replace unit. 9. RTU#18 Replaced Gas Valve, Gas Burners, Inducer Motor, Limit Switch, and Flame Sensor (Jimmy) Provided. 10. RTU #19 Replaced Blower Motor and Fuses to main unit. 11. RTU #21 Had Recharge unit as 1st Contract then motor went out. Replaced Condenser Fan Motor. 12. RTU #22 Replace Blower Wheel Assembly Blower Wheel as 1st Contract and Recharge unit. Unit was all Corroded had to Recharge again. Recommended to change unit. 13. RTU#23 Replaced Blower Motor with Bracket and Replaced Fan Motor Replaced Gas Valve, Gas Burners, Inducer Motor, Limit Switch, and Flame Sensor (Jimmy) Provided. 14. RTU #29 Replace both Condenser Coils and both Filter Driers and recharge Whole System with Refrigerant. 15. RTU #30 Replace both Condenser Coils and both 3/8 Filter Driers and Recharge Whole System with Refrigerant. 16. RTU#29 Replaced Compressor and Mother Board from RTU#9 and	0.0000	0.00

Authorized by: Ignacio Amargosa



Purchase Order COUNTY OF HIDALGO

PO# 892663

DATE: 02/06/2025

PAGE: 2 Of 3

PO TYPE:

VENDOR: 524034

REQ: 00510839

PHONE:

BUYER: SHERIFF'S LAW ENFORCEMENT FACILITY PO

EMAIL:

SHIP TO: HIDALGO COUNTY JAIL

701 EL CIBOLO RD
EDINBURG Tx 78539

AMSTAR INC
1211 PLEASANTON ROAD
SAN ANTONIO TX 78214

VENDOR ACCOUNT:

CONTACT: P EILENBERGER

(956) 393-6023

SITE: HIDALGO COUNTY JAIL

CONTRACT: BUYBOARD JOC 660-21

SPECIAL INSTRUCTIONS:

VENDOR NOTES

1. Do not add to, or alter this Purchase Order. This Order is not renewable.
2. TAX EXEMPTION. This Purchase Order may be accepted in lieu of Exemption Certificate.
3. This Order is also placed F.O.B. Destination. Vendor must repay all shipping costs.
4. Invoice each Purchase Order singly. Original invoices are required customer copy may be accepted. Out number must appear on all invoices, bills of lading, and packages.
5. Payment will be made only for bona fide and fully completed orders, unless otherwise attached.

QTY	UOM	DESCRIPTION	UNIT PRICE	AMOUNT
1.00		Replaced Gas Valve and Limit Switch and Flame Sensor. 17. RTU#19-(A) Replaced Both Gas Valves and Both Module for Heater and Flame Sensors 18. Installed (14) Fresh Air Dampers to New Units 19. Installed 7.5 Carrier RTU Jimmy Provided and we provided Curb Adaptor, Crane Service and Labor. 19. Investigation of gas leak. a. Perform bubble test and electronic gas sniffer. 20. 2" Black steel union a. Remove the existing compromised 2" union. b. Clean and prep threads on the existing pipes. c. Install new 2" black steel union. d. Turn on gas at the shutoff at the riser. e. Check for leaks. 21. 2" PVC Vent Repair a. Setup ladder to access the attic space. b. Cut and remove a section of the 2" PVC vent line. c. Clean and prep area. d. Install a new 2" PVC DWV coupling. e. Install a longer piece of 2" SCH 40 PVC pipe to reconnect to the existing 2" PVC DWV 90 elbow. 22. Gas Line Addition a. The gas line for the new unit which is labeled #21 the gas stub out is on the opposite side of the unit stub in, roughly adding 12-15' of pipe and we will run pipe around the unit shelf. b. Unit labeled #1 has the compromised 90 we will have to disconnect and replace about 6-12 inches of pipe along with a 90 in addition of a new sediment trap as well. 23. Gas Line Checks a. Turned off the shutoff valves at the gas meter and gas riser. b. Installed a test pressure gauge on the outgoing gas line from the gas meter and pumped 15 psi of air into the lines. c. Monitored the gauge for changes for 30 mins and saw no change. d. Turned off all of the shutoff valves before each AC unit located on the roof and before each regulator.	0.0000	0.00

Authorized by: Ignacio Arizaga



Purchase Order COUNTY OF HIDALGO

PO# 892663

DATE: 02/06/2025

PAGE: 3 Of 3

PO TYPE:

VENDOR: 524034

REQ: 00510839

PHONE:

BUYER: SHERIFF'S LAW ENFORCEMENT FACILITY PO

EMAIL:

SHIP TO: HIDALGO COUNTY JAIL

701 EL CIBOLO RD
EDINBURG Tx 78539

AMSTAR INC
1211 PLEASANTON ROAD
SAN ANTONIO TX 78214

VENDOR ACCOUNT:

CONTACT: P EILENBERGER (956) 393-6023

SITE: HIDALGO COUNTY JAIL

CONTRACT: BUYBOARD JOC 660-21

SPECIAL INSTRUCTIONS:

VENDOR NOTES

1. Do not add to, or alter this Purchase Order. This Order is not renewable.
2. TAX EXEMPTION. This Purchase Order may be accepted in lieu of Exemption Certificate.
3. This Order is also placed F.O.B. Destination. Vendor must repay all shipping costs.
4. Invoice each Purchase Order singly. Original invoices are required customer copy may be accepted. Out number must appear on all invoices, bills of lading, and packages.
5. Payment will be made only for bona fide and full completed orders, unless otherwise attached.

QTY	UOM	DESCRIPTION	UNIT PRICE	AMOUNT
1.00	LOT	e. Turned off the two shutoff valves on the gas lines before each regulator located in the kitchen. f. Turned off the gas shutoff valve before the regulator located in the laundry room. g. Disconnected the unions from the two risers located in front of the left and right side of the building. h. Installed a test pressure gauge on each riser and pumped 15 psi of air into the lines. i. Monitored the gauge for any changes for 30 mins and saw no change. CO 24. Installation of new VCCX-IP board supply and program. 25. Connect computer to unit #13 26. Test and Balance Assumptions & Clarifications: 1. Work during normal business hours. 2. We exclude all unforeseen conditions. 3. Not responsible for existing freon leaks. 4. We exclude anything not specifically included in the proposal above. CO BOND	133,250.0000	133,250.00
1.00	EACH		2,999.0000	2,999.00
TOTAL:				136,249.00
REPORT ROAD HAZARDS 1-866-HCR-SAFE OR 1-866-427-7233 ***** For Hidalgo County use only 5-1100-423-21-280-003-0-430 136,249.00				

Authorized by: Ignacio Amigues