

To Melissa Gurka



Melissa,

The first invoice and grease pump haul off docs are attached.

It was deemed necessary to pump the grease trap immediately and inspect the tank to stop the leak as soon as possible due to the grease trap contents leaking into the interior of the facility.

Thank You,

Dale Butler

Facilities Director Williamson County 3101 SE Inner Loop Georgetown, TX 78626 512-943-1609

NOTICE OF CONFIDENTIALITY: The information in this communication is confidential and intended only for the exclusive use of the addressee. The copying, distribution, or other use of this communication by the addressee or any other person or entity is prohibited. If you have received this communication by mistake, please notify the sender immediately and destroy all forms of this communication.