# WILLIAMSON COUNTY, TEXAS CHANGE ORDER NUMBER: 1

1. CONTRACTOR: James Construction			Project:	22IFB57
2. Change Order Work Limits: Sta. 139+10.75 to	Sta.	205+27.24	Roadway:	CR 401 Reconstruction
3. Type of Change(on federal-aid non-exempt projects):	Minor	(Major/Minor)	CSJ Number:	
4. Reasons: 3G (3 Max In order of	of importa	nce - Primary first)		
5. Describe the work being revised:  3G. County Convenience. Compliance requirements of new I 79 TxDOT ROW to meet their requirements and revised some CR 401.				
Work to be performed in accordance with Items:	e attache	ed.		
7. New or revised plan sheet(s) are attached and numbered	d:	2,5,9,9L,9M,11,15,23	3,24,26B,37,147,149,1	65,168,169,231,232
8. New Special Provisions/Specifications to the contract are		d:	es ☑ N	0
9. New Special Provisions to Item N/A No. N/A , Special Specia			tached.	
Each signatory hereby warrants that each has the authority				
,		N. M. W		1
The contractor must sign the Change Order and, by doing so, agrees to waive any and all claims for additional compensation due to any and all other expenses; additional changes for time, overhead and profit; or loss of compensation as a result of this change.	Time E		mation must be  Days added o	
THE CONTRACTOR Date 9/1/2012	Amount	added by this ch	nange order:	\$13,315.52
Typed/Printed Name Toey Williams  Typed/Printed Title Division Manyer				
RECOMMENDED FOR EXECUTION:				
AAAA		County Commis	ssioner Precinct	Date Date
Project Manager Date	- A	PPROVED	a REQI	JEST APPROVAL
		County Commi	ssioner Precinct 2	2 Date
N/A Design Engineer Date	o A	PPROVED		JEST APPROVAL
a a mil				
MA MA		County Commis	ssioner Precinct :	B Date
Program Munager Date	_ A	PPROVED	□ REQI	JEST APPROVAL
Design Engineer's Seal:				
	_ A	County Commi	ssioner Precinct 4	Date JEST APPROVAL
124		Count	ty Judge	Date
	_ /	II FRUVED		

WILLIAMSON COUNTY, TEXAS							
TABLE A: Force A	CHANGE ORDER NUMBER: 1 Project # 22iFB57  [ABLE A: Force Account Work and Materials Placed into Stock						
	LABOR	HOURLY RATE		HOURLY RATE			
			"[				

		ORIGINAL + PREVIOUSLY REVISED (DEDUCT) NEW							
ITEM	DESCRIPTION	UNIT	UNIT PRICE	QUANTITY	ITEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUN/ UNDERRUN
316-6413	ASPH(AC-15P, HFRS-2P OR CRS-2P)	GAL	\$3.84	13,777.00	\$52,903.68	(491.00)	13,286.00	\$51,018.24	(\$1,885.44)
3076-6042	D-GR HMA TY-D SAC-B PG70-22	TON	\$126.47	6,083.00	\$769,317.01	(210.00)	5,873.00	\$742,758.31	(\$26,558.70
3076-6050	D-GR HMA TY-D SAC-B PG76-22	TON	\$170.00	0.00	\$0.00	210.00	210.00	\$35,700.00	\$35,700.00
3076-6066	TACK COAT	GAL	\$4.75	0.00	\$0.00	149.00	149.00	\$707.75	\$707.75
3085-6001	UNDERSEAL COURSE	GAL	\$6.85	0.00	\$0.00	491.00	491.00	\$3,363.35	\$3,363.35
999-WC02	SUBCONTRACTOR MARK-UP (5%)	DOL	\$1.00	0.00	\$0.00	1,988.56	1,988.56	\$1,988.56	\$1,988.56
									'
		L	L						
	TOTALS				\$822,220,69			\$835,538,21	\$13,315,52

## CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E
	1B. Other
Differing Site Conditions	2A. Dispute resolution (expense caused by conditions and/or resulting delay)
(unforeseeable)	2B. Unavailable material
	2C. New development (conditions changing after PS&E completed)
	2D. Environmental remediation
•	2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9)
	2F. Site conditions altered by an act of nature
	2G. Unadjusted utility (unforeseeable)
	2H. Unacquired Right-of-Way (unforeseeable)
	2l. Additional safety needs (unforeseeable)
	2J. Other
County Convenience	3A. Dispute resolution (not resulting from error in plans or differing site conditions)
	3B. Public relations improvement
	3C. Implementation of a Value Engineering finding
	3D. Achievement of an early project completion
	3E. Reduction of future maintenance
	3F. Additional work desired by the County
	3G. Compliance requirements of new laws and/or policies
	3H. Cost savings opportunity discovered during construction
	3I. Implementation of improved technology or better process
	3J. Price adjustment on finished work (price reduced in exchange for acceptance)
	3K. Addition of stock account or material supplied by state provision
	3L. Revising safety work/measures desired by the County
	3M. Other
Third Party Accommodation	4A. Failure of a third party to meet commitment
	4B. Third party requested work
	4C. Compliance requirements of new laws and/or policies (impacting third party)
	4D. Other
F. O	5A Contractor consists with a sharp of the treffic control when
5. Contractor Convenience	5A. Contractor exercises option to change the traffic control plan
28	5B. Contractor requested change in the sequence and/or method of work
	5C. Payment for Partnering workshop
	5D. Additional safety work/measures desired by the contractor
	5E. Other
6. Untimely ROW/Utilities	6A. Right-of-Way not clear (third party responsibility for ROW)
o. Onumely NOVWoundes	6B. Right-of-Way not clear (County responsibility for ROW)
	6C. Utilities not clear
	6D. Other
	Ob. Outer

### **QUOTE FOR**



A CRH COMPANY

### Texas Materials Group, Inc.

1320 Arrow Point Drive, Suite 600

Cedar Park, TX 78613

Contact

David Reese

E-Mail:

David.Reese@texasmaterials.com

Location:

Plant:

Telephone No:

512-633-5680

Date:

8/4/2022

Project:

CR401

Project #: County: 22IFB57 Williamson

Bid Date:

3/9/2022

CO#2 QUOTE

\*\*REVISED deleting TY-B Adjustment

ITEM	DESCRIPTION	QUANTITY	UNIT	UNIT PRICE	AMOUNT	
316-6413	ASPH(AC-15P, HFRS-2P OR CRS-2P)	-491.00	GAL	\$3.84	-1,885.44 -1,865.8	
3076-6042	D-GR HMA TY-D SAC-B PG70-22	-210.00	TON	\$126.47 <b>125.80</b>	-26,558,70	
3076-6050	D-GR HMA TY-D SAC-B PG76-22	210.00	TON	170.00	-	
3085-6001	UNDERSEAL COURSE	491.00	GAL	6.85	3,363.3	
3076-6066	TACK COAT	149.00	GAL	4.75		

#### GRAND TOTAL

#### NOTES:

\*\*\*Terms and conditions of subcontract agreement apply.

\*\*\*No mobilizations added for this work.

\*\*\*This quote expires if not accepted in 30 days.

5% Mark-up \$1,988.56 Total: \$13,315.52

3,363.35 + 707.75

\$39,771,10

+ 1,988.56 5% Sub Mark-up

QUOTE ACCEPTED BY-	
NAME:	DATE:
SIGNATURE:	COMPANY:

#### **Williamson County Road Bond Program**

## CR 401 Reconstruction Williamson County Project No. 22IFB57

### Change Order No. 1 Reason for Change

This Change Order revises the pavement section within the US 79 TxDOT ROW to meet the requirements of TxDOT. TxDOT also made some adjustments to the signal phasing/timing for the new intersection at proposed US 79 and CR 401.

The following new items will be added by this Change Order.

		r	
ITEM	DESCRIPTION	QUANTITY	UNIT
3076-6050	D-GR HMA TY-D SAC-B PG76-22	210.00	TON
3076-6066	TACK COAT	149.00	GAL
3085-6001	UNDERSEAL COURSE	491.00	GAL
999-WC02	SUBCONTRACTOR MARK-UP (5%)	1,988.56	DOL

This Change Order results in an increase of \$13,315.52 to the Contract amount, for an adjusted Contract total of \$12,686,516.46. The original Contract amount was \$12,673,200.94. As a result of this and all Change Orders to-date, \$13,315.52 has been added to the Contract, resulting in a .11% net increase to the overall Contract cost. As a result of this Change Order, zero (0) days will be added to the contract.

#### **HNTB** Corporation

Oscar Salazar-Bueno, P.E.