

# WILLIAMSON COUNTY, TEXAS CHANGE ORDER NUMBER: 9

1. CONTRACTOR: J.D. Ramming Paving Co., LTD.			Project:	10WC817
Change Order Work Limits: Sta537+93 to	Sta.	766+27	Roadway:	US 79 Section 3
3. Type of Change(on federal-aid non-exempt projects):	Minor	(Major/Minor)	CSJ Number:	0204-02-027, etc
4. Reasons: 3E, 2E (3 Max In order o	of importar	nce - Primary first)	, rumber.	020102 021, 010
5. Describe the work being revised:				
3E: County Convenience. Reduction of future maintenance. pavement issues to turn into problems that require repair prior to beyond what the Contractor could have anticipated during the lettin the existing pavement be repaired before placing new HMAC, in the future. 2E. Differing Site Conditions (unforeseeable). Mis 9). During the layout for level-up paving operations, it was discovexceed the quantity needed to address field conditions.	continuing ting proces n an effort scellaneo	the construction of ss. TxDOT is requited to reduce reflectives us difference in s	on the proposed eating that cracks and cracking and proite conditions (u	astbound lanes, far and pavement failures event likely repairs in anforeseeable)(Item
	1 and 712			
7. New or revised plan sheet(s) are attached and numbered	<b>1</b> :	N/A	- No	
New Special Provisions to the contract are attached:		☐ Yes	✓ No	
9. New Special Provisions to Item N/A No. N/A Sp				ched.
Each signatory hereby warrants that each has the authority	to execut	e this Change Or	rder (CO).	
The contractor must sign the Change Order and, by doing so, agrees to waive any and all claims for additional compensation due to any and all other		following Infor		
expenses; additional changes for time, overhead and profit; or loss of compensation as a result of this change.	Time E	xt. #: N/A	Days added o	on this CO: N/A
THE CONTRACTOR Date 9/20/2011	Amoun	t added by this ch	nange order:	(\$14,350.00)
ву () ) 2				
Typed/Printed Name FDD TEKNINEY				
Typed/Printed Name FDD PEKUINEY  Typed/Printed Title FRESET MGR				
RECOMMENDED FOR EXECUTION:				
/2 = 1				
Project Manager Date Construction Observer	□ API	PROVED	ssioner Precinct  REQUE	1 Date EST APPROVAL
			ssioner Precinct	
N/A Design Engineer Date	⊔ AP	PROVED	☐ REQUE	EST APPROVAL
in All al 1		County Commi	ssioner Precinct	3 Date
Program Manager Date	☐ AP	PROVED		EST APPROVAL
Design Engineer's Seal:				
N/A	□ AP	County Commi PROVED	ssioner Precinct	4 Date EST APPROVAL
Z.	2	- 1		10-05-20
	APPRO		ty Judge	Date

# WILLIAMSON COUNTY, TEXAS

CHANGE ORDER NUMBER: 9

Project #

TABLE A: Force Account Work and Materials Placed into Stock

LABOR	HOURLY RATE		HOLIRI Y RATE

				ORIGINAL	ORIGINAL + PREVIOUSLY REVISED	ADD or (DEDUCT)	z	NEW	
ITEM	DESCRIPTION	UNIT	UNIT PRICE	QUANTITY	ITEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUN
341-2011	D-GR HMA (QCQA) TY-8 PG64-22	TON	\$55.00	43,303.91	\$2,381,715.05	(1,200.00)	42,103.91	\$2,315,715.05	(\$66,000.00
351-2013	FLEXIBLE PAVEMENT STRUCTURE REPAIR (4")	SY	\$68.00	0.00	\$0.00		700.00	П	\$47,600.00
712-2004	JTICRCK SEAL (RUBBER - ASPHALT)	LF	\$1.35	00.0	\$0.00	•	3,000.00		\$4,050.00
A CONTRACTOR OF THE PERSON NAMED IN COLUMN									
TOTAL STREET,		_							
		_							
							_		
TOTAL PROPERTY AND ADDRESS OF THE PARTY AND AD	SIATOT				\$2.381.715.05		45 803 94	£2 3£7 3£5 0£	1614 350 001

## CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E
1. Design Error of Offission	1B. Other
	10. Other
2. Differing Site Conditions	2A. Dispute resolution (expense caused by conditions and/or resulting delay)
(unforeseeable)	2B. Unavailable material
	2C. New development (conditions changing after PS&E completed)
	2D. Environmental remediation
	2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9)
	2F. Site conditions altered by an act of nature
	2G. Unadjusted utility (unforeseeable)
	2H. Unacquired Right-of-Way (unforeseeable)
	21. Additional safety needs (unforeseeable)
	2J. Other
3. County Convenience	3A. Dispute resolution (not resulting from error in plans or differing site conditions)
	3B. Public relations improvement
	3C. Implementation of a Value Engineering finding
	3D. Achievement of an early project completion
	3E. Reduction of future maintenance
ll .	3F. Additional work desired by the County
	3G. Compliance requirements of new laws and/or policies
	3H. Cost savings opportunity discovered during construction
1	31. Implementation of improved technology or better process
	3J. Price adjustment on finished work (price reduced in exchange for acceptance)
	3K. Addition of stock account or material supplied by state provision
	3L. Revising safety work/measures desired by the County
	3M. Other
4. Third Party Accommodation	4A. Failure of a third party to meet commitment
l	4B. Third party requested work
1	4C. Compliance requirements of new laws and/or policies (impacting third party)
	4D. Other
	3000 00 00 00 00 00 00 00 00 00 00 00 00
Contractor Convenience	5A. Contractor exercises option to change the traffic control plan
li .	5B. Contractor requested change in the sequence and/or method of work
	5C. Payment for Partnering workshop
N .	5D. Additional safety work/measures desired by the contractor
	5E. Other
6. Untimely ROW/Utilities	6A. Right-of-Way not clear (third party responsibility for ROW)
1	6B. Right-of-Way not clear (County responsibility for ROW)
	6C. Utilities not clear
	6D. Other

### Williamson County Road Bond Program

### US 79 Section 3 Williamson County Project No. 10WC817

Change Order No. 9

### Reason for Change

This Change Order compensates the Contractor for sealing cracks in the existing roadway and for making repairs in the existing roadway in areas where the pavement has failed. The extreme heat and drought appears to have caused minor pavement issues to turn into problems that require repair prior to continuing the construction of the eastbound lanes beyond what the Contractor could have expected during the letting process. These problems are also evident on the surrounding roadways. TxDOT is requiring that these areas be sealed and/or repaired prior to the placement of level-up HMAC and PFC surface course on top of the existing pavement in order to reduce reflective cracking and prevent maintenance problems in the future. This Change Order adds the two new pay items to the Contract in order to make these pay adjustments.

During the layout for level-up paving operations, it was discovered that the Type B HMAC quantity in the Contract appears to exceed the quantity needed to address field conditions. This Change Order reduces the existing Contract item by 1,200 Tons.

Following is a summary of the new items required for this Change Order:

ITEM	DESCRIPTION	QTY	UNIT
351-2013	FLEXIBLE PAVEMENT STRUCTURE REPAIR (4")	700	SY
712-2004	JT/CRCK SEAL (RUBBER – ASPHALT)	3000	LF

This Change Order results in a net decrease of \$14,350.00 to the Contract amount, for an adjusted total Contract amount of \$11,669,294.47. The original Contract amount was \$11,500,547.03. As a result of this and all Change Orders to date, \$168,747.44 has been added to the Contract, resulting in a 1.5% net increase in the Contract Cost. No additional days will be added to or deducted from the Contract as a result of this Change Order.

### RABA-KISTNER INFRASTRUCTURE

Ron Seal, P.E.