
Received

Rec WILLIAMSON COUNTY, TEXAS CHANGE ORDER NUMBER


CHANGE ORDER NUMBER: 3 HNTB Corporation



. CONTRACTOR:	Chasco Co	nstructor	'S	Rour	d Rock	Pro	ject:	1604-075
Change Order W	ork Limits:	Sta.	99+40	_ to Sta.	211+00	Ros	idway:	CR 110 South
. Type of Change(1	non-exemp	t projects):	Mino	r_(Major/Mino		nber:	
Reasons:	3E & 3H		(3 Max In o	rder of impor	tance - Primary	1-2-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		
Describe the work E: County Convenion Upplements the Type Upstitutes single-slop Work to be perform New or revised properties of the Special Propert	ence. Reduction of the second	ion of futu x with Type cost saving ncrete barri ardance with are attach ifications to m_164_ N	11 (Bermud gs opportuni er with low protein Items: ed and num to the contra oWC03S	a), and adds ty discovere ofile concrete see attac bered: ct are attach pecial Specific ority to exec	additional concrete during constants between the barrier (LPCB) and a second se	Yes E are attached.	Change C	ent items at utility Order also
ne contractor must sign ti ly and all claims for addit penses; additional chang impensation as a result c	ional compensations for time, overf	on due to any	and all other	aive	he following in			provided n this CO: 0
THE CONTRACTO By While Typed/Printed Nan Typed/Printed Title	ostoline Cha	-JR ules I (1-28-20 Slace I	17	nt added by th			\$31,812.74
ECOMMENDED F	OR EXECUT	ION:			0 1 0	1-1-1-1-	les almost 1	Date
Gram B. Proj	ect Manager	F: 1	1/29/1 Date	2 🗆	APPROVED	mmissioner F		EST APPROVAL
				-	County Cor	nmissioner P	recinct 2	Date
Des	N/A ign Engineer		Date		APPROVED		REQU	EST APPROVAL
nilla	/	/	./		County Cor	nmissioner P	recinct 3	Date
Prog	ram Managei	11/2	Date	_ 🗆	APPROVED			EST APPROVAL
esign Engineer's S	eal:			-	County Cor	nmissioner P	recinct 4	Date
coign Engineer a c								
odigit Engineer s					APPROVED		REQU	EST APPROVAL
odign Engineer e	see attached	pages		Jan.	APPROVED	91	REQU	12-15-1017

Received

WILLIAMSON COUNTY, TEXAS



see attached pages

County Judge

APPROVED

Date

WILLIAMSON COUNTY, TEXAS

CHANGE ORDER NUMBER:	3	Project #	1604-075

TABLE A: Force Account Work and Materials Placed into Stock

LABOR	HOURLY RATE		HOURLY RATE	

TABLE B: Contract Items:

				ORIGINAL + PRE	VIOUSLY REVISED	ADD or (DEDUCT)		NEW	
ITEM	DESCRIPTION	UNIT	UNIT PRICE	QUANTITY	ITEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUN/ UNDERRUN
0164-WC11	SEEDING FOR EROSION CONTROL (TYPE 11)	SY	\$0.09	0.00	\$0.00	57,886.00	57,886.00	\$5,209.74	\$5,209.74
0341-6027	D-GR HMA TY-C SAC-B PG 70-22	TON	\$75.00	6,909.00	\$518,175.00	(6,909.00)	0.00	\$0.00	(\$518,175.00)
0341-6042	D-GR HMA TY-D SAC-B PG 70-22	TON	\$77.00	0.00	\$0.00	6,909.00	6,909.00	\$531,993.00	\$531,993.00
0464-6001	RC PIPE (CLIII)(12 IN)	LF	\$50.00	0.00	\$0.00	44.00	44.00	\$2,200.00	\$2,200.00
0464-6003	RC PIPE (CLIII)(18 IN)	LF	\$86.00	50.00	\$4,300.00	46.00	96.00	\$8,256.00	\$3,956.00
0467-6326	SET (TYII)(12 IN)(RCP)(6:1)(P)	EA	\$800.00	0.00	\$0.00	2.00	2.00	\$1,600.00	\$1,600.00
0467-6363	SET (TYII)(18 IN)(RCP)(6:1)(P)	EA	\$1,500.00	0.00	\$0.00	12.00	12.00	\$18,000.00	\$18,000.00
0512-6001	PORT CTB (FUR & INSTL)(SGL SLOPE)(TY 1)	LF	\$66.00	881.00	\$58,146.00	(881.00)	0.00	\$0.00	(\$58,146.00)
0512-6009	PORT CTB (FUR & INSTL)(LOW PROFILE)(TY 1)	LF	\$65.00	0.00	\$0.00	881.00	881.00	\$57,265.00	\$57,265.00
0512-6010	PORT CTB (FUR & INSTL)(LOW PROFILE)(TY 2)	LF	\$65.00	0.00	\$0.00	80.00	80.00	\$5,200.00	\$5,200.00
0512-6025	PORT CTB (MOVE)(SGL SLP)(TY 1)	LF	\$9.00	1,000.00	\$9,000.00	(1,000.00)	0.00	\$0.00	(\$9,000.00)
0512-6033	PORT CTB (MOVE)(LOW PROFILE)(TY 1)	LF	\$9.00	0.00	\$0.00	1,000.00	1,000.00	\$9,000.00	\$9,000.00
0512-6034	PORT CTB (MOVE)(LOW PROFILE)(TY 2)	LF	\$9.00	0.00	\$0.00	80.00	80.00	\$720.00	\$720.00
0512-6049	PORT CTB (REMOVE)(SGL SLP)(TY 1)	LF	\$13.00	881.00	\$11,453.00	(881.00)	0.00	\$0.00	(\$11,453.00)
0512-6057	PORT CTB (REMOVE)(LOW PROFILE)(TY 1)	LF	\$13.00	0.00	\$0.00	881.00	881.00	\$11,453.00	\$11,453.00
0512-6058	PORT CTB (REMOVE)(LOW PROFILE)(TY 2)	LF	\$13.00	0.00	\$0.00	80.00	80.00	\$1,040.00	\$1,040.00
0545-6001	CRASH CUSH ATTEN (INSTALL)	EA	\$9,000.00	2.00	\$18,000.00	(2.00)	0.00	\$0.00	(\$18,000.00)
0545-6005	CRASH CUSH ATTEN (REMOVE)	EA	\$525.00	2.00	\$1,050.00	(2.00)	0.00	\$0.00	(\$1,050.00)
	TOTALS				\$620,124.00			\$651,936.74	\$31,812.74

CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E 1B. Other
Differing Site Conditions (unforeseeable)	2A. Dispute resolution (expense caused by conditions and/or resulting delay) 2B. Unavailable material 2C. New development (conditions changing after PS&E completed) 2D. Environmental remediation 2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9) 2F. Site conditions altered by an act of nature 2G. Unadjusted utility (unforeseeable) 2H. Unacquired Right-of-Way (unforeseeable) 2I. Additional safety needs (unforeseeable) 2J. Other
3. County Convenience	3A. Dispute resolution (not resulting from error in plans or differing site conditions) 3B. Public relations improvement 3C. Implementation of a Value Engineering finding 3D. Achievement of an early project completion 3E. Reduction of future maintenance 3F. Additional work desired by the County 3G. Compliance requirements of new laws and/or policies 3H. Cost savings opportunity discovered during construction 3I. Implementation of improved technology or better process 3J. Price adjustment on finished work (price reduced in exchange for acceptance) 3K. Addition of stock account or material supplied by state provision 3L. Revising safety work/measures desired by the County 3M. Other
4. Third Party Accommodation	 4A. Failure of a third party to meet commitment 4B. Third party requested work 4C. Compliance requirements of new laws and/or policies (impacting third party) 4D. Other
5. Contractor Convenience	 5A. Contractor exercises option to change the traffic control plan 5B. Contractor requested change in the sequence and/or method of work 5C. Payment for Partnering workshop 5D. Additional safety work/measures desired by the contractor 5E. Other
6. Untimely ROW/Utilities	 6A. Right-of-Way not clear (third party responsibility for ROW) 6B. Right-of-Way not clear (County responsibility for ROW) 6C. Utilities not clear 6D. Other

Williamson County Road Bond Program

County Road 110 South Williamson County Project No. 1604-075

Change Order No. 3

Reason for Change

This Change Order substitutes the Type C surface hot mix asphalt (HMAC) with Type D HMAC. This provides an improved finished product and aligns with recent County direction utilizing Type D HMAC. The Type 4 seed mixture is also being supplemented with Type 11 seed which is Bermuda grass. This seed will aid in vegetation establishment.

Items for 12" concrete pipe (RCP), 12" Type II RCP safety end treatment (SET's), and 18" Type II RCP SET's are added to the contract due to the need for drainage structures at power poles. Due to the narrow right-of-way (ROW) width, utility poles were set in the ditch backslope, requiring storm water to be put in pipes at the poles. This was necessary to retain pole stability.

This Change Order also substitutes the Portable Single Slope Concrete Traffic Barrier (SSCB) with Low Profile Concrete Traffic Barrier (LPCB). The posted speed limit is 45 mph, which is the maximum speed limit allowed for use of LPCB. This will provide cost savings to the project and expedite construction.

The following summarizes the new Contract items required for this Change Order. The unit rates submitted by the Contractor are consistent with the TxDOT average low bid unit prices.

ITEM	DESCRIPTION	QTY	UNIT
0164-WC11	SEEDING FOR EROSN CTL (TY 11)	57,886	SY
0341-6042	D-GR HMA (TY-D) SAC-B PG 70-22	6,877	TON
0464-6001	RC PIPE (CL III)(12 IN)	44	LF
0467-6326	SET (TY II)(12 IN)(RCP)(6:1)(P)	2	EA
0467-6363	SET (TY II)(18 IN)(RCP)(6:1)(P)	12	EA
0512-6009	PORT CTB (FURN & INSTL)(LOW PROFILE)(TY 1)	881	LF
0512-6010	PORT CTB (FURN & INSTL)(LOW PROFILE)(TY 2)	80	LF
0512-6033	PORT CTB (MOVE)(LOW PROFILE)(TY 1)	1000	LF
0512-6034	PORT CTB (MOVE)(LOW PROFILE)(TY 2)	80	LF

0512-6057	PORT CTB (REMOVE)(LOW PROFILE)(TY 1)	881	LF
0512-6058	PORT CTB (REMOVE)(LOW PROFILE)(TY 2)	80	LF

Plan sheets 80A and 80B are added.

This Change Order results in a net increase of \$31,812.74 to the Contract amount, for an adjusted Contract total of \$11,253,404.45. The original Contract amount was \$11,224,589.02. Because of this and all Change Orders to-date, \$28,815.43 has been added to the Contract, resulting in a 0.3% net increase in the Contract cost. No additional days will be added to or deducted from the Contract as a result of this Change Order.

HNTB Corporation

James Klotz, P.E.



County Project No: 1604-075 CR110S

Chasco Project No: 16169

Engineer Project No: 4862

Chasco CP No:	09 - MODIFIED SEED TY 4 WITH UNHULLED BERMUDA	10/19/17
Owner PR No:		15/11/
Description:	REVISED SEEDING SPEC PER SUBMITTAL #60	

BASED ON DOCUMENTS: SUBMITTAL # 60

NO NO	TECH SPEC	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL
10	164-WC01	SEEDING FOR EROSION CONTROL (TY 4)	-58,874	SY	\$0.16	(\$9,410.84)

	164-WC11	CHANGE ORDER - NEW ITEMS	57,886		. 2516=	5,209,74
New	164-XXXX	MODIFIED SEEDING - TYPE 4 PLUS 10 Lbs UNHULLED - BERMUDA SEEDING FOR EROSION CON TROI	58,874	SY	\$0.25 09	\$14,718.50
		TOTAL (y 11) - Bermuda				\$6,298.66

5, 209.74



County Project No: 1604-075 CR110S

Chasco Project No: 16169 Engineer Project No: 4862

Chasco CP No:	08 - TYPE D HMAC	10/31/17
Owner PR No:		
Description:	USE TYPE D IN LIUE OF TYPE C ON FINISH COURSE	

BASED ON DOCUMENTS: AS REQUESTED AT PAVING PRECON

NO NO	TECH SPEC	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL
22	341-6027	D-GR HMA TY-C SAC-B PG70-22	-6,877	TON	\$75.00	(\$515,775.00)
		TOTAL	- 6,909			(\$515,775.00

(518,175.00)

CHANGE ORDER - NEW ITEMS

NEW ITEM 341-	D-GR HMA TY-D 5AC -B PG 70-22	6,877	TON	\$77.00	\$529,529.00
	TOTAL	6,909			\$529,529.00

551,945.00

TOTAL

13,818



County Project No: 1604-075 CR110S

Chasco Project No: 16169 Engineer Project No: 4862

Chasco CP No:	07 - 12" & 18" RCP & S.E.T.'S		10/19/17
Owner PR No:			
Description:	ADD 12" RCP AND S.E.T'S & 18" RCP & S.E.T'S	8.9	

BASED ON DOCUMENTS: RFI 21 & 24

New New New

BID ITEM NO	TECH SPEC	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL
CP 7	464-6001	RC PIPE (CL III)(12 IN) - DRIVEWAY 2-2	44	LF	\$50.00	\$2,200.00
	1	SET (TY II) (12 IN) (RCP) (6: 1) (P) - DRIVEWAY 2-2	2	EA	\$800.00	\$1,600.00
CP7	467-6363	SET (TY II) (18 IN) (RCP) (6: 1) (P) - RFI 24 POWER POLES	12	EA	\$1,500.00	\$18,000.00
46	464-6003	RC PIPE (CL III)(18 IN) - RFI 24 POWER POLES	0 26 46	LF	\$86.00	\$8,266.00 39
			·			\$0.00
		TOTAL				\$30,056.00

TOTAL \$30,056.00 25,756




County Project No: 1604-075 CR110S

Chasco Project No: 16169 Engineer Project No: 4862

Chasco CP No:	03 - LOW PROFILE BARRIERS	10/19/17
Owner PR No:		
Description:	Alternate price to use low profile barriers in Ileu of single slope. Requested by HNTB,	

BASED ON DOCUMENTS: SUBMITTAL 54


NO NO	TECH SPEC	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL
74	512-6001	PORT CTB (FUR & INST)(SGL SLOPE)(TY 1)	-881	LF	\$66.00	(\$58,146.00)
75	512-6025	PORT CTB (MOVE)(SGL SLP)(TY 1)	-1,000	LF	\$9.00	(\$9,000.00)
76	512-6049	PORT CTB (REMOVE)(SGL SLP)(TY 1)	-881	LF	\$13.00	(\$11,453.00)
89	545-6001	CRASH CUSH ATTEN (INSTL)	-2	EA	\$9,000.00	(\$18,000.00)
90	545-6005	CRASH CUSH ATTEN (REMOVE)	-2	EA	\$525.00	(\$1,050.00)
		CHANGE ORDER - NEW ITEMS				
ew	512-6009	PORT CTB (FUR & INST)(LOW PROFILE)(TY 1)	881	LF	\$65.00	\$57,265.00
ew	5126033	PORT CTB (MOVE)LOW PROFILE)(TY 1)	1,000	LF	\$9.00	\$9,000.00
QW	513-4057	PORT CTB (REMOVE)(LOW PROFILE)(TY 1)	881	LF	\$13.00	\$11,453.00
ew 5	12-6010	PORT CTB (FUR & INST)(LOW PROFILE)(TY 2).SLOPED ENDS	80	LF	\$65.00	\$5,200.00
2W 51	1-6034	PORT CTB (MOVE)LOW PROFILE)(TY 2), SLOPED ENDS	80	LF	\$9.00	\$720.00
2W 512	6058	PORT CTB (REMOVE)(LOW PROFILE)(TY 2) SLOPED ENDS	80	LF	\$13,00	\$1,040.00
		TOTAL				(\$12,971.00



shall be Galvanized.

DIST

SHEET NO 86-A



(#5) Bar

DIST

SHEET NO.

80-B

and do not require formal bends.

for any purpose what is resulting from its

9 6

is mode results

warranty of any kind nats or for incorrect

Por

Act".

Engineering Practice of this standard to a

the "Texas f

by the

DISCLAIMER: The use of this standard is governed IXDOI assumes no responsibility for t