WILLIAMSON COUNTY, TEXAS CHANGE ORDER NUMBER: 9

1. CONTRACTOR: DeNucci Constructors		Project:	Forest North Phase III
Change Order Work Limits: Sta. VARIOUS to Sta.	LOCATIONS	Roadway:	Rdwy Improvements
3. Type of Change(on federal-aid non-exempt projects): Mine	or (Major/Minor)	CSJ Number:	3866
4. Reasons: 3F (3 Max In order of impor	rtance - Primary first)	Number.	3800
5. Describe the work being revised:			
3F: Additional work desired by the County. County Convenience. Toverrun of Contract quantities on the project paid for by Williamson Count accounted for in the original plans. Item 400-WC01 is being added to pavement adjacent to the pipe trench repairs	nty. The overruns were a	result of addres	sing field conditions
See Attac	ched		
7. New or revised plan sheet(s) are attached and numbered:	N/A		
New Special Provisions/Specifications to the contract are attact		☑ No)
9. New Special Provisions to Item <u>N/A</u> No. <u>N/A</u> , Special Spec			
Each signatory hereby warrants that each has the authority to exec	cute this Change Order	(CO).	
The contractor must sign the Change Order and, by doing so, agrees to waive	he following informa	tion must be j	provided
nny and all claims for additional compensation due to any and all other	Ext. #: N/A	Days added or	this CO: 0
THE CONTRACTOR Date 1-6-22 Amou	unt added by this chan	ge order:	\$182,754.00
By Sarand Murrori			
Typed/Printed Name AARON DENUCCI			
Typed/Printed Title PROJECT ENGINEER			
RECOMMENDED FOR EXECUTION:			
	County Commissio	ner Precinct 1	Date
1/6/21 Date	APPROVED		EST APPROVAL
-	County Commissio	ner Precinct 2	Date
N/A Design Engineer Date	APPROVED		EST APPROVAL
M 1 11	County Commissio	nor Procinct 2	Date
Program I lanager Date	APPROVED		EST APPROVAL
esign Engineer's Sea.			
	County Commissio	ner Precinct 4	Date
	APPROVED	□ REQU	EST APPROVAL
Bill Gravell	(Jan 19, 202
g	County Ju APPROVED	ıdge	Date

WILLIAMSON COUNTY, TEXAS

CHANGE ORDER NUMBER:

0

TABLE A: Force Account Work and Materials Placed into Stock

Project # st North Phase III

ABOR	HOURLY RATE	
		HOURET RAIE

TABLE B: Contract Items;

				ORIGINAL + PREVIOUSLY REVISED	IOUSLY REVISED	ADD or (DEDUCT)	2	NEW	
ITEM	DESCRIPTION	TIND	UNIT PRICE	QUANTITY	ITEM COST	QUANTITY	QUANTITY	ITEM COST	OVERRUN/ UNDERRUN
462-6004	CONC BOX CULV (4 FT X 3 FT)	5	\$460.00	92.00	\$42,320.00	36.00	128.00	\$58.880.00	\$16.550.00
465-6002	MANH (COMPL)(PRM)(48IN)	EA	\$4,200.00	2.00	\$8,400.00	1.00	3.00	\$12.600.00	\$4.200.00
465-6074	INLET (COMPL)(PSL)(RC)(SFTX5FT)	EA	\$5,600.00	2.00	\$11,200.00	1.00	3.00	\$16,800.00	\$5.600.00
465-6127	INLET (COMPL)(PSL)(FG)(4FT X 4FT-3FT X 3FT)	EA	\$4,400.00	10.00	\$44,000.00	2.00	12.00	\$52.800.00	\$8.800.00
467-6363	SET (TY II) (18 IN) (RCP) (6: 1) (P)	EA	\$3,000.00	13.00	\$39,000.00	12.00	25.00	\$75.000.00	\$36,000.00
467-6390	SET (TY II) (24 IN) (RCP) (4: 1) (C)	EA	\$3,500.00	1.00	\$3.500.00	1.00	2.00	87 non no	\$3 500 00
496-6007	REMOV STR (PIPE)	5	\$14.00	00.629	\$9,506.00	234.00	913.00	\$12.782.00	\$3.276.00
560-6001	MAILBOX INSTALL-S (TWG-POST) TY 1	Æ	\$400.00	19.00	\$7,600.00	7.00	26.00	\$10.400.00	\$2.800.00
752-6005	TREE REMOVAL (4" - 12" DIA)	EA	\$600.00	10.00	\$6,000.00	71.00	81.00	\$48.600.00	\$42,600.00
752-6006	TREE REMOVAL (12" - 18" DIA)	EA	\$1,000.00	9.00	\$9,000.00	9.00	18.00	\$18,000.00	\$9.000.00
752-6007	TREE REMOVAL (18" - 24" DIA)	EA	\$1,400.00	3.00	\$4,200.00	9.00	12.00	\$16,800.00	\$12,600.00
701S-E	WOOD FENCE	4	\$28.00	808.00	\$22,624.00	11.00	819.00	\$22,932.00	\$308.00
WC9007	IRRIGATION SYSTEM CAPPING	EA	\$125.00	33.00	\$4,125.00	38.00	71.00	\$8,875.00	\$4,750.00
400-WC01	CUT & RESTORE PAV (ADDED WIDTH)	SY	\$45.00	0.00	\$0.00	728.00	728.00	\$32,760.00	\$32,760.00
	TOTALS	rs			\$211.475.00			\$394 229 00	\$182.754.00

Williamson County Road Bond Program

Forest North Drainage Phase 3 Williamson County Project No. 3866

Change Order No. 9

Reason for Change

This Change Order provides the interim balancing for the overrun of Contract quantities on the project paid for by Williamson County. The overruns were a result of addressing field conditions not accounted for in the original plans.

Explanation of overruns:

Item 462-6002 CONC BOX CULV (4FT X 3FT) – The box culvert was lengthened to reduce the length of an open drainage channel located between two residences.

Item 467-6363 SET (TY II)(18IN)(RCP)(6:1)(P) – Sloped end treatments were changed to 6:1 slopes from 4:1 slopes. The reduction in quantity for the 4:1 SET's will be documented in a future change order.

Item 400-WC01 CUT & RESTORE PAV (ADDED WIDTH) – This item is being added to compensate the Contractor for repairs to the existing pavement adjacent to the pipe trench repairs. The pavement was in such poor condition that the pavement was damaged during routine pipe installation procedures at no fault of the contractor. The additional width was repaired during the trench repair operation.

The following new items will be added by this Change Order.

ITEM	DESCRIPTION	QUANTITY	UNIT
400-WC01	CUT & RESTORE PAV (ADDED WIDTH)	728.00	SY

This Change Order results in a net increase of \$182,754.00 to the Contract amount, for an adjusted Contract total of \$5,103,631.74. The original Contract amount was \$4,793,058.15. As a result of this and all Change Orders to-date, \$310,573.59 has been added to the Contract, resulting in a 6.48% net increase in the overall Contract cost. No time will be added to the Contract for this Change Order.

HNTB Corporation

Oscar Salazar-Bueno, P.E.

CHANGE ORDER REASON(S) CODE CHART

Design Error or Omission	1A. Incorrect PS&E
	1B. Other
2. Differing Site Conditions	2A. Dispute resolution (expense caused by conditions and/or resulting delay)
(unforeseeable)	2B. Unavailable material
	2C. New development (conditions changing after PS&E completed)
	2D. Environmental remediation
	2E. Miscellaneous difference in site conditions (unforeseeable)(Item 9)
	2F. Site conditions altered by an act of nature
	2G. Unadjusted utility (unforeseeable)
	2H. Unacquired Right-of-Way (unforeseeable)
	2I. Additional safety needs (unforeseeable)
	2J. Other
3. County Convenience	3A. Dispute resolution (not resulting from error in plans or differing site conditions)
	3B. Public relations improvement
	3C. Implementation of a Value Engineering finding
	3D. Achievement of an early project completion
	3E. Reduction of future maintenance
	3F. Additional work desired by the County
	3G. Compliance requirements of new laws and/or policies
	3H. Cost savings opportunity discovered during construction
	3I. Implementation of improved technology or better process
	3J. Price adjustment on finished work (price reduced in exchange for acceptance)
	3K. Addition of stock account or material supplied by state provision
	3L. Revising safety work/measures desired by the County
	3M. Other
4. Third Party Accommodation	4A. Failure of a third party to meet commitment
	4B. Third party requested work
	4C. Compliance requirements of new laws and/or policies (impacting third party)
	4D. Other
5. Contractor Convenience	5A. Contractor exercises option to change the traffic control plan
	5B. Contractor requested change in the sequence and/or method of work
	5C. Payment for Partnering workshop
	5D. Additional safety work/measures desired by the contractor
	5E. Other
6. Untimely ROW/Utilities	6A. Right-of-Way not clear (third party responsibility for ROW)
	6B. Right-of-Way not clear (County responsibility for ROW)
	6C. Utilities not clear
	6D. Other

Eddie R. Church

From:

Clayton Weber

Sent:

Monday, December 20, 2021 4:11 PM

To:

Aaron DeNucci

Cc:

Bruce Thurin; 34275_RB_ForestNorthDrainage; Eddie R. Church

Subject:

Forest North trench repairs

We agree to pay \$32,760.00 for the additional width of trench repair.

This is for 3000 LF of repair at an added with of 2.0 ft. We only measured trenches that were over width per the City and County cut and restore pavement details.

3000 LF x 2.0 ft = 6000 SF divided by 9 = 667.00 SY x \$45.00 = \$30015.00. Plus 61.00 SY x \$45.00 = \$2745.00 repair on StillForest, for a total additional payout of \$32,760.00.

A bid item will be added to the contract for this compensation. Let me know of any questions or need to discuss further.

Clayton K. Weber, Construction Manager

Tel (512-527-6718 Cell (512) 539-9342 Email cweber@hntb.com

HNTB CORPORATION

CELEBRATING 25th OFFICE ANNIVERSARY IN AUSTIN AND MORE THAN 100 YEARS IN THE REGION 101 E. Old Settlers Blvd, Ste 100 | Round Rock, Texas 78664 | hntb.com

105 YEARS OF INFRASTRUCTURE SOLUTIONS

Twitter | LinkedIn | Facebook | Instagram

Eddie R. Church

From:

Oscar Salazar-Bueno

Sent:

Wednesday, December 8, 2021 5:07 PM

To:

paul@denucciconstructors.com

Cc:

Clayton Weber; Cindy Niels; Christy Jessee; Aaron DeNucci; 34275_RB_ForestNorthDrainage; Bruce

Thurin; Eddie R. Church; Christen Eschberger

Subject:

RE: Forest North Street Patching

In spirit of cooperation and to keep the project moving forward we accept the proposed \$45.00/SY price. Please have your superintendent/foreman contacting Bruce Thurin to mark the limits of the repairs and agree on the quantity of work to be done before starting any repairs.

Thanks,

Oscar Salazar-Bueno, PE

Sr. Resident Engineer
Williamson County Road Bond Program
Tel (512) 527-6734 Mobile (737) 237-3581 Email osalazarbueno@hntb.com

HNTB CORPORATION

101 E. Old Settlers Blvd., Ste. 100 | Round Rock, TX 78664 | hntb.com

■100+ YEARS OF INFRASTRUCTURE SOLUTIONS

Twitter | LinkedIn | Facebook | Instagram



From: paul@denucciconstructors.com <paul@denucciconstructors.com>

Sent: Wednesday, December 8, 2021 4:31 PM

To: Oscar Salazar-Bueno <osalazarbueno@HNTB.com>

Cc: Clayton Weber <cweber@HNTB.com>; Cindy Niels <cindyn@denucciconstructors.com>; Christy Jessee

<admin@denucciconstructors.com>; Aaron DeNucci <aarond@denucciconstructors.com>;

34275_RB_ForestNorthDrainage <34275_RB_ForestNorthDrainage@HNTB.com>; Bruce Thurin

 Sthurin@HNTB.com>;

Eddie R. Church <erchurch@HNTB.com>; Christen Eschberger <ceschberger@HNTB.com>

Subject: RE: Forest North Street Patching

HNTB holding at \$15.00 is what prompted this email. We moved to 45.00 from 85.00 with no response yet. If you would respond and agree to the 45.00 for the additional SY on both assignments we can move forward.

Paul T. DeNucci DeNucci Constructors, LLC 8310-1 Cap Tx Hwy N. Ste 275 Austin, Texas 78731 512-335-0600 512-342-0600 fax