

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year <u>12</u> Make <u>Chevrolet</u> Model <u>Tahoe PPV</u>		
VIN: 16N1C2E0C1319186 Title Restriction: ☐ Y ☒ N Odometer: 201481 ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____		
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>5.3 L, V 8</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: _____ This vehicle was maintained every <u>5,000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>4/25</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u>6</u> Speed Condition: ☐ Operable ☒ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>Transmission is slipping and going out</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____		
Exterior: Color: <u>WW</u> Windows: ☒ No Cracked Glass ☐ Cracked Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>OK</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: _____ Additional Damage: _____ Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☐ Has been removed & ☒ There are holes in the exterior ☐ There are no holes		
Interior: Color <u>Gr</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>normal wear + tear</u> Damage to Dash/Floor: <u>cracks on Dash</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☒ Driver's Side ☒ Dual ☒ Cruise Control ☐ Tilt Steering ☒ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: <u>1601 E. Polk - Bonnet, TX 78611</u> For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		

Vehicle Inspection Form

LP 1372082

Inventory ID: 20-1136

Asset Number:

Fair Market Value: pv \$15,250

Short Description:

Year 2019 Make Ford Model F250 XL

VIN: 1FT7X2B62KE52938 Title Restriction: ☐ Y ☒ N

Odometer: 104214 ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 6.2L V-8 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: Front end wobble

This vehicle was maintained every 8,000 ☐ Days ☐ Hours ☒ Miles

Date Removed From Service: Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: N/A

Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition:

Exterior: Color: White Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: Fair Tread: #Flat Hubcaps #2

Major Damage to: N/A

Additional Damage: N/A

Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color Grey/Black ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: Minor tear Driver's seat

Damage to Dash/Floor: N/A

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual

☐ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment: N/A

Manufacturer Model Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand ☒ Hitch: Type receiver

Location of Asset:

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.

Vehicle Inspection Form

LP 1171264

Inventory ID: <u>15-1031</u>	Asset Number: _____	Fair Market Value: <u>PV \$11,700</u>
Short Description: Year <u>2015</u> Make <u>Chev</u> Model <u>2500 HD</u>		
VIN: 1 G C 1 K U E G 4 F F 5 7 7 5 1 8		
Odometer: 1 4 8 6 1 4 ☐ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N: _____		
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>6 L, V 8 V-tec</u> ☐ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>Steering/stability sensor issue.</u> This vehicle was maintained every <u>3,000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual _____ Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>N/A</u> Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: _____		
Exterior: Color: <u>White</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☒ Dents ☐ Scratches ☐ Dings Tire Condition: <u>Good</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: <u>Front Bumper/Right fender</u> Additional Damage: <u>Front Bumper/Right fender</u> Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes		
Interior: Color: <u>Grey</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>Stains/tears</u> Damage to Dash/Floor: <u>N/A</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☐ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats		
Additional Equipment: <u>N/A</u> Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: _____ For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		

Generic Inspection Form

Inventory ID: 10057

Asset Number

Anticipated Sale Price:

Short Description: SA-200 DC Arc Welder

Year Unknown

Manufacturer Lincoln

Model SA-200-F-162

Please fill in or check if apply

Long Description:

This Equipment: ☐ Is Operable ☐ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☐ Hours: Unknown This equipment was maintained every N/A ☐ Hours ☐ Days

Serial # 499108

Repairs needed: Unknown

Description of Use

Color _____ ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: _____

For more information contact: _____

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:																
Short Description:																		
Year <u>1987</u>	Make <u>Cat</u>	Model <u>416 Backhoe</u>																
VIN: <u>SN</u> <table border="1" style="display: inline-table; border-collapse: collapse;"> <tr> <td>4</td><td>1</td><td>7</td><td>6</td><td>0</td><td>7</td><td>6</td><td>P</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> </table>		4	1	7	6	0	7	6	P									Title Restriction: ☐ Y ☐ N
4	1	7	6	0	7	6	P											
Odometer: <table border="1" style="display: inline-table; border-collapse: collapse;"> <tr> <td></td><td></td><td>4</td><td>0</td><td>7</td><td>2</td> </tr> </table> <u>Hours</u>				4	0	7	2	☐ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N: <u>N/A</u>										
		4	0	7	2													
Long Description:																		
This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>L, V</u> ☐ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>N/A</u> This vehicle was maintained every <u>N/A</u> ☐ Days ☐ Hours ☐ Miles Date Removed From Service: <u>N/A</u> Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☐ Automatic ☐ Manual <u>Speed</u> Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>N/A</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>N/A</u>																		
Exterior:																		
Color: <u>yellow</u> Windows: ☐ No Cracked Glass ☐ Cracked Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>Fair</u> Tread: <u></u> #Flat <u></u> Hubcaps # <u></u> Major Damage to: <u></u> Additional Damage: <u></u> Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																		
Interior:																		
Color <u>black</u> ☐ Cloth ☒ Vinyl ☐ Leather Damage to Seats: <u></u> Damage to Dash/Floor: <u></u> Radio: ☐ Stock or ☐ Brand & Model: <u></u> ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control Power: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats																		
Additional Equipment:																		
Manufacturer <u></u> Model <u></u> Serial # <u></u> ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand <u></u> ☐ Hitch: Type <u></u>																		
Location of Asset:																		
For more information contact:																		
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																		

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year <u>1987</u> Make <u>Cat</u> Model <u>416 Backhoe</u>		
VIN: <u>4176076P</u> Title Restriction: ☐ Y ☐ N		
Odometer: <u>4072</u> ^{Hours} ☐ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N: <u>N/A</u>		
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u> </u> L, V ☐ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>N/A</u> This vehicle was maintained every <u>N/A</u> ☐ Days ☐ Hours ☐ Miles Date Removed From Service: <u>N/A</u> Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☐ Automatic ☐ Manual <u> </u> Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>N/A</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>N/A</u>		
Exterior: Color: <u>yellow</u> Windows: ☐ No Cracked Glass ☐ Cracked Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>Fair</u> Tread: <u> </u> #Flat <u> </u> Hubcaps # <u> </u> Major Damage to: <u> </u> Additional Damage: <u> </u> Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes		
Interior: Color <u>black</u> ☐ Cloth ☒ Vinyl ☐ Leather Damage to Seats: <u> </u> Damage to Dash/Floor: <u> </u> Radio: ☐ Stock or ☐ Brand & Model: <u> </u> ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control Power: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats		
Additional Equipment: <u> </u> Manufacturer <u> </u> Model <u> </u> Serial # <u> </u> ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand <u> </u> ☐ Hitch: Type <u> </u>		
Location of Asset: <u> </u> For more information contact: <u> </u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		

Vehicle Inspection Form

LP 1312211

Inventory ID: 9438-09

Asset Number:

Fair Market Value: PV \$9275

Short Description:

Year 2009

Make Chevrolet

Model 3500 HD

VIN: 1GC HC 736 49 F 11 70 27

Title Restriction: ☐ Y ☒ N

Odometer:

179985

☒ Miles

☐ Kilometers

Odometer Accurate

☒ Y ☐ N:

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 6.6 L, V ☐ Gas ☒ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: ~~AAA~~ Front/Rear suspension need repair / Engine powers down from time to time

This vehicle was maintained every 8,000 ☐ Days ☐ Hours ☒ Miles

Date Removed From Service:

Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual ☐ Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: N/A

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: N/A

Exterior:

Color: White

Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☒ Scratches ☒ Dings

Tire Condition: Good Tread: #Flat Hubcaps #4

Major Damage to:

Additional Damage:

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color: Black

☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: Minor Tears

Damage to Dash/Floor: N/A

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC

Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☒ Door Locks ☐ Seats

Additional Equipment: Utility Bed

Manufacturer

Model

Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☒ Utility Body: Brand Knapheide ☒ Hitch: Type receiver

Location of Asset:

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.

Generic Inspection Form

Inventory ID: _____

Asset Number _____

Anticipated Sale Price: _____

Short Description: A.C. ARC Welder 235 AMP
Year _____ Manufacturer Marquette Model 85

Please fill in or check if apply

Long Description:

This Equipment: ☐ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☒ The Condition is Unknown

☐ Hours: N/A This equipment was maintained every N/A ☐ Hours ☐ Days

Serial # 178214

Repairs needed: Unknown

Description of Use

Color _____ ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: _____

For more information contact: _____

Vehicle Inspection Form

Inventory ID:	Asset Number: <u>M05</u>	Fair Market Value:																	
Short Description: Year <u>2011</u> Make <u>Chevrolet</u> Model <u>1500</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 250px;"> <tr><td>3</td><td>G</td><td>C</td><td>P</td><td>C</td><td>P</td><td>E</td><td>0</td><td>0</td><td>B</td><td>G</td><td>2</td><td>6</td><td>4</td><td>3</td><td>1</td><td>1</td></tr> </table> Title Restriction: ☐ Y ☒ N			3	G	C	P	C	P	E	0	0	B	G	2	6	4	3	1	1
3	G	C	P	C	P	E	0	0	B	G	2	6	4	3	1	1			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr><td>2</td><td>1</td><td>9</td><td>0</td><td>3</td><td>2</td></tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			2	1	9	0	3	2											
2	1	9	0	3	2														
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>5.3 L, V8</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>Metal in oil</u> This vehicle was maintained every <u>5000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>4/21/2025</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual ___Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>None</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>Good</u>																			
Exterior: Color: <u>White</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: <u>Good</u> Tread: <u>70%</u> #Flat___ Hubcaps #___ Major Damage to: <u>N/A</u> Additional Damage: <u>Rear Bumper</u> Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☒ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>Black and Grey</u> ☒ Cloth ☐ Vinyl ☒ Leather Damage to Seats: <u>None</u> Damage to Dash/Floor: <u>None</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats																			
Additional Equipment: <u>Grill Guard</u> Manufacturer <u>N/A</u> Model <u>N/A</u> Serial # <u>N/A</u> ☒ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☒ Hitch: Type <u>Receiver</u>																			
Location of Asset: <u>Maintenance Shop</u> For more information contact: <u>Zachary Reagor (512) 755-4653</u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			