

BURNET COUNTY



AUTHORIZATION AND ASSIGNMENT OF COUNTY PROPERTY

			(Auditor's Use)
Name of Item	Description	Property #	Cost
1.) 2018 Ford PIU	Unit #185	18-1084	
2.) Garrett Metal Detector	PD6500	5789	
3.) Garrett Metal Detector	PD6500	8242	
4.)			
5.)			
6.)			
7.)			
8.)			
9.)			

Dept. Transferred From: Sheriff Dept. Assigned To: GovDeals

Requested By: Josh Swain/Amy Willeke DATE: May 27, 2025

Comments: _____

COMMISSIONERS COURT APPROVAL:

☐ New in Service ☐ Transfer
☐ Return to Donor ☐ Out of Service ☒ Hold For Auction
☐ Dispose ☐ Donation

Authorization Signature: _____ Date: _____

Comments: _____

PROPERTY MOVED BY MAINTENANCE DEPT.:

Authorization Signature: _____ Date: _____

Comments: _____

CHANGES MADE TO RECORDS BY AUDITOR'S OFFICE:

Changed in Books: _____ Date of change: _____

Comments: _____

Per LGC 263.153 (c)--Burnet County, Texas contracts with online auction sites as licensed under Chapter 1802 of the Occupations Code to sell surplus and/or salvage property. The property is posted on the auction site for at least 10 days to comply with the publication requirement for the notice of sale.

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:																	
Short Description: Year <u>2018</u> Make <u>FORD</u> Model <u>POLICE INTERCEPTOR UTILITY</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 250px;"> <tr><td>1</td><td>F</td><td>M</td><td>5</td><td>K</td><td>8</td><td>A</td><td>R</td><td>6</td><td>J</td><td>G</td><td>A</td><td>8</td><td>9</td><td>9</td><td>4</td><td>5</td></tr> </table> Title Restriction: ☐ Y ☒ N			1	F	M	5	K	8	A	R	6	J	G	A	8	9	9	4	5
1	F	M	5	K	8	A	R	6	J	G	A	8	9	9	4	5			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr><td>1</td><td>7</td><td>8</td><td>5</td><td>9</td><td>3</td></tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			1	7	8	5	9	3											
1	7	8	5	9	3														
Long Description: This Vehicle: ☒ Starts ☒ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>3.7</u> L, V <u>6</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☒ Needs repair ☐ is in unknown condition Repairs needed: <u>WATER PUMP IS LEAKING AND NEEDS REPLACING</u> This vehicle was maintained every <u>3,000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>5/5/2025</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual ___Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: _____																			
Exterior: Color: <u>WHITE</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☒ Dents ☐ Scratches ☒ Dings Tire Condition: <u>GOOD</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: _____ Additional Damage: <u>LIGHT HAIL DAMAGE TO HOOD, BROKEN REAR PILLAR(IN PICS)</u> Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☒ Has been removed & ☒ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>GRY</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>DRIVER FRONT SEAT BACK DOES NOT ADJUST</u> Damage to Dash/Floor: _____ Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☒ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats																			
Additional Equipment: <u>SETIINA BOX IN BACK, PRISONER CAGE, GUN RACK IN FRONT</u> Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: <u>1601 E. POLK ST BURNET, TEXAS 78611</u> For more information contact: <u>SSGT SWAIN 512-756-8080 EXT 23006</u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			

Two going to Auction Generic Inspection Form

Inventory ID:

Asset Number

Anticipated Sale Price:

Short Description:

walk Thru

Year Jan 2003

Manufacturer

Garrett

Model

PD6500i

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: unk This equipment was maintained every ☐ Hours ☐ Days

Serial #

33041650

Repairs needed:

No

Description of Use

Detection of metal items that are dangerous or could be used in a dangerous manner.

Color

Tan

☐ Cloth

☐ Vinyl

☐ Leather

☒ Metal

☐ Plastic

☐ Wood

☐ Rubber

Minor damage to:

Major damage to:

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size:

Women's Size:

Additional Equipment:

Manufacturer

Model

Serial #

Condition:

☐ Is Operable

☐ Needs repair

☐ Unknown Condition

Description:

Additional Equipment:

Manufacturer

Model

Serial #

Condition:

☐ Is Operable

☐ Needs repair

☐ Unknown Condition

Description:

Additional Equipment:

Manufacturer

Model

Serial #

Condition:

☐ Is Operable

☐ Needs repair

☐ Unknown Condition

Description:

Comments:

Location of Asset:

South Annex

For more information contact:

Amg Willeke 325-716-8655

Generic Inspection Form

May 12, 2025

Inventory ID:

Asset Number

Anticipated Sale Price:

Short Description: Garrett metal detector & cradleYear Jan 2003Manufacturer GarrettModel PD 6500

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown☐ Hours: _____ This equipment was maintained every 1 month ☐ Hours ☒ Days 30 daySerial # 33041650 (South Annex)Repairs needed: None known

Description of Use

Screening Entrants for metal items
At South AnnexColor tan ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: 38 Width/Depth: Feet: _____ Inches: 28 Height: Feet: _____ Inches: 88 = 4' 11"

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer Garrett Model PD 6500Serial # 33059124 Condition: ☒ Is Operable ☐ Needs repair ☐ Unknown ConditionDescription: Jan 2003 model upstairs at Courthouse

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown ConditionDescription: At Courthouse, up stairs

Comments:

Location of Asset: _____

For more information contact: _____