

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:																	
Short Description: Year <u>2018</u> Make <u>Ford</u> Model <u>Explorer(Police Interceptor Utility)</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 600px;"> <tr><td>1</td><td>F</td><td>M</td><td>5</td><td>K</td><td>8</td><td>A</td><td>R</td><td>4</td><td>J</td><td>G</td><td>A</td><td>8</td><td>9</td><td>9</td><td>4</td><td>4</td></tr> </table> Title Restriction: ☐ Y ☒ N			1	F	M	5	K	8	A	R	4	J	G	A	8	9	9	4	4
1	F	M	5	K	8	A	R	4	J	G	A	8	9	9	4	4			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 150px;"> <tr><td>1</td><td>7</td><td>1</td><td>8</td><td>3</td><td>0</td></tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			1	7	1	8	3	0											
1	7	1	8	3	0														
Long Description: This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>3.5</u> L, V <u>6</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>CHECK ENGINE LIGHT IS ON, A/C EVAP CORE IS LEAKING BLOWS HOT AIR</u> This vehicle was maintained every <u>3,000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>7-1-2025</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u>5</u> Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: _____																			
Exterior: Color: <u>WHITE</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>GOOD</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: _____ Additional Damage: <u>NORMAL DENTS AND SCRATCHES AND DINGS</u> Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☐ Has been removed & ☒ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>BLK</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>NORMAL</u> Damage to Dash/Floor: _____ Radio: ☐ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☐ AC (Condition: ☐ Cold ☐ Unknown) ☒ No AC Air Bags: ☒ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats																			
Additional Equipment: <u>SETINA CARGO BOX IN REAR, PLASTIC REAR SEATS</u> Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: <u>1601 E. POLK ST BURNET, TX 78611</u> For more information contact: <u>SSGT. SWAIN 512-756-8080 EXT 23006</u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			