

Generic Inspection Form

Inventory ID: _____

Asset Number _____

Anticipated Sale Price: _____

Short Description: Small Blade 12'
Year _____ Manufacturer Fiat Allis Model 65-B

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☒ Hours: 3577 This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # 68004195

Repairs needed: Multiple

Description of Use

20' LENGTH BY 6 1/2 WIDE BLADE MOTOR GRADER
12' MOLO DECK HEIGHT 9'4"

Color Yellow ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

80 HP Diesel ENG. / 6 Forward Speeds, 6 Reverse Speed, 4WD

Location of Asset: _____

For more information contact: _____

Generic Inspection Form

HD Tilt Trailer

23'

Inventory ID: (Plate) 902-0742	Asset Number	Anticipated Sale Price:
Short Description: HD Tilt trailer 23'		
Year	Manufacturer	Model

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: _____ This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # 30410 (Frame)

Repairs needed: None

Description of Use

Don't use any more

Color white ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: N/A

Major damage to: N/A

Size: Length: Feet: 23 Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: Pet 5 Barn

For more information contact: _____

Tractor Inspection Form

Inventory ID:

Asset Number

4663

Fair Market Value:

Short Description:

Year _____ Manufacturer John Deere Model 5400

PIN

Serial Number LV5400E643971

Please fill in or check

Long Description:

This Equipment: ☒ Starts ☐ Starts with a Boost & ☐ Is Operable ☐ Is not operable ☐ For Parts Only

Engine 2.9 L, V ☐ Gas ☒ Diesel engine ☒ Hours 3190 ☐ Miles _____

This vehicle was maintained every year ☐ Hours _____ Horse Power 70 hp

Engine Manufacture: JD Condition: ☒ Is Operable ☐ Needs repair ☐ Is in Unknown Condition

Repairs needed: 2 Front tires need replacing

Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission

Transmission: ☐ Automatic ☒ Manual _____ Speed _____ Transmission: ☐ Hours _____ ☐ Miles _____

Transmission Manufacture: _____ Condition: ☒ Is Operable ☐ Needs Repair ☐ Is Unknown

Drivetrain _____ Repairs Needed: N/A / 3 gears plus Reverse.
3 Ranges (A-C) Gear shift Synchronized
using clutch.

Attachments & Additional Equipment

☐ Backhoe ☐ Front End Loader ☐ PTO Drive ☐ 3 Point Hitch ☒ Other: Batwing Mower

Mowing Deck: Manufacture: Bush Hog Model: 3710 Type: Batwing Size: _____

Deck Condition: ☐ Operable ☒ Not Operable & ☐ Damage: _____

Other Equipment: Manufacturer _____ Model _____

Serial # BH 70997 029 Condition: ☐ Is Operable ☐ Needs repair ☐ Is in Unknown Condition

Description: _____

Exterior: Color Green

Windows: ☐ No cracked glass ☐ Cracked N/A

Minor ☐ Dents ☒ Scratches ☒ Dings Tire Condition: ☐ Low ☒ Flat 2

Minor dents to: _____

Major damage to: _____

Dimensions: 12' Tractor / 15' Batwing Brush Hog / 7' main Deck, 5' wing

Decals: ☐ None ☐ Have been sprayed ☒ Have been removed ☒ Impressions remain ☐ No impressions

Interior: Color Yellow Seat ☐ Cloth ☒ Vinyl ☐ Leather

Damage to: _____

Radio: Brand N/A ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☐ Cruise Control Power: ☒ Steering ☐ Seats ☐ AC ☒ No AC Condition: ☐ Cold ☐ Unknown

Location of Asset: Plot 3 Barn

For more information contact: _____

Generic Inspection Form

OLD Broom

Inventory ID:

Asset Number

6046

Anticipated Sale Price:

Short Description: Street SweeperYear 86Manufacturer WaldonModel Sweep MasterPlease fill in or check if apply

Long Description:

This Equipment: ☐ Is Operable ☒ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☒ The Condition is Unknown☒ Hours: 53.5 This equipment was maintained every N/A ☐ Hours ☐ DaysSerial # 18601Repairs needed: MultipleDescription of UseL.P. 806540Color Yellow ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

PARTS ONLYLocation of Asset: Pct 3 Barn

For more information contact: _____

Generic Inspection Form

Inventory ID: _____

Asset Number

7934

Anticipated Sale Price: _____

Short Description: _____

Year 89

Manufacturer Waldon

Model Sweep Master

Please fill in or check if apply

Long Description:

This Equipment: ☐ Is Operable ☒ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☒ The Condition is Unknown

☒ Hours: 1109 This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # 20988

Repairs needed: _____

Description of Use

Color Yellow ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

PARTS ONLY

Location of Asset: Pet 3 Barn

For more information contact: _____

Generic Inspection Form

Inventory ID: _____

Asset Number _____

Anticipated Sale Price: _____

Short Description: AIR COMPRESSOR

Year _____

Manufacturer _____

Model 82378VAT

Please fill in or check if apply

Long Description:

This Equipment: ☐ Is Operable ☒ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: _____ This equipment was maintained every YEAR ☐ Hours ☐ Days

Serial # 474753840

Repairs needed: NEEDS PUMP

Description of Use

PUMP LOCKED UP MODEL 82378VAT

80 GALLON / 24 ACFM @ 175 PSI

Color GREY ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: N/A

Major damage to: N/A

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: _____

For more information contact: _____