

BURNET COUNTY

25



AUTHORIZATION AND ASSIGNMENT OF COUNTY PROPERTY

			(Auditor's Use)
Name of Item	Description	Property #	Cost
1.) 2012 Chevrolet Tahoe	Unit #71	12-1109	
2.)			
3.)			
4.)			
5.)			
6.)			
7.)			
8.)			
9.)			

Dept. Transferred From: Sheriff

Dept. Assigned To: GovDeals

Requested By: Josh Swain DATE: May 13, 2025

Comments: _____

COMMISSIONERS COURT APPROVAL:

☐ New in Service ☐ Transfer
☐ Return to Donor ☐ Out of Service ☒ Hold For Auction
☐ Dispose ☐ Donation

Authorization Signature:

Date: 5/13/25

Comments: _____

PROPERTY MOVED BY MAINTENANCE DEPT.:

Authorization Signature: _____ Date: _____

Comments: _____

CHANGES MADE TO RECORDS BY AUDITOR'S OFFICE:

Changed in Books: _____ Date of change: _____

Comments: _____

Per LGC 263.153 (c)--Burnet County, Texas contracts with online auction sites as licensed under Chapter 1802 of the Occupations Code to sell surplus and/or salvage property. The property is posted on the auction site for at least 10 days to comply with the publication requirement for the notice of sale.

Vehicle Inspection Form

Inventory ID: _____	Asset Number: _____	Fair Market Value: _____
Short Description: Year <u>12</u> Make <u>Chevrolet</u> Model <u>Tahoe PPV</u>		
VIN: <u>16N1C2E0C1R319186</u> Title Restriction: ☐ Y ☒ N Odometer: <u>201481</u> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____		
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>5.3 L, V8</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: _____ This vehicle was maintained every <u>5,000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>4/25</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u>6</u> Speed Condition: ☐ Operable ☒ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>Transmission is slipping and going out</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____		
Exterior: Color: <u>Wh</u> Windows: ☒ No Cracked Glass ☐ Cracked Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>OK</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: _____ Additional Damage: _____ Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☐ Has been removed & ☒ There are holes in the exterior ☐ There are no holes		
Interior: Color <u>Gr</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>normal wear + tear</u> Damage to Dash/Floor: <u>cracks on Dash</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☒ Driver's Side ☒ Dual ☒ Cruise Control ☐ Tilt Steering ☒ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: <u>1601 E. Polk - Burnet, TX 78611</u> For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		

BURNET COUNTY



AUTHORIZATION AND ASSIGNMENT OF COUNTY PROPERTY

			(Auditor's Use)
Name of Item	Description	Property #	Cost
1.) 2016 John Deere	Tractor	16-1060	
2.) 2009 Chevrolet Silverado	3500HD	9438-09	
3.) Lincoln Welder	200 AMP DC ARC	10057	
4.) Lincoln Welder	235 AMP ARC	n/a	
5.) 1987 Waldon Road Sweeper	Backhoe/Loader	6046	
6.)			
7.)			
8.)			
9.)			

Dept. Transferred From:
Road and Bridge Pct. 2

Dept. Assigned To:
GovDeals Auction

Requested By: Damon Beierle

DATE: May 13, 2025

Comments: _____

COMMISSIONERS COURT APPROVAL:

☐ New in Service ☐ Transfer
☐ Return to Donor ☐ Out of Service ☒ Hold For Auction
☐ Dispose ☐ Donation

Authorization Signature:  Date: _____

Comments: _____

PROPERTY MOVED BY MAINTENANCE DEPT.:

Authorization Signature: _____ Date: _____

Comments: _____

CHANGES MADE TO RECORDS BY AUDITOR'S OFFICE:

Changed in Books: _____ Date of change: _____

Comments: _____

Per LGC 263.153 (c)—Burnet County, Texas contracts with online auction sites as licensed under Chapter 1802 of the Occupations Code to sell surplus and/or salvage property. The property is posted on the auction site for at least 10 days to comply with the publication requirement for the notice of sale.

Vehicle Inspection Form

Inventory ID: <u>16-1060</u>	Asset Number:	Fair Market Value:																
Short Description: Year <u>2016</u> Make <u>John Deere</u> Model <u>CX15 Single Bat Shredder</u>																		
VIN: <table border="1" style="display: inline-table; text-align: center; font-family: monospace;"> <tr><td>B</td><td>W</td><td>1</td><td>5</td><td>7</td><td>2</td><td>2</td><td>1</td><td>0</td><td>C</td><td>X</td><td>1</td><td>5</td><td>G</td><td>A</td><td>Z</td></tr> </table> 046468 (serial #) Title Restriction: ☐ Y ☐ N			B	W	1	5	7	2	2	1	0	C	X	1	5	G	A	Z
B	W	1	5	7	2	2	1	0	C	X	1	5	G	A	Z			
Odometer: <table border="1" style="display: inline-table; text-align: center; font-family: monospace;"> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> </table> ☐ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N:																		
Long Description: This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u> L, V </u> ☐ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☐ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>Good Working Condition</u> This vehicle was maintained every <u> </u> ☐ Days ☐ Hours ☐ Miles Date Removed From Service: <u> </u> Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☐ Automatic ☐ Manual Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u> </u> Drivetrain: ☐ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u> </u>																		
Exterior: Color: <u> </u> Windows: ☐ No Cracked Glass ☐ Cracked <u> </u> Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: <u> </u> Tread: <u> </u> #Flat Hubcaps # <u> </u> Major Damage to: <u> </u> Additional Damage: <u> </u> Decals: ☐ None ☐ Have Been Sprayed <u>or</u> ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																		
Interior: Color <u> </u> ☐ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u> </u> Damage to Dash/Floor: <u> </u> Radio: ☐ Stock <u>or</u> ☐ Brand & Model: <u> </u> ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control Power: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats																		
Additional Equipment: <u> </u> Manufacturer <u> </u> Model <u> </u> Serial # <u> </u> ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand <u> </u> ☐ Hitch: Type <u> </u>																		
Location of Asset: <u> </u> For more information contact: <u> </u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																		

Vehicle Inspection Form

LP 1312211

Inventory ID: 9438-09

Asset Number:

Fair Market Value: PV \$9275

Short Description:

Year 2009 Make Chevrolet Model 3500 HD

VIN: 1GCHC73649F117027 Title Restriction: ☐ Y ☒ N

Odometer: 179985 ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 6.6 L, V ☐ Gas ☒ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: ~~Front/Rear suspension need repair~~ Engine powers down from time to time

This vehicle was maintained every 8,000 ☐ Days ☐ Hours ☒ Miles

Date Removed From Service: Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: N/A

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: N/A

Exterior: Color: White Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☐ Scratches ☐ Dings Tire Condition: Good Tread: #Flat Hubcaps #4

Major Damage to:

Additional Damage:

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color: Black ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: minor Tears

Damage to Dash/Floor: N/A

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☒ Door Locks ☐ Seats

Additional Equipment: Utility Bed

Manufacturer Model Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☒ Utility Body: Brand Knapheide ☒ Hitch: Type receiver

Location of Asset:

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.

Generic Inspection Form

Inventory ID: <u>10057</u>	Asset Number	Anticipated Sale Price:
Short Description: <u>SA-200 DC Arc Welder</u>		
Year <u>Unknown</u>	Manufacturer <u>Lincoln</u>	Model <u>SA-200-F-162</u>

Please fill in or check if apply **Long Description:**

This Equipment: ☐ Is Operable ☐ Is Not Operable ☐ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☐ Hours: Unknown This equipment was maintained every N/A ☐ Hours ☐ Days

Serial # 499108

Repairs needed: Unknown

Description of Use

Color ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to:

Major damage to:

Size: Length: Feet: Inches: Width/Depth: Feet: Inches: Height: Feet: Inches:

Men's Size: Women's Size:

Additional Equipment: Manufacturer Model

Serial # Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description:

Additional Equipment: Manufacturer Model

Serial # Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description:

Additional Equipment: Manufacturer Model

Serial # Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description:

Comments:

Location of Asset: <u> </u>
For more information contact: <u> </u>

Generic Inspection Form

Inventory ID: _____	Asset Number: _____	Anticipated Sale Price: _____
Short Description: <u>A.C. Arc Welder</u> <u>235 AMP</u>		
Year: _____	Manufacturer: <u>Marquette</u>	Model: <u>85</u>

<u>Please fill in or check if apply</u>	Long Description:
This Equipment: ☐ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☒ The Condition is Unknown	
☐ Hours: <u>N/A</u> This equipment was maintained every <u>N/A</u> ☐ Hours ☐ Days	
Serial # <u>178214</u>	
Repairs needed: <u>Unknown</u>	
Description of Use	
Color: _____ ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber	
Minor damage to: _____	
Major damage to: _____	
Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____	
Men's Size: _____ Women's Size: _____	
Additional Equipment: Manufacturer: _____ Model: _____	
Serial #: _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition	
Description: _____	
Additional Equipment: Manufacturer: _____ Model: _____	
Serial #: _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition	
Description: _____	
Additional Equipment: Manufacturer: _____ Model: _____	
Serial #: _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition	
Description: _____	
Comments:	

Location of Asset: _____
For more information contact: _____

Vehicle Inspection Form

Inventory ID: _____	Asset Number: _____	Fair Market Value: _____																
Short Description: Year <u>1987</u> Make <u>Cox</u> Model <u>416 Backhoe</u>																		
VIN: <u>SN</u> <table border="1" style="display: inline-table; text-align: center; width: 150px;"> <tr><td>4</td><td>1</td><td>7</td><td>6</td><td>0</td><td>7</td><td>6</td><td>P</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </table> Title Restriction: ☐ Y ☐ N			4	1	7	6	0	7	6	P								
4	1	7	6	0	7	6	P											
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr><td></td><td></td><td>4</td><td>0</td><td>7</td><td>2</td></tr> </table> <u>Hours</u> ☐ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N: <u>N/A</u>					4	0	7	2										
		4	0	7	2													
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>L, V</u> ☐ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>N/A</u> This vehicle was maintained every <u>N/A</u> ☐ Days ☐ Hours ☐ Miles Date Removed From Service: <u>N/A</u> Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☐ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>N/A</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>N/A</u>																		
Exterior: Color: <u>yellow</u> Windows: ☐ No Cracked Glass ☐ Cracked Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>Fair</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: _____ Additional Damage: _____ Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																		
Interior: Color <u>black</u> ☐ Cloth ☒ Vinyl ☐ Leather Damage to Seats: _____ Damage to Dash/Floor: _____ Radio: ☐ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control Power: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats																		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																		
Location of Asset: _____ For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																		

BURNET COUNTY



AUTHORIZATION AND ASSIGNMENT OF COUNTY PROPERTY

			(Auditor's Use)
Name of Item	Description	Property #	Cost
1.) 2015 Chevrolet Silverado	2500HD	15-1031	
2.) 2109 Ford	F250	20-1136	
3.)			
4.)			
5.)			
6.)			
7.)			
8.)			
9.)			

Dept. Transferred From:
Road and Bridge Pct. 2

Dept. Assigned To:
Maintenance

Requested By: Damon Beierle

DATE: May 13, 2025

Comments:

COMMISSIONERS COURT APPROVAL:

☐ New in Service ☒ Transfer
☐ Return to Donor ☐ Out of Service ☐ Hold For Auction
☐ Dispose ☐ Donation

Authorization Signature: TRP Date:

Comments:

PROPERTY MOVED BY MAINTENANCE DEPT.:

Authorization Signature: Date:

Comments:

CHANGES MADE TO RECORDS BY AUDITOR'S OFFICE:

Changed in Books: Date of change:

Comments:

Per LGC 263.153 (c)--Burnet County, Texas contracts with online auction sites as licensed under Chapter 1802 of the Occupations Code to sell surplus and/or salvage property. The property is posted on the auction site for at least 10 days to comply with the publication requirement for the notice of sale.

Vehicle Inspection Form

LP 1171264

Inventory ID: 15-1031

Asset Number:

Fair Market Value: PV \$11,700

Short Description:

Year 2015

Make Chev

Model 2500 HD

VIN: 1GCKUEG4FF577518

Title Restriction: ☐ Y ☒ N

Odometer: 148614

☐ Miles ☐ Kilometers

Odometer Accurate ☐ Y ☐ N:

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 6 L, V 8 Valve ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: ~~N/A~~ Steering/stability sensor issue.

This vehicle was maintained every 3,000 ☐ Days ☐ Hours ☒ Miles

Date Removed From Service: Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: N/A

Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition:

Exterior: Color: White Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☐ Scratches ☐ Dings Tire Condition: Good Tread: #Flat Hubcaps #

Major Damage to: Front Bumper/Right fender

Additional Damage: Front Bumper/Right fender

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color: Grey ☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: Stains/tears

Damage to Dash/Floor: N/A

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC

Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats

Additional Equipment: N/A

Manufacturer Model Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand ☐ Hitch: Type

Location of Asset:

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.

Vehicle Inspection Form

LP 1372082

Inventory ID: 20-1136

Asset Number:

Fair Market Value: PV \$15,250

Short Description:

Year 2019 Make Ford Model F250 XL

VIN: 1FT7X2B62KEG52938 Title Restriction: ☐ Y ☒ N

Odometer: 104214 ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 6.2L V-8 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: ~~N/A~~ Front end wobble

This vehicle was maintained every 8,000 ☐ Days ☐ Hours ☒ Miles

Date Removed From Service: Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: N/A

Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition:

Exterior: Color: White Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: Fair Tread: #Flat Hubcaps #2

Major Damage to: N/A

Additional Damage: N/A

Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color Grey/Black ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: ~~N/A~~ Minor Tear Driver's seat

Damage to Dash/Floor: N/A

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual

☐ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment: N/A

Manufacturer Model Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand ☒ Hitch: Type receiver

Location of Asset:

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.

BURNET COUNTY



AUTHORIZATION AND ASSIGNMENT OF COUNTY PROPERTY

Name of Item	Description	Property #	(Auditor's Use) Cost
1.) 2011 Chevrolet Silverado	Unit# M05	11-9914	
2.)			
3.)			
4.)			
5.)			
6.)			
7.)			
8.)			
9.)			

Dept. Transferred From: Maintenance
Dept. Assigned To: GovDeals

Requested By: Zach Reagor

DATE: May 13, 2025

Comments:

COMMISSIONERS COURT APPROVAL:

☐ New in Service ☐ Transfer
☐ Return to Donor ☐ Out of Service ☒ Hold For Auction
☐ Dispose ☐ Donation

Authorization Signature:

Date:

Comments:

PROPERTY MOVED BY MAINTENANCE DEPT.:

Authorization Signature:

Date:

Comments:

CHANGES MADE TO RECORDS BY AUDITOR'S OFFICE:

Changed in Books:

Date of change:

Comments:

Per LGC 263.153 (c)--Burnet County, Texas contracts with online auction sites as licensed under Chapter 1802 of the Occupations Code to sell surplus and/or salvage property. The property is posted on the auction site for at least 10 days to comply with the publication requirement for the notice of sale.

Vehicle Inspection Form

Inventory ID:

Asset Number: **M05**

Fair Market Value:

Short Description:

Year 2011

Make Chevrolet

Model 1500

VIN:

3 G C P C P E 0 0 B G 2 6 4 3 1 1

Title Restriction: ☐ Y ☒ N

Odometer:

2 1 9 0 3 2

☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 5.3 L, V8 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: Metal in oil

This vehicle was maintained every 5000 ☐ Days ☐ Hours ☒ Miles

Date Removed From Service: 4/21/2025 Maintenance Records: ☐ Available ☒ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: None

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: Good

Exterior:

Color: White

Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: Good Tread: 70% #Flat Hubcaps #

Major Damage to: N/A

Additional Damage: Rear Bumper

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☒ No Impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color Black and Grey ☒ Cloth ☐ Vinyl ☒ Leather

Damage to Seats: None

Damage to Dash/Floor: None

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC

Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats

Additional Equipment: Grill Guard

Manufacturer N/A Model N/A Serial # N/A

☒ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand ☒ Hitch: Type Receiver

Location of Asset: Maintenance Shop

For more information contact: Zachary Reagor (512) 755-4653

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.