


## COCHISE COUNTY INSPECTION REPORT VIOLATION / HAZARD

<input type="checkbox"/> First Inspection <input checked="" type="checkbox"/> Re-Inspect	Parcel #: 10671297A	Case#: 24-002851
Property Owner(s): HOUSTON JASON		Zoning: MH-72
Site Address: 300 N 6TH ST, SIERRA VISTA, AZ 85635		Category: A-NEIGHBORHOOD REHABILITATION
Complaint: Installed mesh on fence and is blocking site triangle.		
Inspection Instructions:		
Inspection Summary: ORDER. the screening has not been removed. the screening blocks your vision going onto theater drive.		
Owner or Resident Contacted?		
Phone Number:		
Inspection Status: Failed		Date Assigned: 02/28/2025 Date Inspected: 02/28/2025
 Inspector Signature:		

### Parcel History:

File#	Permit#	Type	Description	Status	Opened	Issued	Closed
24-002967	ROW22-000191	Permitting	6' High Fence panels on (e) chain link fence	Open	08/30/2024	11/09/2023	
24-002851		Violation	Installed mesh on fence and is blocking site triangle.	Open	08/19/2024		
22-002003		Engineering	Construction of New SFH	Closed	05/31/2022		08/02/2023
			Right - away	Open	05/24/2022		
2014-00000193		Violation	OUTDOOR STORAGE OUTDOOR STORAGE IN EXCESS OF 60 SQ FEET	Closed	04/25/2014		05/05/2014

## Violation Photo(s):

**Taken On:** 02/28/2025

**Taken By:** Chris Saylor

**Description:** inspection photo's

