


# Closed Inspections




Closed Inspections Closed Work Orders

## Closed Hydrant Inspection by Crew



Inspections Work Orders



City of Flagstaff, Coconino County, County of Yavapai, Bureau of Land Management, Esri, HERE, Garmin, USGS, NGA, EPA, USDA, NPS | Azteca Systems, LLC - Cityworks® 2009 - 2022 Powered by Esri

The following numbers reflect **Open Fire Hydrant Work Orders** based on closed Fire Hydrant Inspections. The bold numbers reveal current fire hydrants with that condition.

| Hydrants   | Hydrants  | Hydrants  | Hydrants  |
|--|---|---|---|
| Condition 2  | Condition 3   | Condition 4   | Condition 5   |
| 8  | 105   | 25  | 2   |
| <ul style="list-style-type: none"> <li>Priority: 4 - Repair</li> <li>Priority: 4 - Repair</li> <li>Priority: 4 - Repair Valve</li> <li>Priority: 5 - General Site</li> <li>Priority: 5 - General Site</li> <li>Priority: 5 - Repair</li> </ul> | <ul style="list-style-type: none"> <li>Priority: 3 - General Site</li> <li>Priority: 3 - Repair</li> <li>Priority: 3 - Repair</li> <li>Priority: 3 - Replacement</li> <li>Priority: 3 - Repair</li> <li>Priority: 3 - Repair</li> </ul> | <ul style="list-style-type: none"> <li>Priority: 2 - Repair</li> <li>Priority: 2 - Replacement</li> <li>Priority: 2 - Replacement</li> <li>Priority: 2 - Replacement</li> <li>Priority: 2 - Rebuild</li> <li>Priority: 2 - Rebuild</li> </ul> | <ul style="list-style-type: none"> <li>Priority: 1 - General Site</li> <li>Priority: 1 - Replacement</li> </ul> |