

Photo Name	Date Taken	Building	Interior/Exterior	Room (if applicable)	Direction (facing)	Description
100-3819	10/1/2025	House	Exterior	n/a	NW	Exterior of the house, facing NW
100-3820	10/1/2025	House	Exterior	n/a	W	Overview of historic window on eastern side of house, facing W
100-3821	10/1/2025	Historic Shed	Exterior	n/a	SE	Historic shed, facing SE
100-3822	10/1/2025	Historic Shed	Exterior	n/a	NE	Historic shed, facing NE
100-3823	10/1/2025	Historic Shed	Exterior	n/a	E	Historic shed (southern half), facing E
100-3824	10/1/2025	Historic Shed	Interior	n/a	E	Interior of shed with historic door, facing E
100-3825	10/1/2025	Historic Shed	Interior	n/a	E	Close-up of handle on historic door, facing E
100-3826	10/1/2025	Historic Shed	Interior	n/a	E	Closeup of hinge of historic door, facing E
100-3827	10/1/2025	Historic Shed	Interior	n/a	E	Interior of shed (middle section of E wall), facing E
100-3828	10/1/2025	Historic Shed	Interior	n/a	E	Overview of hearth & exhaust pipe exit in historic shed, facing E
100-3829	10/1/2025	Historic Shed	Exterior	n/a	NW	Historic shed, facing NW
100-3830	10/1/2025	Historic Shed	Exterior	n/a	SW	Historic shed, facing SW
100-3831	10/1/2025	Historic Shed	Exterior	n/a	W	Exterior overview of exhaust pipe exit, facing W
100-3832	10/1/2025	Historic Shed	Exterior	n/a	Plan	Rubble pile from chimney at the base of exhaust, facing plan view
100-3833	10/1/2025	Historic Shed	Exterior	n/a	W	Close-up of historic nail, facing W
100-3834	10/1/2025	House	Interior	Entry Room	NW	Interior of house, entry room, facing NW
100-3835	10/1/2025	House	Interior	Entry Room	SE	Interior of house, entry room, facing SE
100-3836	10/1/2025	House	Interior	Entry Room	SW	Interior of house, entry room, facing SW
100-3837	10/1/2025	House	Interior	Entry Room	NW	Interior of house, front door, top hinges, facing NW
100-3838	10/1/2025	House	Interior	Entry Room	NW	Interior of house, front door, bottom hinges, facing NW
100-3839	10/2/2025	House	Interior	Front Bedroom	SW	Interior of house, front bedroom, from NE corner
100-3840	10/2/2025	House	Interior	Front Bedroom	NE	Interior of house, front bedroom, from SW corner
100-3841	10/2/2025	House	Interior	Front Bedroom	SE	Interior of house, front bedroom, from NW corner
100-3842	10/2/2025	House	Interior	Front Bedroom	NW	Interior of house, front bedroom, from SE corner
100-3843	10/2/2025	House	Interior	Front Bedroom	NE	Interior of house, front bedroom, structural damage in NE corner
100-3844	10/2/2025	House	Interior	Front Bedroom	NW	Interior of house, front bedroom, structural damage in NW corner
100-3845	10/2/2025	House	Interior	Front Bedroom	SW	Interior of house, front bedroom, structural damage in SW corner
100-3846	10/2/2025	House	Interior	Front Bedroom	NE	Interior of house, front bedroom, mouse hole in NE corner
100-3847	10/2/2025	House	Interior	Shared Closet	S	Interior of house, shared closet, from N end
100-3848	10/2/2025	House	Interior	Shared Closet	N	Interior of house, shared closet, from S end
100-3849	10/2/2025	House	Interior	Shared Closet	S	Interior of house, shared closet, close-up of rounded ceiling and original molding in the S end
100-3850	10/2/2025	House	Interior	Shared Closet	N	Interior of house, shared closet, close-up of covered molding and structural issue in the N end
100-3851	10/2/2025	House	Interior	Main Bedroom	SE	Interior of house, main bedroom, from NW corner
100-3852	10/2/2025	House	Interior	Main Bedroom	NW	Interior of house, main bedroom, from SE corner
100-3853	10/2/2025	House	Interior	Main Bedroom	SW	Interior of house, main bedroom, from NE corner
100-3854	10/2/2025	House	Interior	Main Bedroom	NE	Interior of house, main bedroom, from SW corner
100-3855	10/2/2025	House	Interior	Main Bedroom	NE	Interior of house, main bedroom, close-up of NE corner structural damage
100-3856	10/2/2025	House	Interior	Kitchen	SE	Interior of house, kitchen, from NW corner
100-3857	10/2/2025	House	Interior	Kitchen	NW	Interior of house, kitchen, from SE corner
100-3858	10/2/2025	House	Interior	Kitchen	SW	Interior of house, kitchen, from NE corner
100-3859	10/2/2025	House	Interior	Kitchen	NE	Interior of house, kitchen, from SW corner
100-3860	10/2/2025	House	Interior	Sun Room	S	Interior of house, sun room, from N end
100-3861	10/2/2025	House	Interior	Sun Room	N	Interior of house, sun room, from S end
100-3862	10/2/2025	House	Interior	Sun Room	E	Interior of house, sun room, E wall windows; only southern windows are original
100-3863	10/2/2025	House	Interior	Entry Room off Kitchen	E	Interior of house, entry room off kitchen, from W end
100-3864	10/2/2025	House	Interior	Entry Room off Kitchen	W	Interior of house, entry room off kitchen, from E end
100-3865	10/2/2025	House	Interior	Bathroom	SW	Interior of house, bathroom, from NE doorway; everything is replaced
100-3866	10/2/2025	House	Interior	Living Room	SW	Interior of house, living room, from NE corner
100-3867	10/2/2025	House	Interior	Living Room	SE	Interior of house, living room, from NW corner
100-3868	10/2/2025	House	Interior	Living Room	NE	Interior of house, living room, from SW corner
100-3869	10/2/2025	House	Interior	Living Room	NW	Interior of house, living room, from SE corner
100-3870	10/2/2025	House	Interior	Living Room	W	Interior of house, living room, overview of chimney, facing W
100-3871	10/2/2025	House	Interior	Kitchen	E	Interior of house, kitchen, overview of ironing board on E wall
100-3872	10/2/2025	House	Interior	Entry Room	W	Interior of house, front door top hinge, facing W
100-3873	10/2/2025	House	Interior	Entry Room	W	Interior of house, front door top hinge, facing W
100-3874	10/2/2025	House	Interior	Entry Room	W	Interior of house, front door bottom hinge, facing W
100-3875	10/2/2025	House	Interior	Living Room/Main Bedroom	E	Interior of house, living room-main bedroom door, top hinge, facing E
100-3876	10/2/2025	House	Interior	Living Room/Main Bedroom	E	Interior of house, living room-main bedroom door, bottom hinge, facing E
100-3877	10/2/2025	House	Interior	Living Room/Main Bedroom	W	Interior of house, living room-main bedroom door, int. handle, facing W
100-3878	10/2/2025	House	Interior	Living Room/Main Bedroom	E	Interior of house, living room-main bedroom door, ext. handle, facing E
100-3879	10/2/2025	House	Interior	Main Bedroom/Kitchen	W	Interior of house, main bedroom-kitchen door, top hinge, facing W
100-3880	10/2/2025	House	Interior	Main Bedroom/Kitchen	W	Interior of house, main bedroom-kitchen door, bottom hinge, facing W
100-3881	10/2/2025	House	Interior	Main Bedroom/Kitchen	E	Interior of house, main bedroom-kitchen door, int. handle, facing E
100-3882	10/2/2025	House	Interior	Main Bedroom/Kitchen	W	Interior of house, main bedroom-kitchen door, ext. handle, facing W
100-3883	10/2/2025	House	Interior	Sunroom	E	Interior of house, sunroom, E wall window handle overview
100-3884	10/2/2025	House	Interior	Sunroom	E	Interior of house, sunroom, E wall window handle overview
100-3885	10/2/2025	House	Interior	Sunroom	E	Interior of house, sunroom, E wall window handle overview
100-3886	10/2/2025	House	Interior	Sunroom	E	Interior of house, sunroom, E wall window handle overview
100-3887	10/2/2025	House	Interior	Sunroom	E	Interior of house, sunroom, E wall window handle overview
100-3888	10/2/2025	House	Interior	Sunroom	E	Interior of house, sunroom, E wall window handle overview
100-3889	10/2/2025	House	Interior	Bathroom/Entry Room off Kitchen	S	Interior of house, bathroom-entry room off kitchen door, top hinge
100-3890	10/2/2025	House	Interior	Bathroom/Entry Room off Kitchen	S	Interior of house, bathroom-entry room off kitchen door, top hinge
100-3891	10/2/2025	House	Interior	Bathroom/Entry Room off Kitchen	S	Interior of house, bathroom-entry room off kitchen door, bottom hinge
100-3892	10/2/2025	House	Interior	Bathroom/Entry Room off Kitchen	S	Interior of house, bathroom-entry room off kitchen door, ext. handle
100-3893	10/2/2025	House	Interior	Bathroom/Entry Room off Kitchen	N	Interior of house, bathroom-entry room off kitchen door, int. handle
100-3894	10/2/2025	House	Interior	Living Room	S	Interior of house, living room SE door, top hinge
100-3895	10/2/2025	House	Interior	Living Room	S	Interior of house, living room SE door, middle hinge
100-3896	10/2/2025	House	Interior	Living Room	S	Interior of house, living room SE door, bottom hinge
100-3897	10/2/2025	House	Interior	Living Room	S	Interior of house, living room SE door, middle hinge
100-3898	10/2/2025	House	Interior	Living Room	S	Interior of house, living room SE door, bottom hinge
100-3899	10/2/2025	House	Interior	Living Room	S	Interior of house, living room SE door, door mantle decoration
100-3900	10/2/2025	Historic Shed	Interior	Main Room	E	Historic shed, E door, top hinge
100-3901	10/2/2025	Historic Shed	Interior	Main Room	E	Historic shed, E door, bottom hinge
100-3902	10/2/2025	Historic Shed	Interior	Main Room	E	Historic shed, E door, int. handle
100-3903	10/2/2025	Historic Shed	Interior	Main Room	W	Historic shed, NW door, top hinge
100-3904	10/2/2025	Historic Shed	Interior	Main Room	W	Historic shed, NW door, bottom hinge
100-3905	10/2/2025	Historic Shed	Interior	Main Room	W	Historic shed, NW door, int. handle
100-3906	10/2/2025	Historic Shed	Exterior	n/a	W	Historic shed, E door, ext. handle and wood repair
100-3907	10/2/2025	Historic Shed	Exterior	n/a	E	Historic shed, NW door, ext. handle
100-3908	10/2/2025	Historic Shed	Exterior	n/a	E	Historic shed, W wall window and frame constructed with wooden dowels
0440_wall_constr	10/17/2025	House	Exterior	N/A	N	Partial interior of exterior wall
7171-1	10/20/2025	House	Exterior	N/A	E	Exterior of house, west elevation
7171-2	10/20/2025	House	Exterior	N/A	E	Exterior of house, west elevation
DSCF0899	10/24/2025	House	Exterior	N/A	E	Exterior of house, west elevation
DSCF0900	10/24/2025	House	Exterior	N/A	NE	Exterior of house, South elevation minus porch
DSCF0901	10/24/2025	House	Exterior	N/A	N	Exterior of house, West side of the South elevation, porch
DSCF0902	10/24/2025	House	Exterior	N/A	NW	Exterior of the house, facing NW, South Elevation
DSCF0903	10/24/2025	House	Exterior	N/A	N	Exterior of the house showing door into main living area, South elevation
DSCF0904	10/24/2025	House	Exterior	N/A	NW	Exterior of the house, facing NW, East elevation
DSCF0905	10/24/2025	Historic Shed	Exterior	N/A	E	Exterior of Shed, facing West elevation as it presents to the rest of the property
DSCF0906	10/24/2025	House	Exterior	N/A	E	Exterior of the house showing gap between the neighboring property and the North elevation. A tall fence line prohibits better access or photos.
DSCF0907	10/24/2025	House	Exterior	N/A	E	Exterior of the house, showing front entrance and west elevation
DSCF0908	10/24/2025	Historic Shed	Exterior	N/A	NW	Exterior of the historic shed, showing east elevation as it presents to the alleyway
DSCF0909	10/24/2025	Historic Shed	Exterior	N/A	SW	Exterior of the historic shed, showing east elevation as it presents to the alleyway
DSCF0910	10/24/2025	Historic Shed	Exterior	N/A	NW	Exterior of the historic shed, showing east elevation as it presents to the alleyway. The historic chimney is visible.
DSCF0911	10/24/2025	Historic Shed	Exterior	N/A	W	Exterior of the historic shed, showing east elevation as it presents to the alleyway. A possibly historic door is in the center of the image
DSCF0912	10/24/2025	Historic Shed	Exterior	N/A	W	Close up photo of historic malpais basalt chimney
DSCF0913	10/24/2025	Historic Shed	Exterior	N/A	W	Exterior of the Historic shed, showing north elevation as is visible from the alleyway, looking west. Thick vegetation and the neighboring property fence line prohibit access and better photos
DSCF0914	10/24/2025	Historic Shed	Exterior	N/A	W	Exterior of the Historic shed, showing north elevation as is visible from the alleyway, looking west. Thick vegetation and the neighboring property fence line prohibit access and better photos
DSCF0915	10/24/2025	Historic Shed	Exterior	N/A	W	Exterior of the Historic shed, showing South elevation as is visible from the alleyway, looking west. Thick vegetation and the neighboring property fence line prohibit access and better photos
DSCF0916	10/24/2025	House	Exterior	N/A	E	Exterior of the house, showing the side entrance step up
DSCF0917	10/24/2025	House	Exterior	N/A	N	Exterior of the house, showing the side entrance step up
DSCF0918	10/24/2025	Historic Shed	Interior	Main Room	N	Interior of the shed showing the main room looking north.
DSCF0919	10/24/2025	Historic Shed	Interior	Main Room	S	Interior of the shed showing the main room looking south.
DSCF0920	10/24/2025	Historic Shed	Interior	Main Room	NE	Interior of the shed showing the main room looking Northeast
DSCF0921	10/24/2025	Historic Shed	Interior	Main Room	N	Interior of the shed showing the main room from other side of the shelves, looking north.
DSCF0922	10/24/2025	Historic Shed	Interior	Main Room	S	Interior of the shed showing the main room from other side of the shelves, looking south
DSCF0923	10/24/2025	Historic Shed	Interior	Main Room	S	Interior of the shed showing the main room from other side of the shelves, looking south
DSCF0924	10/24/2025	N/A	N/A	N/A	N/A	Photo deleted as the photo angle and alignment were awful.
DSCF0925	10/24/2025	House	Exterior	N/A	E	Exterior of the house, showing the west elevation.
DJI_0876	10/3/2025	Historic Shed	Exterior	N/A	W	Drone photography of the roof of the shed, highlighting damage
DJI_0969	10/3/2025	House	Exterior	N/A	E	Drone photography of the roof of the house/porch, showing roof detail
DJI_0970	10/3/2025	House	Exterior	N/A	E	Drone photography of the roof of the house/porch, showing roof detail