

Open Space Commission Prioritization Exercise

6
Responses

05:31
Average time to complete

Active
Status

1. Full Name

6
Responses

Latest Responses


"Lina H Wallen "

"Nat White"

"Jackie Thomas"


2. McMillan Mesa Property Restoration

7.17
Average Rating




3. McMillan Mesa Signage

6.50
Average Rating




4. McMillan Mesa Trail Rehabilitation

8.00
Average Rating




5. McMillan Mesa Tree Canopy Buffer

5.50
Average Rating




6. Observatory Mesa Fencing

5.83
Average Rating




7. Observatory Mesa Property Restoration

6.50
Average Rating




8. Observatory Mesa Trail Plan Implementation

7.67
Average Rating




9. Observatory Mesa Water Tank Restoration

6.00
Average Rating




10. Picture Canyon Fencing

7.00
Average Rating




11. Picture Canyon FUTS Connection

7.67
Average Rating




12. Picture Canyon Locus D Trail Spur and Viewing Area

7.17
Average Rating




13. Picture Canyon Property Restoration

6.33
Average Rating




14. Picture Canyon Rio De Flag Bridge Replacement

5.67
Average Rating




15. Picture Canyon Signage Replacement

7.17
Average Rating




16. Picture Canyon Toilet

8.17
Average Rating




17. Picture Canyon Trail Rehabilitation

6.67
Average Rating



18. Picture Canyon Trailhead Entry Road and Parking Lot

6.67
Average Rating



19. Schultz Creek Trailhead

7.67
Average Rating

