





# Water Main Break Repair - Jan 2026



- Water main failed on Tuesday, Jan. 20 in the evening.
- Flagstaff Police Department and Flagstaff Fire Department immediately responded to the emergency, securing the roadway and reducing the impact to vehicular and pedestrian traffic.
- Flagstaff Water Services crews immediately responded to isolate the water main and perform excavation work.





# Water Main Break Repair - Jan 2026



- JOC Eagle Mountain mobilized very next day
- Placement of utilities (natural gas, fiber optic, irrigation) and a stormwater collection basin delayed repair
- Water restored to surrounding properties on Wednesday at 10:00 p.m. after City crews completed installation of a 12” water valve
- The repair was complete by the following Monday, and traffic was restored on Huntington Drive. Flagstaff Public Works will oversee backfilling, paving, and sidewalk repair.



Photo of water main break taken at 1:15 a.m. Wednesday morning.



# Water Main Break Repair - Jan 2026



Wednesday: City Water Services crews prepare a 2<sup>nd</sup> site to install valve that returns flow to remaining properties.



Wednesday: Debris of the stormwater collection basin that had to be removed before water main could be repaired.



Wednesday: Valve waiting to be installed restores water to affected customers while also isolating the break location for repair.



# Water Main Break Repair - Jan 2026



Wednesday: Vantage point of two sites from 50 yards away shows extent of impact.



Wednesday: Site of main break shows proximity of utilities to water main, including natural gas directly above and to the right, and fiber optics and irrigation above and to the left.